

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 3 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

66

Section Corner to Secs. 32 & 33, T23-3W. & Secs. 5 & 4, T24-3W.
Found - 1950 GLO Brass Cap, firmly set & properly mkd.
Orig. Fir to S.W., now stump, no bark scribe.
No trace Orig. BT. to S.E.
8", now 16" Hemlock, alive, N.53 $\frac{1}{4}$ °E. 19.8 ft., scribe marks visible on unhealed blaze.
8", now 14" Hemlock S.18 $\frac{1}{4}$ °E. 20.5 ft., alive, healed blaze.
12" Hemlock, now stump, S.70°45'E. 37.0 ft., scribe mks. visible.
18" Yew, now stump, N.49 $\frac{1}{2}$ °W. 64.0 ft., scribe marks visible.
New BT's: 8" Hemlock S. 38° W. 18.4 ft. mkd. T24S R3W S5 CS BT.
9" Chinq. N. 34° W. 12.8 ft. mkd. T23S R3W S32 CS BT.
Note - This corner lies 150 ft. N. of small creek, dry in cut off area.

Vernon "Ray" Tracy
Jack Heritage
Sept. 25, 1967
C.S. File No. 54/16

MICROFILM TO HERE 10/67

67

Section Corner to Sections 22 - 23 - 26 - 27.
Found - Orig. 36" Fir, now 42" stump, N.21°E. 27.7 ft., open & find scribe marks.
Orig. 24" Fir, now burned stump, S.20°E. 28.4 ft., no scribe.
Orig. 24" Fir, now 30" stump, S.51°W. 12.5 ft., frag. scribe on burned face.
Orig. 24" Fir, now 24" stump, N.39°W. 22.8 ft., shows scars.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1967
T 24 S R 3 W
S 22 | S 23
S 27 | S 26
New BT: 7" D.Fir N. 4° W. 70.0 ft. mkd. T24S R3W S22 CS BT.
No other tree or solid stumps. A 48" Fir Stump S.88°E. 32.2 ft., "W" nail & tag.
Set - 6' steel fence post alongside brass Cap.
Note - This corner lies on verysteep west slope. 11/30/67

Vernon "Ray" Tracy
J. Heritage & V. Perron
November, 1967
C. S. File No. 54/27

68

$\frac{1}{4}$ Cor. to Sec. 7, T24-2W. & Sec. 12, T24-3W.
Found - 1" Alum. Pipe, set at corner, See Ren. #19, T24-2W.
14" Hemlock, now stump, S.61°E. 60.2 ft., with "W" nail & tag.
62" Fir, now stump, N.57°W. 112.0 ft. (Rec.102.9) with "W" nail & tag. Dist. on tag changed since being recorded.
Orig. 24", now 34" Hemlock, down, N.40°E. 19.8 ft., prev. open. & shows scribe.
Set - Brass Cap at Cor Mkd: County Surveyors Office, 1968
R T 24 S R
3W $\frac{1}{4}$ S 12 | S 7 2W
New BT's: 11" Hemlock N.11 $\frac{1}{2}$ °E. 54.2 ft. mkd. " $\frac{1}{4}$ S12 CS BT".
11" Hemlock Stump N.68°W. 19.2 ft. mkd. " $\frac{1}{4}$ S12 CS BT".
Note - This corner lies 10 ft. S. of old cat. logging road in cut off area. 3/4/68

Vernon "Ray" Tracy & Crew
March, 1968
C. S. File No. 54/27

69

Sec. Cor. to Secs. 18 & 19, T24-2W. & Secs. 13 & 24, T24-3W.
Found - 1"x30" Alum. Pipe & BT's. recorded Ren. #45. Pipe bent over under log.
Orig. 30", now 44" Cedar, S.30°W. 26.4 ft., axe notch on reverse face. (Rescribed "T24S R3W S24 CS BT")
Orig. 20", now 42" Cedar, N.82°E. 15.2 ft., open & find "B" scribe. (Rescribed "T24S R2W S18 CS BT")
No trace Orig. N.W. BT. - S.E. BT., down.
36" Hemlock Stump N.88°W. 25.3 ft. to "W" nail, we mark "T24SR3WS13CS BT"
68" D.Fir Stump N.28°E. 35.9 ft. to "W" nail. This area clear cut, No live trees.
Set - Brass Cap at Cor. Mkd: County Surveyors Office 1968
R T 24 S R
3 S 13 | S 18 2
W S 24 | S 19 W
Note - This corner lies 20 ft. S. of cat. logging road, course N.W.

70

$\frac{1}{4}$ Corner to Sec. 19, T24-2W. & Sec. 24, T24-3W.
Found - $\frac{1}{2}$ " I.P. set at corner & "W" method BT, unrecorded.
Orig. 12", now 14" Hemlock, S.35°E. 15.8 ft., now down & out of position, we find probable stump hole, face rotted, no scribe.
Orig. 12", now 14" Hemlock, S.88°W. 17.2 ft., now stump, leaning, "BT" scribe visible on previously opened blaze.
30" D.Fir Stump S.48°W. 15.0 ft., "W" nail (We mark " $\frac{1}{4}$ S24 CS BT")
Set - Brass Cap at Cor. Mkd: County Surveyors Office, 1968
R T 24 S R
3W $\frac{1}{4}$ S 24 S 19 2W
New BT: 20" Cedar Stump S.28°E. 40.1 ft. mkd. " $\frac{1}{4}$ S19 CS BT".
Note - This corner lies on moderate N.W. slope changing to very steep N.W. slope. 3/6/68