

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 24

T. S.

R 3

R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

. H. Gee  
For Joe Cole and  
Stan Mohr  
June 1978  
M 71 - 56

Center 1/4 for Section 32  
Set by proportionate measure:  
Set - 5/8" I. Rod  
Scribe BT's:  
~~11" Hemlock S.40°W., 24.7 ft. scribed C 1/4 S 32 B T"~~  
~~8" D. Fir N.38°W., 10.3 ft. "C 1/4 S32 BT".~~  
*10" D. FIR, S.69°E 12.1'*  
*8" D. FIR N46°W 9.5'*

FD. OK BY D. EDWARDS OCT. 2002 - M137-52 **81**

*CORRECTIONS PER  
MAP CHANGES DATED  
9/26/78 -*

6/78

*1-79*  
Donald Peel  
Triangle Eng.  
For: Weyerhaeuser  
and Champion Int.  
Oct. 1979 M 80 - 57

Center 1/4 for Section 6  
Set - 5/8" x 60" Monel pipe in mound of stone  
BT's - 20" Fir bears N.89°E. 22.2 feet  
17" Fir bears S.16°W. 20.0 feet

**82**

Donald Peel, For  
Weyerhaeuser and  
Chmapiion International  
Oct. 1979  
M 80 - 57

Section corner for Secs. 6 and 5; and secs. 31 & 32 of T23-3.  
Found - 2" I.P. with 1950 GLO brass cap.  
18" Yew snag, N.41°E., 31.9 ft. See Ren. #23  
60" Fir stump, S.70°W., 53.8 ft. (brg. & dist. to "W" nail)  
New BT - 8" Fir, bears N.53°E., 15.4 ft.

**83**

10/79

Glen Mc Chesney  
For Weyerhaeuser Co.  
Sept. 29, 1977  
(Filed 12/80)  
C.S. 58/8

1/4 Corner for Secs. 5 and 8  
Found - 1950 GLO brass cap  
15" nwo 20" Fir, face healed over; also Weyerhaeuser plate and  
scar of healed over W nail, bears N.50°, 21.1 ft. center of tree  
12" now 18" Red cedar, some scribing visible but much of scribing  
has weathered off; also Weyerhaeuser plate and square W nail  
bears S.42°E., 18.2 ft. center of tree measurement .  
Accessories added this date:  
36" Fir, N.33°E., 18.1 ft. with "W" nail and plate  
36" Fir, S.88°E., 40.0 ft. with "W" nail and plate.

**84**

9/29/77

Gregory Quibell  
Deputy, Doug. Co.  
Surveyors Office  
D. Stewart  
March 18, 1981  
C.S. 61/19

1/4 Corner for Sections 27 and 34  
Found - At corner location I found a fairly new 2" x 4' limb 6" in the  
ground "1/4 Secs. 34" was written on south face. Lying on the  
ground nearby was a 4" square by 4' wood post with axe marks.  
(unrecorded Weyerhaeuser renewal)  
36" stump of original 24" Fir, N.64°E., 11.9 ft. Fragments of  
scribed 4 S are visible on opened upper blaze. A fragment of  
a scribed line visible in opened lower blaze. A "W" nail is  
also in lower blaze.  
A rotten Cedar stump which is possibly the orig. 10" Cedar bears  
S.37°W., 9.7 ft. No scribing or blazes visible.  
Also found an unrecorded BT, 40" Cedar stump bears S.38°E., 19.7 ft  
with a "W" nail visible on a rotted face. Remainder of tree with  
Weyerhaeuser BT tag is lying nearby.  
Set - At the location of the 2" x 4' post and at record bearing and dist.  
from orig. 24" Fir stump, I SET a 1" x 30" I.P. with brass cap  
stamped "Douglas County Surveyor 1/4 S27 S34 T24S R3W 1981.  
20" into the ground and place both wood posts alongside.  
New BT's- 8" Fir bears N.67°W., 12.0 ft. scribed 1/4 S27 CS BT.  
7" Alder bears N.69°E., 21.3 ft. scribed 1/4 S27 CS BT  
10" Fir bears S.56°E., 8.8 ft. scribed 1/4 S34 CS BT.  
10" Chinquapin bears S.23°W., 12.4 ft. scribed 1/4 S34 CS BT.  
All trees double blazed and have DCSO BT tags.

**85**

3/81

Larry E. Monrean  
Deputy, Doug. Cou.  
Surveyors Office  
T. Plouff, witness  
Nov. 17, 1981  
C.S. 61 / 29

Sec. corner common to Sec's. 19 & 30, on West Tnsp. line.  
Found - 2" I.P. w/a BLM B.C. properly marked, protrud- 1950 RESURVEY.  
ing 1 foot above ground.  
BT's - 16" Fir, now a stump w/scar visible in growth rings, bears  
N.17 1/2 °E., 48.8-ft. to face, 49.7-ft. to center. This  
stump is 20" in diameter.  
31" Fir, now a 31" stump about 5-ft. high w/partially healed  
pitched over blaze, bears S.57 1/2 °E., 6.2-ft.(Rec.7.3-ft.).  
No other BT's found...SW BT decayed during 1950 Resurvey; NW  
BT position located in newly logged area.

**86**