

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 24 T. S. R 3 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21991

100

1/4 Corner for Secs. 15 and 22.
Set - 1 5/8" x 40" iron pipe with brass cap mkd. with standard markings
and "PLS 1978".
New BTs - 17" fir, S.11°E., 21.3 ft.
18" fir, N.76°W., 7.3 ft.

101

Section corner for secs. 14, 15, 22 and 23.
Set - 1 5/8" x 40" iron pipe with brass cap mkd. with standard markings
and "PLS 1978".
New BTs - 18" fir, N.7°E., 35.1 ft.
18" fir, S.39°E., 23.4 ft.
14" hemlock, S.80°W., 33.1 ft.
24" fir, N.46 1/2°W., 19.9 ft.

102

1/4 corner for secs. 14 and 23.
Set - 2" x 36" iron pipe with brass cap mkd. with standard markings
and "PLS 1978".
New BTs - 14" fir, N.4°E., 12.4 ft.
21" fir, S.86°E., 33.3 ft.

103

Section corner for Secs. 13, 14, 23 and 24.
Found - 1 1/4" iron pipe approx. 4 ft. high
50" fir stump, N.68°E., 21.6 ft. (dist. to "W" nail.)
14" rotten hemlock stub (down) S.10°E., 25.1 ft. (from center of
uproot hole.) (old Weyer. Co. tag - scribing once visible, see
notes of V.R. Tracy, Doug. Co.; C.S. 54/27)
Set - Drove in iron pipe to 16" above ground and cemented in brass cap.
New BTs - 10" fir, N.29°E., 7.4 ft.
12" fir, S.35 1/2°E., 28.8 ft.
12" fir, S.72 1/2°W., 18.1 ft.
12" fir, N.53 1/2°W., 37.4 ft.

104

1/4 Corner for sections 21 and 22
Set - 1 1/4 x 57" iron pipe with brass cap mkd. with standard markings
and "PLS 1978".
30" fir, N.88°E., 34.8 ft.
22" fir, N.34°W., 32.8 ft.
Note - 1" al. pipe set by Weyer. Co. bears N.84°25'51"E., 13.47 ft. Ren.#
38

105

Center 1/4 corner for section 22.
Set - 1 5/8" x 40" iron pipe with brass cap mkd. with standard markings
and "PLS 1978".
New BTs - 23" cedar, N.51°E., 25.2 ft.
27" fir, S.15°W., 9.4 ft.
Note - 1" al. pipe set by Weyer Co. bears N.67°52'58"E., 46.09.

106

1/4 Corner for Secs. 22 and 23
Set - 2 1/2" x 36" iron pipe with brass cap mkd. with standard markings
and "PLS 1978".
New BTs - 8" fir, N.57°E., 22.2 ft.
6" hemlock, N.12°W., 26.6 ft.
Note - 1/2" monel pipe set by Weyer Co. Bears N.80°15'49"E., 82.32 ft.

107

1/4 Corner for Secs. 23 and 24.
Set - 2" x 30" iron pipe with brass cap mkd. with standard markings
and "PLS 1978".
12" fir, N.9°E., 16.5 ft.
11" fir, S.61°W., 15.6 ft.

108

Section corner for Secs. 21, 22, 27 and 28.
Found - 1 1/2" iron pipe. Ren. #37
60" fir stump, S.41°E., 30.8 ft. (dist. to "W" nail.)

C O N T. N E X T P A G E

Daniel Baker, LS 1978 Peel Baker Land Surveying
For: Weyerhaeuser Company
December 8, 1983
M 90 - 48