

Douglas County Surveyor's Record of  
Government Corners Renewed

24

T. S.

3

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Ronald Geisler  
For: Champion  
International  
L. Sibley and D.  
Turner Witnesses  
October 9, 1985  
C.S. 63/22

Section corner for Sections 17, 18, 19 and 20  
Found - 1950 BLM brass cap on 2" I.P. extends 6" above ground.  
R.M. to the SE not found.  
R.M. - 2 1/2 brass cap on 2" I.P. extends 6" above ground and  
marked with arrow pointing to true corner bears N.45°W.,  
19.80 ft. from corner.  
No record of the following BTs I found:  
13" chinquapin bears S.25°E., 11.18 ft. (metal disc in face of  
tree).  
32" stump bears S.43°W., 11.14 ft. (Metal disc in face of tree)  
36" snag bears N.77°W., 43.0 ft. (metal disc in face of tree).  
New Accessorie:  
2 1/2" alum. cap on 1" x 36" iron pipe extends 5" above ground  
and marked "LS-1988, 1985, R.M. with arrow pointing to  
true corner bears S.45°E., 19.80 ft. from true corner.

115

10/9/85

Ronald Geisler  
L.S. #1988  
For: International  
Paper  
Oct. 25, 1985  
C.S. 63/22

Northwest section corner for Section 18 (and SW of Sec. 7)  
Found - 1950 BLM 2 1/2" brass cap on a 2" I.P. extending 14" above  
ground. See Ren. #28/  
22" cedar snag bears S.82°E., 62.22 ft. (Rec. S.85°E.,  
61.38 ft.) Scribing partially visible.  
New BTs - 16" fir bears S.38°E., 69.2 ft. scribed T24S R3W S18 BT.  
14" fir bears N.59°E., 77.2 ft. scribed T24S R3W S7 BT.

116

10/25/85

Donald L. Peel  
P.L.S. #752  
For: Weyerhaeuser Co.  
M 99 - 77  
Nov. 13, 1985

Center 1/4 Section Corner for Section 15  
Set - 2" x 36" iron pipe, with brass cap mkd. T24S R3W C 1/4 S15  
PLS 752 1985.  
BT's - 32" Cedar, bears S.52°E., 27.9 ft. Scribed C 1/4 S15 BT.  
26" Fir, bears N.74°W., 26.0 ft. Scribed C 1/4 S15 BT.

117

Donald Peel L.S. 752  
For: Wyerhaeuser Co.  
Jan. 31, 1986  
M 100 - 29

1/4 Corner for Sections 16 and 21  
Found - 1" I.P. with GLO brass cap. "1950" Ren. No. 62  
18" triple maple, S.10½°W., 63.3 ft. (center measure)  
30" fir stump, N.7½°W., 34.5 ft. (face measure)  
SE BT now uprooted and down.  
New BT - 13" fir, N.39½°E., 30.4 ft. scribed 1/4 S16 BT (dist. to "W" nail).

118

119

FND OK  
6/91 D. PEEL  
M 113 43

1/4 Corner for Sections 20 and 21  
Found - 1" iron pipe with GLO brass cap "1950".  
19" fir, N.83½°E., 24.0 ft. (center measure)  
18" fir, S.20½°E., 13.4 ft. (center measure)  
45" fir stump, S.14°W., 35.8 ft. (center measure)  
New BT - 16" fir, S.36°W., 34.0 ft. scribed 1/4 S20 BT (dist. to "W" nail)

120

1/4 Corner for Sections 21 and 28  
Set - 1½" x 54" iron pipe with brass cap marked T24S R3W 1/4 S21  
S28 PLS 752 1986.  
New BTs - 21" fir, N.0½°E., 24.1 ft. scribed 1/4 S21 BT.  
22" fir, S.39°W., 11. ft. scribed 1/4 S28 BT.

1/4 Corner for Sections 20 and 29 FD OK - M121-SB A+B - 12/15/94  
Found - A 2½" dia. GLO brass cap on 1" O.D. iron pipe, protruding  
12" above ground. (1950 BLM)  
1" square x 24½" long iron bar is found loose on top of  
ground near BC/IP. (Land owner pulled bar out of ground).  
5" now 7" dia. Cedar with a fully healed double blaze, bears  
S.19°E., 75.7 ft. (Rec. S.24°E., 75.7 ft.) (fence attracts  
compass needle bearing taken away from fence) Ren. No. 75  
Red Brick shimney bears N.26½°E., (Rec. N.21½°E.) (see bearing  
problem above) Ren. No. 75  
No other accessories found.  
New BTs - 11" dia. d. Fir double blazed and scribed "¼ S20 CS BT" bears  
N.80½°W., 55.8 ft.  
23" dia. D. Fir single blazed and scribed "¼ S20 CS BT" bears  
N.49°E., 92.4 ft.  
5" dia. Ash double blazed and scribed "XBT" bears S.63½°E. 7.8 ft.  
Corner lies in an E-W fence line.

121

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Sept. 17, 1991  
C.S. 64/17