

Douglas County Surveyor's Record of
Government Corners Renewed

24

T. S.

4

R. W. W. M.

$\frac{1}{4}$ corner to secs. 9 and 10.

Found O. B. T. - W. Fir, snag, badly rotted - scribe plain.

Set 3 inch x 3 inch x 48 inch Hemlock stake.

Blazed and scribed New B. T.s:

36 inch D. Fir, N. $67\frac{1}{2}^{\circ}$ W., 38.0 feet, mkd. $\frac{1}{4}$ S - 9 - R. E. 2741 B. T.,
(bark scribe - distance to center).

40 inch Inc. Cedar, S. $59\frac{1}{2}^{\circ}$ E., 59.8 feet, mkd. $\frac{1}{4}$ S - 10 - B. T.

Yellow tag - "Grant and Evans" on N.W. B.T.

Yellow F. S. location tag on O. B. T. snag.

SEE CORNER NO. 28
37 # 67

Arthur R. Evans
Work done for Martin
Bros. Box Co.
March 14, 1956.
C. S. File No. 42/207.
(no map)

N. E. corner of D. L. C. No. 39.

Found - burned stump 24 inch B. O., N. 1° E., 82.5 feet - found scribing.

Also found 18 inch B. O., S. 24° W., 48.8 feet with center rotted - found scribing.

Both B. T.s are originals and check for bearing and distance.

Set an iron pipe with brass cap at corner point mkd. NE DLC 39 T24S R4W,

County Surveyors Office 1956,

from which:

18 inch Cedar bears N. $28\frac{1}{2}^{\circ}$ E., 39.7 feet scribed NE Cl 39 CS BT.

12 inch W. O. bears N. 85° E., 27.6 feet scribed NE Cl 39 CS BT.

Note: $1\frac{1}{2}$ inch iron pipe on N-S fence line bears N. 27° W., 3.2 feet. Ren #20

S 27° E M.E.G.

S. E. corner Cl. 39.

Found 50 inch B. O., S. $5^{\circ}30'$ E., 157.8 feet with tree and scribing in good condition and from which corner was established. Ren #21

Set an iron pipe with brass cap mkd. SE DLC 39, T24S, R4W, County Surveyor's Office, 1956, from which:

~~20~~ inch W. O., bears N. 89° E., 22.0 feet scribed SE Cl 39 CS BT.

Note: pipe not found. 12" DIAM. IN 1963 M.E.G.

S. W. corner D. L. C. 38. (Langley Hall D. L. C.)

Found orig. B. T.s open and find scribing - check for bearing and distances.

Position of corner determined from orig. B.T.s.

Set an iron pipe with brass cap at corner point mkd. SW DLC 38 T24S R4W,

County Surveyors Office, 1956.

From which:

9 inch W. O. bears N. 16° E., 22.0 feet.

9 inch W. O. bears N. 80° E., 33.9 feet scribed SW cor DLC 38 CS BT.

Renewal of Corner to Sections 10, 11, 14, & 15.

Corner set from two witness trees 1/3/58.

6" Fir, green & standing bears S. $64\frac{1}{2}^{\circ}$ E. 54 lks.

Stump for the Fir which bears S. 58° W. 52 lks. Was cut high, catface still visible, with two tags.

No other trees available, area was logged & burned.

Set 1" x 30" Iron Pipe with Brass Cap marked: $\frac{10|11}{15|14}$ T24 S R4 W

Renew Twp. Corner Twp. 24 & 25 S., R's. 4 & 5 W.

Found - Laurel Tree, now 30" diam. standing but dead, chopped open & found good scribing "BT" (N. 41° E. 13.2 ft.)

Laurel Tree, standing & alive but rotted out inside, now 40" diam. N. 74° W. 207.9 ft.

Stump Hole S. 22° E. 25.7 ft.

Oak Tree (dead & down), now 16" diam. S. 22° W., instead of S. $29\frac{1}{2}^{\circ}$ W. 82.5 ft. chopped out upper blaze & found reverse of scribing "R5W T25S & S".

Set Brass Cap at Corner Mkd: County Surveyor's

R5W	$\frac{T24S}{S36}$	S31	R4W
	S 1	S 6	
	T25S		

Blaze & Scribe the following trees:

8" W. Oak S. $52\frac{1}{2}^{\circ}$ W. 24.4 ft. mkd. "T25S R5W S 1 CS BT"

10" W. Oak S. 44° E. 45.0 ft. mkd. "T25S R4W S 6 CS BT"

8" W. Oak N. 48° W. 15.6 ft. mkd. "T24S R5W S36 CS BT"

7" W. Oak N. 15° E. 25.9 ft. mkd. "T24S R4W S31 CS BT"

29

30

31

32

33

County Surveyor's Office
Sept. 27, 1956
C. S. File No. 47/134.

James W. Byron,
Dep. Co. Surveyor
Sept. 28, 1956
C. S. File No. 47/141.

Richard C. Grant
J. Chapman
D. Powell - W. Oilar
Jan. 3, 1958
C.S. File No. 42/328

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
December 1958
C. S. File No. 49/124

FD OK 7/84
B. M. 11/24
BY R. Dolan M. 20-11
7/94