

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 S. T. S. R 4 W R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

52

Closing Corner between Sections 1 and 12.

Found - G.L.O. Brass Cap, dated 1950.

28" Fir N.31 $\frac{1}{2}$ °W. 25.1 ft., recent blowdown, portions of scribe marks visible in not completely healed scar.

26" Fir S.54°45'W. 32.3 ft., recent blowdown, scar visible, lying face down.

New BT's: 13" D.Fir N.57°W. 10.2 ft. Mkd: T24S R4W S1 CC CS BT. - Tree down June 1963

7" I.Cedar S.79°W. 28.2 ft. Mkd: CC S12 CS BT. See new tree mkd.

Mkd.New BT: in June 1963: 7" Hemlock N.57°W. 70.8 ft. scribed CC S1 CS BT.

53

Corner to Sections 6 & 7, T24-3W.

Found - G.L.O. Brass Cap dated 1950

36" Fir N.68°E. 29.7 ft., recent blowdown, scribing visible on not healed over scar.

36" Fir S.62°45'E. 48.2 ft., recent blowdown, face pitched over, scribe marks not readily visible.

New BT's: 19" Red Cedar N.36°E. 20.5 ft. Mkd: T24S R3W S6 CS BT.

D. Fir S.45°E. 63.7 ft. Mkd: T24S R3W S7 CS BT.

$\frac{1}{4}$ Corner Sec. 31, T23-4W. & Sec. 6, T24-4W.

5/81 Fnd. OK. R. QUIMBY M 79-77

54

Found - Rotten Oak Log S.40°E. 55.4 ft., picked rotten wood apart and found good reverse scribing "S".

Small depression in ground (possible stump hole) N.5°E. 42.9 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T23S R4W $\frac{1}{4}$ S31 T23S S 6 T24S

New BT's: 11" D.Fir N.29°W. 17.6 ft. Mkd: $\frac{1}{4}$ S31 CS BT.

D. Fir S.11°W. 22.4 ft. Mkd: $\frac{1}{4}$ S6 CS BT.

Corner lies .8 ft. south of E. & W. fence line, near N.W. corner of patch of 2nd. growth fir timber.

55

Corner to Sections 32 and 33 only, T23-4W.

Found - at a point 271 lks. East of the Closing Corner of Sections 4 and 5, T24S R4W, entered as next renewed corner.

65" Fir Stump S.86°E. 29.7 ft., old axe marks on bark appear to be where Thiel destroyed bark scribing, see notes, on lower scar what appear to be portion of scribe mk. "B" is visible.

50" Fir Stump N.70°E. 27.7 ft., no marks found.

60" Fir Stump N.43°W. 25.1 ft, one single axe mark found in wood approximately 110 years old. No trace of S.W. BT.

I believe these trees to have been larger at time of Original survey than field notes indicate and that they were bark scribed.

Did not find Rock set by Thiel. Appears to be in old slide area.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T23 R4W S32/S33

New BT's: 52" D.Fir N.75°W. 65.0 ft. Mkd: T23S R4W S32 CS BT.

12" Red Cedar S.73°E. 38.0 ft. mkd. T23S R4W S32 S33 CS BT.

No trees available to N.E. Cor. lies on very steep N. face.

56

Closing Corner between Sections 5 and 4, S. line of T23-4W.

Found - 30" Maple S.40°E. 23.8 ft., scribing visible on old face opened several years ago, "R4W S4 BT", main trunk of tree broken off 5 ft. above ground, badly rotted.

Rotten Maple Stump S.72°W. 27.7 ft., broken trunk of tree lying alongside, axe marks visible, but no scribing found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 S 5/ S 4 T24S R4W CC

New BT's: 16" White Fir S.1°E. 55.6 ft. Mkd: T24S R4W CC S4 CS BT.

11" I. Cedar S.77 $\frac{1}{2}$ °W. 86.4 ft. Mkd: T24S R4W CC S5 CS BT.

Corner lies on a bench just below steep north face of mountain.

57

$\frac{1}{4}$ Corner to Sections 5 and 8.

Found - 42" Fir N.20°E. 73.9 ft., recently uprooted, chopped open & fd. scribe.

No trace of S. E. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S R4W $\frac{1}{4}$ S 5 S 8

New BT's: 8" W.Fir S.31°W. 119.2 ft. Mkd: $\frac{1}{4}$ S8 CS BT.

11" I.Cedar N.44°E. 67.5 ft. Mkd: $\frac{1}{4}$ S5 CS BT.

A fence corner, fences E, W, and North bears N.75°W. 21 feet.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
February and March 1963
C. S. File No. 53/9