

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO. EUGENE, ORE. 21881

58

1/4 Corner to Sections 7 and 18.

Found - Rotted Point of Oak Stake set by Eppstein for Corner. See Cor. #12  
14" W.Oak N.35 1/2°E. 10.8 ft. Has been opened previously & faint  
scribing visible on badly rotting face.

16" W.Oak S.42°W. 10.1 ft., shows 2 very plain scars. Did not open.  
Tree alive and in good condition.

Rotten remnants of both Orig. BT's. found, no mks. remaining on either.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T24S R4W 1/4 S7  
S18

New BT's: 7" D.Fir N.1°E. 16.1 ft. Mkd: 1/4 S7 CS BT.

Reinforcing Rod set by Frear bears N.77°W. 1.7 feet.

Fence corner, fences West and South bears S.46°E. 23 feet.

Corner is approximately 200 ft. East of County Road.

59

Section Corner to Sections 4 - 5 - 8 - 9.

Found - 14" Laurel S.18°W. 59.4 ft. (slope dist.) Cut open & found  
unmistakable but illegible reverse scribing.

60" Fir N.40°E. 34.3 ft. (slope dist.) Shows scar.

Clump of small maples S.80°E. 11.2 feet. Did not find N.W. Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T24S R4W S5 | S4  
S8 | S9

Rescribe - 60" Fir N.40°E. 34.3 ft. (slope dist.) Mkd: T24S R4W S4 CS BT.

New BT's: 7" D.Fir S.14°E. 36.0 ft. Mkd: T24SR4W S9 CS BT.

7" D.Fir S.61°W. 25.7 ft. Mkd: T24S R4W S8 CS BT.

28" D.Fir N.78°W. 25.0 ft. Mkd: T24SR4W S5 CS BT.

A steel fence post set for approx. cor. bears S.12°E. 35.8 feet.

Corner lies on precipitous very rocky slope, just below nearly perpendicular

Rock Cliff 100 ft. high. Cut cross 6x6 in base of cliff 36.2 ft. E. of Cor.

60

Section Corner to Sections 13 - 14 - 23 - 24.

Found - Laurel S.68°E. S.68°E. 52.8 ft. Tree broken off near ground. Cut open  
& found good reverse scribing (old) "S".

Laurel N.81°E. 35.0 ft. Tree alive, but S. side & entire center of  
tree rotted & burned away. Fairly recent scrbing on both Laurels.

No trace of S. W. or N. W. Trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T24S R4W S14 | S13  
S23 | S24

New BT's: 5" D.Fir N.38°W. 8.4 ft. Mkd: S14 CS BT.

16" D.Fir S.8°E. 8.4 ft. Mkd: T24S R4W S24 CS BT.

7" D.Fir N.60°E. 30.7 ft. Mkd: T24S R4W S13 CS BT.

6" Madrone S.43°W. 50.4 ft. Mkd: T24SR4W S23 CS BT.

An old fence line running East bears South 8 feet.

61

1/4 Corner to Sections 5 and 4.

Found - Rock as called for in Gov't. notes, faint marks visible on West Face.

10" Fir Snag S.86°W. 2.6 ft., previously opened, scribing visible.

29" D.Fir N.62°E. 8.2 ft., shows very plain axe scar. Did not open.

Alongside E. Side of Rock, Set - Brass Cap Mkd: County Surveyor's Office, 1963  
T24S R4W 1/4 S5/S4

New BT's: 24" D.Fir S.44°W. 15.8 ft. Mkd: 1/4 S5 CS BT.

Top of ridge running nearly North & South bears West approx. 250 ft.

62

1/4 Corner to Sections 9 and 16.

Found - 3/4" iron pipe driven flush with ground.

26" Maple N.19°W. 9.2 ft., opened several years ago. Fd. 2 old faces,  
upper & lower, surface rotted, no scribe marks found. Call on

creek in gov't. notes approx. 15 ft. more than present dist.

Cedar Stake rotted off, cruiser's marks on small cedar near corner,  
fits good for line between section corners.

No trace of Orig. S.W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T24S R4W 1/4 S9  
S16

New BT's: 6" I. Cedar S.36°W. 17.3 ft. Mkd: 1/4 S16 CS BT.

6" I. Cedar N.45°E. 29.7 ft. Mkd: 1/4 S9 CS BT.

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
February and March 1963  
C. S. File No. 53/9

Stamped By  
MISTAKE

4196