

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

63
 $\frac{1}{4}$ Corner to Section 4 and 9.
 Found - 33" Fir S.25°E. 25.7 ft., uprooted & down, not recent)
 Opened scar and found good scribing " $\frac{1}{4}$ ".
 12" Fir N. 6° W. 3.3 ft., shows good scars. Did not open.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office T24S R4W $\frac{1}{4}$ S 4
 New BT: 22" D.Fir S.37°E. 39.2 ft. Mkd: $\frac{1}{4}$ S 9 CS BT. S 9

64
 Section Corner to Sections 5 - 6 - 7 - 8.
 Found - 36" Bl. Oak S.78 $\frac{1}{2}$ °E. 378.2 ft. Cut open & fd. good scribing "B".
 Old Rotten, hollow Alder Stump in clump of alders S.68°W. 285.1 ft.
 All marking rotted away. No trace of other Original Bearing Trees.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S R4W S 6 | S 5
 S 7 | S 8
 New BT's: 16" Dbl. W. Oak N.36°E. 69.4 ft. Mkd: T24S R4W S5 CS BT.
 9" W. Oak N. 1° W. 48.5 ft. Mkd: T24S R4W S6 CS BT.
 10" Maple S.15 $\frac{1}{2}$ °E. 207.0 ft. Mkd: T24S R4W S8 CS BT. 177
 No suitable trees available in Section 7.
 A western most pole on the westerly line of Pac. Power & Light Co.
 bears N.76°E. 113.5 ft. Cor. lies in old abandoned orchard.
 Pinkston's House bears N.75°W. approximately 300 yards.

65
 Section Corner to Sections 9 - 10 - 15 - 16.
 Found - Haines' "T" Iron & Cap under log. - SEE COR. #39
 12" I. Cedar N. 6° E. 31.3 ft., scribing all visible.
 Rotten Fir Snag, now 24", S.38°W. 115 ft. Opened previously,
 good scribing visible on old face.
 54" Fir N.70°W. 101.6 ft., recently uprooted & down, old face
 badly burned. 44" Fir Stump S.10°E. 141 ft. Edge of face
 scar visible on top of stump. Did not find N.E. BT.
 DID NOT SET BRASS CAP.
 New BT's: 21" D.Fir S.56°E. 65.3 ft. Mkd: T24S R4W S15 CS BT.
 17" D.Fir S.55°W. 46.3 ft. Mkd: T24S R4W S16 CS BT.
 9" W.Fir N.58°W. 69.5 ft. Mkd: T24S R4W S9 CS BT.

66
 Section Corner to Sections 3 - 4 - 9 - 10.
 Found - County Surveyor Brass Cap set in 1961. REN #46
 Orig. S.W. Hemlock & N.W. Cedar are still standing, but dead.
 The trees mkd. in 1961 are all alive & in good condition:
 10" Hemlock, (not Yew) N.77°W. 23.5 ft.
 11" Hemlock N. $\frac{1}{2}$ ° E. 49.0 ft.
 5" Hemlock (not Yew) S.13 $\frac{1}{2}$ °W. 48.0 ft.
 40" Cedar S.88°E. 58.1 ft. has top broken out, probably die.
 New BT: 40" R.Cedar S.38°E. 54.2 ft. Mkd: T24S R4W S10 CS BT.

67
 $\frac{1}{4}$ Corner to Sections 9 and 10.
 Found - Haines' "T" Iron at Corner. - SEE COR. #37
 36" Fir N.67 $\frac{1}{2}$ °W. 38.0 ft., recently uprooted & down. Good
 bark scribing "T24" (Evan's BT.) SEE COR. #37
 40" I.Cedar S.59 $\frac{1}{2}$ °E. 59.8 ft., recently uprooted, lying face
 down. (Evan's BT.)
 Rotten remnants of White Fir Stump S.65°E. 42.9 ft. All markings
 completely rotted away. No trace of Original N.W. tree.
 DID NOT SET BRASS CAP.
 New BT's: 4" Hemlock N.42°E. 10.6 ft. Mkd: $\frac{1}{4}$ S10 CS BT.
 5" Hemlock S.48°W. 18.8 ft. mkd: $\frac{1}{4}$ S9 CS BT.
 FD OK, W 25-97, S. PRESS, CS 05 | 15 - 4A

68
 $\frac{1}{4}$ Corner to Sections 14 and 23.
 Found - 40" Fir Stump N.25°E. 25.1 ft. Cut open & fd. good scribing.
 24" Laurel S.23°W. 78.5 ft. Tree nearly dead, cut open & found
 good scribing "S", 4 inches inside tree.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S R4W $\frac{1}{4}$ S14
 S23
 New BT's: 18" D.Fir N.27°E. 34.4 ft. Mkd: $\frac{1}{4}$ S14 CS BT.
 14" D.Fir S.13°W. 49.6 ft. Mkd: $\frac{1}{4}$ S23 CS BT.

Milo E. Godfrey, Deputy County Surveyor
 Vernon Tracy and Mike Stone
 February & March 1963
 C. S. File No. 53/9