

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

75
 $\frac{1}{4}$ Corner to Sections 11 and 14.
 Found - Rock set by Thiel, mkd: "S on N. Face.
 24" I. Cedar S. 9° W. 37.6 ft., shows 2 very plain axe scars.
 Badly burned Cedar Snag N. 30° E. 25.1 ft. No mks. left on snag.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W $\frac{1}{4}$ S 11
 Alongside Rock Office, 1963 S 14
 New BT: 12" D. Fir N. 61° E. 26.0 ft. Mkd: $\frac{1}{4}$ S 11 CS BT.
 Corner lies on bench at edge of marshy ground, just E. of top of ridge.

76
 Section Corner to Sections 11 - 12 - 13 - 14.
 Found - G.L.O. Brass Cap set in 1957.
 32" Cedar S. 68° E. 39.6 ft., alive & in good condition, scribing vis.
 20" Cedar S. 11° W. 14.8 ft., alive & in good condition, shows scar.
 27" Fir N. 47° W. 68.6 ft. alive & in good condition, scribing all
 visible, scar not healed over.
 17" Fir N. 18° E. 19.1 ft. is now dead, scribing all visible.
 Reblaze & Scribe: 32" Cedar S. 68° E. 39.6 ft. Mkd: T24SR4WS13 CS BT.
 20" Cedar S. 11° W. 14.8 ft. Mkd: T24S R4W S14 CS BT.
 New BT: 10" D. Fir N. 80° E. 76.2 ft. Mkd: T24S R4W S12 CS BT.

77
 Most Northerly N.W. Corner D.L.C. No. 37.
 Found - 1" Iron Rod 7" above ground. - SEE COR. # 7
 16" W. Oak S. 4° E. 9.4 ft., good scars but face rotted away.
 17" W. Oak N. 70° E. 33.8 ft., shows good scars. Did not open.
 DID NOT SET BRASS CAP.
 New BT's: 13" D. Fir S. 57° W. 12.5 ft. Mkd: NW DLC 37 CS BT.
 8" D. Fir N. 24° W. 13.3 ft. Mkd: NW DLC 37 CS BT.
 A N. & S. Fence line bears east approx. 60 ft. & a N. & S. logging
 road (?) bears West 35 feet.

78
 N. W. Corner Samuel Driver D.L.C. No. 41
 Found - 2" Iron pipe at Corner as set by Woodford & Richardson, 1945.
 14" W. Oak S. 67 $\frac{1}{2}$ ° E. 31.6 ft., shows very plain axe scar. - SEE COR. # 17
 Orig. 12" W. Oak, now 15", S. 53° W. 149.8 ft., scribing visible.
 Orig. 18" W. Oak, now 36", S. 63° W. 151.8 ft., shows good scar.
 No trace of either tree marked by Roberts in 1904. - SEE COR. # 11
 New BT: 13" Bl. Oak North 6.5 ft. Mkd: NW DLC 41 CS BT.
 Corner is in fence corner, fences East, West and South.

79
 Most Southerly S.E. Corner D.L.C. No. 46.
 Found - 20" Bl. Oak N. 7° E. 159.7 ft., shopped open & fd. good scribing,
 "4W"; Tree alive but dying, top broken out.
 Rotten remains of Oak Stump & tree trunk N. 13° W. 158.4 ft.,
 (240 lks. instead of 230 lks.) No mks. fd., too badly rotted.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
 T24S R4W S SW DLC 46
 New BT's: 14" W. Oak S. 80° E. 24.4 ft. Mkd: S SE DLC 46 CS BT.
 12" W. Oak N. 17° W. 80.2 ft. Mkd: S SE DLC 46 CS BT.
 A fence corner - fences North, West & S.E. bears N. 34° W. 37 ft.
 Corner lies in West edge of old wood or logging road.

80
 Most Westerly N. W. Corner D. L. C. No. 37.
 Found - Oak, down & partly rotted, N. 40° W. 82.5 ft. Cut open & fd. good scribing.
 Big Stump Hole S. 89° E. 248.8 ft. No trace of stump left.
 (Both trees measured slope distance.)
 Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W W N.W. DLC 37
 Office, 1963
 New BT's: 8" D. Fir N. 72° W. 22.7 ft. Mkd: W NW DLC 37 CS BT.
 15" D. Fir S. 41° W. 24.2 ft. Mkd: W NW DLC 37 CS BT.
 Corner lies approximately 65 ft. west of centerline of Elkhead Road.

Milo E. Godfrey, Deputy County Surveyor
 Vernon Tracy and Mike Stone
 February and March 1963
 C. S. File No. 53/9