

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
March and April 1963  
C.S. File No. 53/9

Section Corner to Sections 7 - 8 - 17 - 18. 81  
Found - 32" Bl. Oak, dead but standing, N.69°W. 36.3 ft. Cut open &  
found good scribing "24"  
Oak, down & rotting S.55°W. 61.4 ft., fd. good scribing "S1".  
Oak Stump, pushed out of position, S.77°E. 96.4 ft. Good rev. scribing.  
Oak, down & rotting, N.78°E. 233.0 ft. Lying face down, did not open.  
Scribed Wooden Stake hanging in fence line, just East of Corner.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W 

S 7	S 8
S18	S17

  
Office, 1963  
New BT's: 14" W.Oak S.56°E. 24.0 ft. Mkd: T24S R4W S17 CS BT.  
7" W.Oak N.62°E. 7.2 ft. Mkd: T24S R4W S8 CS BT.  
7" D.Fir S.52°W. 28.4 ft. Mkd: T24S R4W S18 CS BT.  
9" D.Fir N.52°W. 35.2 ft. Mkd: T24S R4W S7 CS BT.  
A N. & S. fence line bears East 3 feet from corner.

Closing Corner Sections 4 and 3. 82  
Found - Brass Cap set by County Surveyor, 1959. - *SEE COR. #35*  
Orig. S.W. BT., 40" D.Fir S.1°W. 18.5 ft., alive and standing.  
6" Cedar S.43°W. 34.5 ft. in good condition.  
Orig. S. E. BT., now uprooted & down.  
New BT: 11" Red Cedar S.69°E. 63.8 ft. Mkd: T24S R4W CC S 3 CS BT.

Corner to Sections 33 and 34, only, T23-4W. 83  
Found - Haines' "T" Iron & Cap at Corner. (*SEE ALSO REN. #38 IN T. 23-4*)  
7" Hemlock N.25°W. 5.5 ft., alive & standing, good condition.  
Northeast Bearing Tree is now down.  
New BT: 10" Hemlock N.39°E. 48.0 ft. Mkd: T23SR4W S34 CS BT.

1/4 Corner to Section 34 only, T23-4W. North Bdry. Sec. 3, T24-4W. 84  
Found - 32" Fir S.42°W. 42.2 ft., has been previously opened, good  
scribing "13" visible on old face.  
Old Fir Stump N. 5°W. 11.9 ft., small portion of old face  
exposed, good scribing, portion of "4" visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T23S R4W S 1/2 S34 only  
Office, 1963 T24S  
New BT's: 32" Red Cedar N.81°E. 21.0 ft. Mkd: 1/2 S34 CS BT.  
24" Hemlock N.77°W. 53.3 ft. Mkd: 1/2 S34 CS BT.  
Corner lies in dry draw draining Southwest.

1/4 Corner to Sections 4 and 3. 85  
Found - County Surveyor's Brass Cap, 1961; O.K. - *SEE COR. # 47*  
32" Fir Stump N.13 1/2°W. 24.4 ft. scribing still visible "13".  
Both trees marked in 1961 are down, blown over in Oct. 1962 windstorm.  
New BT's: 38" D.Fir N.78°E. 33.6 ft. Mkd: 1/2 S3 CS BT.  
12" Incense Cedar S.57°W. 111.3 ft. Mkd: 1/2 S4 CS BT. ~~# 156~~

1/4 Corner to Section 3 and 10. 86  
Found - Haines' "T" Iron & Cap. - *SEE COR. # 36*  
12" Fir S.81°W. 19.1 ft, previously opened, good scribing visible.  
17" Fir N.72°E. 23.1 ft., previously opened, good scribing visible.  
New BT's: 15" D.Fir N.18°E. 35.1 ft. Mkd: 1/2 S3 CS BT.  
7" D.Fir S.35°E. 40.6 ft. Mkd: 1/2 S10 CS BT.

Most Easterly S. E. Corner D. L. C. No. 47. 87  
Found - Old Oak, down & badly rotted, N.16°E. 160.4 ft., cut open & find  
fragmentary reverse scribing, "S" "W", legible.  
Stump Hole with small portion of Oak Stump lying nearby, N.6 1/2°W  
159.1 ft, no marks found. T24S R4W  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 E SE DLC 47  
New BT's: 14" W.Oak N.9 1/2°E. 102.6 ft. Mkd: E SE DLC 47 CS BT.  
11" W.Oak N.68°E. 125.6 ft. Mkd: E SE DLC 47 CS BT.  
From cor. a fence cor., fences N., W., & SE. bears S.50°W. 3.0 ft.  
Note - needle bearing may be affected by fence wires.

FO OK  
6/9/66  
Templin  
M 125-36