

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

North East Corner D. L. C. No. 47.

88

Found - Old Oak Stump, rotten trunk, lying alongside N.50°E. 20.5 ft.,
found reverse scribing in trunk "24 4W".
Old rotted Oak, down, S.60°W. 51.5 ft. Too badly rotted to find
and marks.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W N.E. D.L.C. 47

New BT's: 6" White Oak S.77°W. 5.8 ft. Mkd: NE. DLC 47 CS BT.
7" White Oak N.20°W. 24.7 ft. Mkd: N.E. DLC 47 CS BT.

A North and South Fence Line runs 2 feet west of corner.

Most Easterly S. E. Corner D.L.C. No. 40.

89

Found - White Oak, now 24", N.50°E. 21.1 ft. Cut open & found good
scribing, "BT". Tree in good condition.
Rotten remains of large Oak N.30°W. 132.0 ft. Too far gone
to find scars or scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W E SE DLC 40

New BT's: 14" White Oak S.65°W. 24.1 ft. Mkd: E SE DLC 40 CS BT.
12" White Oak S. 2°W. 31.2 ft. Mkd: E SE DLC 40 CS BT.

Northeast Corner D. L. C. No. 40.

90

Found - 34" Bl. Oak S.25°W. 19.8 ft., cut open lower scar & found good
rev. scribing "BT". Center of tree rotten, shows very plain upper
scar, tree dying.

30" Bl. Oak N.65°W. 16.5 ft., 2 good axe scars very plain #174
Did not open. Tree in fair condition.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W N.E. DLC 40

New BT's: 15" Maple N.15°W. 48.0 ft. Mkd: N.E. DLC 40 CS BT.
12" D. Fir S.56°E. 53.6 ft. Mkd: N.E. DLC 40 CS BT.

An E. and W. Fence line is 22.0 feet North of corner.

Northwest Corner D. L. C. #38.

91

Found - Dead White Oak Snag, now 40", West 93.7 ft., shows 2 good
scars, open lower scar & fd. very good scribing "BT".
Oak Stump S.24°E. 693.0 ft. Cut open & fd. fragments of scribe marks.
Did not find Stone Post at Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W N.W. DLC 38

New BT's: 13" White Oak S.5°W. 19.0 ft. Mkd: N.W. DLC 38 CS BT.
7" White Oak N.37°E. 8.2 ft. Mkd: N.W. DLC 38 CS BT.

Interior "L" Corner D. L. C. #47.

92

Found - 32" Bl. Oak S.59°W. 260.0 ft., cut open & find good scribng, "BT".
Did not find other Bearing Trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W Int.L DLC 47

New BT's: 9" W. Oak S.52½°W. 155.7 ft. Mkd: Int. L. DLC 47 CS BT.
14" White Oak N.44½°W. 150.7 ft. Mkd: Int. L. DLC 47 CS BT.

Corner lies on bare west slope in pastured area.

FD OK - 6/96 - M125-36 - TEMPLIN

N. W. Cor. DLC #47 and Int. "L" Cor. DLC #40.

93

Found - Bl. Oak, now 42", N.60°W. 318.1 ft., opened several years
ago, good scribing visible "24S" & "4W".

No trace of S.E. BT. - Area has been cultivated, but not recently.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, T24S R4W DEC
1963

New BT's: 10" W. Oak S.41°W. 113.4 ft. Mkd: "NW DLC 47 CS BT.
30" W. Oak N.9½°W. 143.4 ft. Mkd: "Int. "L" DLC 40 CS BT.

Old fence corner in present N. & S. fence line bears S.55°E. 2.0 feet.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
March and April 1963
C. S. File No. 53/9