

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21881

James Byron  
Milo Godfrey  
S.A. Bilow  
Dec. 1958  
C.S. File  
No. 49/124

Section Cor. to Secs. 30 & 31, T24-4W. & Secs. 25 & 36, T24-5W. 94  
Found - All 4 BT's. as recorded, except N.59°W. 39.8 ft. which is W. Oak  
recorded as Bl. Oak. Open this BT. & find good scribing "5".  
Orig. 16", now 40" Maple, shows good scribing, center rotted N.61½°E.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1958 R5W R4W 46.2 feet.  
T24S S 25 | S 30  
S 36 | S 31  
New BT: 14" B. Oak bears N.38°W. 13.0 ft. scribed S25 T24S R5W CS BT.  
(see also "Duplicate" Rev. #132)

Most Estrly. S.E. Cor. D.L.C. No. 41. 95  
Found - Splintered Fir Stump, now 60", S.79°E. 124.1 ft. (slope dist.),  
found good reverse scribing "BT".  
50" Fir Stump N.71°E. 166.3 ft. (slope dist.) Cut open & fd. scribing.  
2 Fir Stumps near corner, both with scribing "BT" which I assume  
were marked by Roberts in 1904. However, neither of them fits  
corner as set. No combination or juggling of bearings & distances  
would make it possible to set a corner from these stumps. - See Cor. #10  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T24S R4W E SE DLC 41  
New BT's: 16" D. Fir N.43½°E. 123.4 ft. Mkd: E SE DLC 41 CS BT.  
14" D. Fir N.77°E. 82.7 ft. (88 ft. on 20° slope) Mkd: ESE DLC 41 CS BT  
Note - Corner lies on very steep N.W. slope.

¼ Corner Sections 18 and 17 96  
which is also the N. W. Corner D.L.C. #40.  
Found - Oak, dead & down, N.69°W. 139.9 ft. Cut open & fd. good scribing.  
Large Stump Hole N.8°E. 150.5 ft., pieces of Oak Log lying nearby.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S R4W ¼ S18 | S17  
DLC #40  
New BT's: 18" W. Oak North 19.0 ft. Mkd: ¼ S17 CS BT (clump of 4 trees)  
14" W. Oak N.59°W. 40.1 ft. Mkd: ¼ S18 CS BT (clump of 4 trees)  
Note - A 4-Way fence corner (N.S.E.&W.) bears S.45°E. 14.0 ft.  
Corner lies just west of power line.

S. W. Corner D. L. C. No. 47. 97  
Found - Old Oak, down & dead, S.59°W. 786.7 ft. Cut open & fd. good scribing.  
Old Oak, down & dead, S.52¾°W. 821.0 ft. Cut open & fd. portion  
of "BT" scribing on badly rotted face.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T24S R4W S.W. DLC 47  
New BT: 18" W. Oak N.89°E. 245.7 ft. Mkd: S.W. DLC 47 CS BT.  
No other trees within 600 ft. of corner.  
Note - Corner lies in N. & S. fence line 9.5 ft. South of 4-Way Fence  
Corner (fences N. S. E. & W.)  
Old Iron gate hinge in ground at corner.

Section Corner to Sections 19 - 29 - 20 - 30. 98  
Found - W. Oak Stump S.70°E. 143.2 ft., now 20", Cut open & found good scribing.  
Part of old Oak Stump, S. Side rotted away, N.2°W. 88.4 ft. No mks.  
No trace of N. E. or S. W. Bearing Trees.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S R4W S19 | S20  
S30 | S29  
New BT's: 14" W. Oak S.84°W. 32.5 ft. Mkd: T24S R4W S30 CS BT.  
16" D. Fir N.55°W. 52.4 ft. Mkd: T24S R4W S19 CS BT.  
8" W. Oak N.49°E. 72.6 ft. Mkd: T24S R4W S20 CS BT.  
A Cross, 2" diam. cut in top of S.W. wing wall (south end) of Co. Bridge  
across Oldham Creek bears S.80°E. 108.85 feet.  
Cor. lies just west of power line & approx. 50 ft. N. of English Settlement  
Road, a fence cor. (fences N.-S. & W.) lies 3 ft. West of corner.

¼ Corner to Sections 28 and 33. 99  
Found - 28" W. Oak S.54°E. 440.9 ft. Cut open & fd. faint reverse scribing.  
Tree hollow, center completely rotted away.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S R4W ¼ S28  
S33  
New BT's: 24" Ash S.62°E. 11.2 ft. Mkd: ¼ S33 CS BT.  
9" W. Oak N.52°W. 220.5 ft. Mkd: ¼ S28 CS BT.

Milo E. Godfrey, Deputy County Surveyor  
V. Tracy and Mike Stone  
Mar April 1963  
C. S. File No. 53/9