

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

100

Section Corner to Sections 21 - 22 - 27 - 28.

Found  $\frac{3}{4}$ " Iron Pipe set in 1945. — See Cor. # 15.

18" W.Oak N.20°W. 38.3 ft. Has been opened, probably 1945.

Faint scribing visible on badly rotted face.

20" W.Oak N.39°E. 48.2 ft. Faint scar visible. Did not open.

Down & partly rotted Oak Log S.72°W. 53.5 ft. Cut open & found reverse scribing, "BT".

34" W. Oak S.72°E. 183.5 ft. Shows very plain axe scar. Didn't open.

Iron Pipe at Corner in good condition extends 19" above surface of ground.

New BT's: 9" W.Oak N.4°E. 56.1 ft. Mkd: T24S R4W S22 CS BT.

7" W.Oak N.53°W. 22.0 ft. Mkd: T24S R4W S21 CS BT.

8" Bl.Oak S.61°W. 24.8 ft. Mkd: T24S R4W S28 CS BT.

8" W.Oak S.38 $\frac{1}{2}$ °E. 36.3 ft. Mkd: T24S R4W S27 BT CS.

101

$\frac{1}{4}$  Corner to Sections 27 and 34.

Found - Laurel Stool of Young Shoots with large Stump Hole in center.

Fragments of rotten Laurel Wood on ground. Found old axe marks in wood, also a faint, illegible, portion of reverse scribing on badly rotted face. Laurel S.76°W. 20.5 ft. #186

Found, Stump Hole only N.20°E. 59.4 ft. No trace of tree remains.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W  $\frac{1}{4}$  S27  
Office, 1963 S34

New BT's: 11" D.Fir N.31°E. 21.6 ft. Mkd:  $\frac{1}{4}$  S27 CS BT.

6" D.Fir S.35°W. 15.2 ft. Mkd:  $\frac{1}{4}$  S34 CS BT.

Corner lies on West slope approx. 50 ft. West of top of spur sloping N.W.

FD. OK 12-95 BY CHRISTENSEN M 123-21

102

Section Corner to Sections 27 - 28 - 33 - 34.

Found - 18" W.Oak S.10°W. 57.4 ft. Cut open & fd. good scribing "W".

(Size when scribed approx. 6", not 18")

Rotten Oak Uproot S.75°E. 102.3 ft. Found portion of over-growth of old face with good reverse scribing "S".

20" W.Oak N.77°W. (not N.80°W) 103.0 ft. Opened & fd. good scribng.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W S28 | S27  
Office, 1963 S33 | S34

New BT's: 9" D.Fir S.57°E. 15.3 ft. Mkd: T24S R4W S34 CS BT.

10" D.Fir N.76°W. 9.7 ft. Mkd: T24S R4W S28 CS BT.

16" D.Fir N.50°E. 19.4 ft. Mkd: T24S R4W S27 CS BT.

11" D.Fir S.38 $\frac{1}{2}$ °W. 22.0 ft. Mkd: T24S R4W S33 CS BT.

103

Most Southerly S.E. Cor. D.L.C. No. 40.

Found - 36" Bl.Oak N.89°W. 669.9 ft. Opened scar & fd. good scribng.

No trace of S. W. tree. Position for Corner falls in field.

Set - Witness Corner 6 ft. West of Corner.

Brass Cap Mkd: County Surveyor's Office, 1963

T24S R4W WC SE DLC 40 6 Ft. E. to Corner.

New BT: 22" W.Oak N.53 $\frac{1}{2}$ °W. 487.4 ft. Mkd: WC S SE DLC 40 CS BT.

Witness Corner lies 1 foot East of N. & South Fence line.

104

N. E. Corner D.L.C. No. 43.

Found - Oak, down & partly rotten, S.20°W. 54.1 ft. (slope dist.)

Cut open & found good reverse scribing.

32" W.Oak N.80°E. 125.4 ft. (slope dist.) Shows scar. Didn't open.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W

Office, 1963 N.E. DLC 43

New BT's: 12" W.Oak N.81°W. 16.1 ft. Mkd: NE DLC 43 CS BT.

13" W.Oak N.9°E. 44.0 ft. Mkd: N.E. DEC 43 CS BT.

105

N. W. Corner Bl L. C. No. 43.

Found - Hollow dead Oak Snag N.30°E. 9.2 ft. Cut open & fd. reverse face with reverse scribing visible "24S".

Stump Hole & Rotten Oak Log S.60°E, 17.8 ft. Didn't look for scribng.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

T24S R4W NW DLC 43

New BT's: 11" D.Fir S.10°E. 13.0 ft. Mkd: NW DLC 43 CS BT.

12" D.Fir N.43°E. 12.0 ft. Mkd: NW DLC 43 CS BT.

Corner lies on S. slope approx. 200 ft. S. of ridge Top. A N.&S. Fence line is 24 feet East of Corner.

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
May 1963  
C. S. File No. 53/9 C.S. 53/9

FD. OK  
11/95 BY CHRISTENSEN  
M 123-21

REF