

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

112

Interior "L" DLC No. 44 & N.E. Corner DLC No. 45.
Found - 66" Fir Stump S.51°E. 214.5 ft., opened & found good scribing "BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
N.E. DLC No. 45 | Int. "L" DLC 44
New BT's: 12" W.Oak S.42°E. 11.3 ft. Mkd: Int. DLC 44 CS BT.
18" W.Oak S.14°W. 35.6 ft. Mkd: NE DLC 45 CS BT.

113

S. S.W. Corner DLC No. 44 and E. S.E. Corner DLC No. 45.
Found - 66" Dead Fir Snag N.24°W. 244.9 ft. Opened & found good scrbing.
No trace of Southwest Tree.
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1963
T24S R4W E. SE | S SW
DLC 45 | DLC 44
New BT's: 10" D.Fir N.43°E. 3.3 ft. Mkd: S SW DLC 44 CS BT
8" D.Fir N.67°W. 8.5 ft. Mkd: E SE DLC 45
Corner lies on N. W. slope in dense thicket of young fir timber.

114

N. W. Corner D. L. C. No. 45.
Found - 22" W.Oak N.73½°W. 623.7 ft. Cut open & found good scribing.
Down & badly burned Oak N.80°W. 521.4 ft. Good reverse scrbing.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W NW DLC 45 |
New BT's: 15" W.Oak N.66°W. 81.3 ft. Mkd: NW DLC 45 CS BT.
8" W.Oak N.46°E. 33.4 ft. Mkd: NW DKC 45 CS BT.
Corner lies 15 ft. west of a N. & S. fence line & 7 ft. south of
small creek flowing S. E.

115

Most Southerly S. E. Corner D.L.C. No. 47.
Set - from distance East of S.W. corner DLC 47, according to gov't notes.
Call to N.E. BT. evidently in error - N.W. tree not found. The
S.W. corner was set from both old BT's. The S.W. corner is nearer
to this S. SE. corner than the BT. found.
Found - 42" W.Oak N.52°E. 785.0 ft. (record bearing & dist. is N.44°E.
846.1 ft.) Opened & found scribing "24S 4W".
No trace of N. W. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W S SE DLC 47 |
New BT's: 7" W.Oak S.41°W. 150.8 ft. Mkd: S SE DLC 47 CS BT.
14" W.Oak (in clump of 8 trees) S.20°W. 256.6 ft. Mkd:
S SE DLC 47 CS BT.
Corner lies in E. and W. fence line. Fence Corner (fences North & West)
bears East 36.5 feet.

116

¼ Corner to Sections 32 and 33.
Found - 32" W.O., showing faint scar. Inside found good "¼S" scribe
& reverse of scribe. This tree faced good for bearing, called
for N.25°E.
No trace of other Bearing Trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W ¼ S32/S33
New BT's: 7" W.O. N.75°E. 147.3 ft. Mkd: ¼ S33 CS BT.
13" Ash S.24°W. 273.3 ft. Mkd: ¼ S32 CS BT.

117

Section Corner to Secs. 32 & 33, T24-4W & Secs. 4 & 5, T25-4W.
Found - 28" Rotted Oak Stump S.53½°W. 128.7 ft. No scribing.
28" W.O. N.38½°W. 55.4 ft. & chopped it open & fd. "4W"
48" W.O. S.54½°E. 219.1 ft., shows good scar.
No trace of other Bearing Tree.
1" I. Rod and a Sandstone 9" x 16" x 6".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24 S32 | S33 R4W
T25S S 5 | S 4
New BT's: 7" W.O. N.60°E. 19.0 ft. Mkd: T24S R4W S33 CS BT.
9" D.Fir N.24°W. 55.2 ft. Mkd: T24S R4W S32 CS BT.
7" D.Fir S.14°E. 46.5 ft. Mkd: T25S R4W S4 CS BT.
5" W.O. S.41½°W. 28.7 ft. Mkd: T25S R4W S5 CS BT.

FD OK 12/95 H. Christiansen M123-25 A+B

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
May 1963
C. S. File No. 53/9

FD OK 8/92 D. PZEL
M 115-62