

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

123

1/4 Corner to Sec. 31, T24-4W. & Sec. 6, T25-4W.

Found - Mound of Rock at Corner (No Record)

Down & Partly Rotted Old Oak N.11 1/2°W. 231.7 ft. Opened & found fragmentary but legible reverse scribing "1/4 S".

30" Bl. Oak S.69°W. 351.1 ft. Alive & Standing, shows good scars, did not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S 1/4 S31
(Replace Rocks around Office, 1963 T25S R4W S 6
Cap)

New BT's: 15" W.Oak N.10 1/2°W. 148.5 ft. Mkd: 1/4 S31 CS BT.

9" W.Oak S.28°E. 59.6 ft. Mkd: 1/4 S6 CS BT.

Note - Corner lies 8 ft. west of a N. & S. Fence Line.

FD B.C.
n/16 W. Barnes
11-60-70

124

Corner to Sections 7 and 18 only, T24-3W.

East Boundary of T24S R4W.

Found - Brass Cap set in 1950 - Corner lies on high mound in center of Logging Road.

24" Dead Cedar Snag S.85°E. 61.4 ft., shows good scar.

Fir Stump N.35 1/2°E. 68.6 ft., is almost completely buried in road fill.

New BT's: 14" R.Cedar N.33°E. 103.8 ft. Mkd: T24S R3W S7 CS BT.

6" D.Fir S.39 1/2°E. 69.2 ft. Mkd: T24S R3W S18 CS BT.

RE-RENEWED, SEE CORNER NO. #171

125

Township Corner -

S36	S31	T24S
R4W	S 1 S 6	R3W T25S

Found - Brass Cap set by Price, 1944, buried under fill on W. side of Logging Railroad.

18" D.Fir S.58°E. 71.9 ft. Cut open & fd. traces of scribing on badly rotted face.

Stump of 50" Fir S.69°W. 219.8 ft. (across Calapooia from cor.) Shows good scar.

No trace of N. E. or N. W. Bearing Trees.

Dig around & Straighten Brass Cap - Drive Cedar Stake alongside.

New BT's: 18" D.Fir S.58°E. 71.9 ft. Mkd: T25S R3W S6 CS BT. (Rescribed)

9" D.Fir N.82 1/2°E. 66.1 ft. Mkd: T24S R3W S31 CS BT. (new tree)

10" D.Fir S.81°W. 34.5 ft. Mkd: T25S R4W S1 CS BT. (new tree)

18" D.Fir N.4°W. 50.4 ft. Mkd: T24S R4W S36 CS BT. " "

FO. OK 12/95 BY CHRISTENSEN M 123-21

126

1/4 Corner to Sections 27 and 26.

Found - 36" Fir Snag, old & rotten, S.57°W. 21.1 ft. Portions of bark scribing visible "1/4" & "B".

Stump Hole with small fragments of rotten Laurel wood

N.75°E. 25.1 ft., not enough left to find any markings.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

T24S R4W 1/4 S27/S26

New BT's: 11" B.Oak N.14°E. 24.0 ft. Mkd: 1/4 S26 CS BT.

8" D.Fir N.46°W. 16.8 ft. Mkd: 1/4 S27 CS BT.

Corner lies in fence corner, fences South & East from Corner.

FO. OK 12/95 BY CHRISTENSEN M 123-21

127

1/4 Corner to Sections 33 and 34.

Found - Old 24" Fir Snag, rotten & badly charred, N.30°E. 25.1 ft.

2 old charred faces visible, faint scribing "BT" visible on lower face & part of "4" visible on upper face.

No trace of N. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

T24S R4W 1/4 S33/S34

New BT's: 24" D.Fir S.25°E. 25.8 ft. Mkd: 1/4 S34 CS BT.

26" D.Fir S.28°W. 38.3 ft. Mkd: 1/4 S33 CS BT.

The N. end of a fence line running approx. south, is fastened to the S. E. BT., old timber in S.W. Quad., All other directions have been logged off.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
May 1963
C. S. File No. 53/9