

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21991

134

1/4 Corner to Section 35 and 36.
Found - 34" W.Oak N.63°E. 153.1 ft., showed 2 very plain scars,
opened & found fragment of reverse scribing "1". Tree
rotted out inside, destroying most of the scribing before
the scar healed over.
No trace of N. W. Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W 1/4 S35/S36
New BT's: 36" I. Cedar S.63°E. 60.0 ft. Mkd: 1/4 S36 CS BT.
7" D.Fir S.87°W. 41.0 ft. Mkd: 1/4 S35 CS BT.
Note - Corner lies in nearly level creek valley, approximately
150 feet west of creek.

135

1/4 Corner to Sections 26 and 35.
Found - Stump hole & remains of rotted Oak Log S.58°W. 23.8 ft.,
Found good reverse scribing "1/4 S" & portion of "BT".
Old Laurel, down & shoved out of position, N.25°W. 22.4 ft.
Could not determine exactly where it stood, opened
& found portion of reverse scribing "4 & S".
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W 1/4 S26
Office, 1963 S35
New BT's: 16" D.Fir S.33°W. 12.6 ft. Mkd: 1/4 S35 CS BT.
10" D.Fir N.12°W. 17.9 ft. Mkd: 1/4 S26 CS BT.
Note - Corner lies on nearly flat area on top of ridge at head
of draw running south.

136

Section Corner to Secs. 35 & 36, T24-4W. & Secs. 1 & 2, T25-4W.
Found - 14" W.Oak N.30°E. 63.4 ft. (to face) opened & found good
scribing "CS".
14" W.Oak N.54°W. 18.5 ft. (to face) shows good scar.
Did not open.
10" W.Oak, in clump of 7, S.42°W. 21.8 ft. (to face)
Shows scar, Did not open.
Dead Oak Snag S.37°E. 119.0 ft. Had been opened previously,
shows old axe marks, face rotted - (Orig BT)
Shell of old Oak Stump S.84°W. 103.5 ft. (possible Orig. BT)
Does not fit bearing & distance on Gov't. notes.
No trace of other Orig. BT's.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W S35/S36
Office, 1963 T25S R4W S 2 | S 1
New BT's: (Rescribe) 10" W.Oak S.42°W. 21.8 ft. Mkd: T25S R4W S2 CS BT.
10" W.Oak N.41°E. 62.6 ft. Mkd: T24S R4W S36 CS BT.
11" W.Oak S.3 1/2°E. 35.3 ft. Mkd: T25S R4W S1 CS BT.
10" W.Oak N.88°W. 26.1 ft. Mkd: T24S R4W S35 CS BT.

SEE ROW.
#31
T. 25-4

137

FD. OK 12/95 BY CHRISTENSEN M123-21
Section Corner to Secs. 34 & 35, T24-4W. & Secs. 3 & 2, T25-4W.
Found - 20" W.Oak S.7 1/4°W. 223.1 ft. (slope dist.) Cut open &
found good scribing "25S R4W".
20" W.Oak S.10°E. 429.0 ft. Opened & found good scribing.
24" W.Oak N.5°E. 306.9 ft. (slope dist.) Opnd.&fd. good scrbing.
No trace of N.W. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W S34 S35
Rocks piled below pipe-Office, 1963 T25S S 3 S 2
New BT's: 24" D.Fir S.75°W. 65.7 ft. Mkd: T25S R4W S3 CS BT.
34" I.Cedar N.51°W. 30.5 ft. Mkd: T24S R4W S34 CS BT. (scribed above fence)
16" W.Oak S.50°E. 63.7 ft. Mkd: T25S R4W S2 CS BT.
No trees near in Section 36.
Corner lies on steep south slope, bedrock close to ground surface.
A fence corner, fences north, south & west is fastened to N.W. BT.

FILE E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
June 1963
C. S. File No. 53/9