

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
June 12, 1963
C. S. File No. 53/9

Closing Corner to Sections 12 and 13.

(West line of Sec. 7, T24S R3W)

Found - G.L.O. Brass Cap set in 1950, mkd: as described in Gov't. notes.
8" Fir S. $81\frac{1}{2}^{\circ}$ W. 31.0 ft. is broken, down & dead, some scribing
visible on partly rotted face.

No trace of N.W. Bearing Tree.

New BT's: 11" Red Cedar N. 42° W. 78.7 ft. Mkd: T24S R4W CC S12 CS BT.

9" Red Cedar S. 46° W. 14.9 ft. Mkd: T24S R4W CC S13 CS BT.

138

$\frac{1}{4}$ Corner to Sections 12 and 13.

Found - 36" Doug. Fir N. 78° E. 30.4 ft. Has been opened previously,
scribing (portion of "S") visible in opening. Tree alive.

Maple, down & rotten, S. $58\frac{1}{2}^{\circ}$ W. 20.5 ft., no scribing found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W $\frac{1}{4}$ S12
Office, 1963 S13

New BT's: 10" I. Cedar N. 56° E. 17.5 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

20" D. Fir S. 9° E. 39.7 ft. Mkd: $\frac{1}{4}$ S13 CS BT.

Note - Corner lies in bottom of small draw on steep south slope.

139

West $\frac{1}{4}$ Corner to Section 18, T24S R3W.

(on East line of Sec. 13, T24S R4W)

Found - Iron Pipe with B.L.O. Brass Cap set in 1950 in good condition.

22" Fir S. 19° E. 38.3 ft. is alive & in good condition, scar plain.

Sawed Stump of 22" Fir N. $43\frac{1}{2}^{\circ}$ E. 76.6 ft., scribe visible.

New BT: 6" White Fir N. 52° E. 26.9 ft. Mkd: $\frac{1}{4}$ S18 CS BT.

140

West $\frac{1}{4}$ Corner to Section 19 only, T24-3W.

On East Line Sec. 24, T24-4W.

Found - G. L. O. Brass Cap set in 1950

13" Red Cedar S. $84\frac{1}{2}^{\circ}$ E. 59.4 ft. Alive & in good condition, shows scar.

Sawed Stump of 32" Fir N. $64\frac{1}{2}^{\circ}$ E. 19.8 ft. Face still on stump.

New BT: 12" Hemlock N. $77\frac{1}{2}^{\circ}$ E. 55.3 ft. Mkd: $\frac{1}{4}$ S19 CS BT.

141

East $\frac{1}{4}$ Corner to Section 12 only, T24-4W.

On West line Sec. 7, T24-3W.

Found - G. L. O. Brass Cap at Corner set in 1950 survey.

20" Red Cedar S. 64° W. 54.1 ft. All scribing ($\frac{1}{4}$ S12 BT) visible in not
yet healed over blaze, Tree alive & in good condition.

20" Hemlock to the N. W. is uprooted, down and dead.

New BT: 7" Hemlock N. 44° W. 45.5 ft. Mkd: $\frac{1}{4}$ S12 CS BT.

Note - Corner lies on bench near foot of steep S. W. slope.

142

Orig. Closing Corner to Section 12 and 13, only, T24-4W.

On West Line Sec. 7, T24-3W.

Found - 34" Cedar S. 73° W. 21.8 ft., previously opened, old scribing "13BT".
vis. on old face, Tree still alive, but top broken out approx.

40 ft. above ground, newer scribing visible "EM BT"

32" Fir N. 6° W. 31.0 ft. Has been opened previously but scar nearly
healed shut. No scribing visible, newer blaze below, also healed over

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W Orig. CC S12
Office, 1963 S13

Note - From this Corner, brass cap set by Price for CC S12 & S13 bears
West 41.6 ft. (63 lks. instead of 62 lks.)

DID NOT MARK ANY NEW BEARING TREES.

143

$\frac{1}{4}$ Corner to Sections 24 and 25.

Found - Cedar N. 45° W. 5.3 ft., uprooted, down & badly rotted, previously
opened, scribing visible, portion of "S" & "B".

No trace remains of S. W. Bearing Tree.

Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W $\frac{1}{4}$ S24
Office, 1963 S25

New BT's: 12" Hemlock N. 23° E. 9.6 ft. Mkd: $\frac{1}{4}$ S24 CS BT.

12" Red Cedar S. 17° W. 27.4 ft. Mkd: $\frac{1}{4}$ S25 CS BT.

Corner lies on fairly steep East slope, approx. 65 ft. West of small stream.

144