

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

152

Milo E. Godfrey
Vernon Tracy and
Mike Stone
July 1963
C. S. File No. 53/9

S. W. Corner Section 31, T23S R3W. SW Cor. S31
Found - Brass Cap set by Prine in mound of rocks.
30" Fir Stump(sawed high) N.21°E. 175.6 ft., all scribing visible.
82" Fir Stump N.63³/₄°E. 169.6 ft., scribing visible "31 BT".
2 Fir Snags mentioned by Price:
22" Fir Stub S.57³/₄°W. 24.4 ft., charred face.
50" Fir Snag N.30°W. 59.4 ft., axe scar on bark (charred).
New BT's: 28" D.Fir S.59°W. 55.1 ft. Mkd: T23S R3W S31 CS BT.
7" Chinq. N.54°E. 35.8 ft. Mkd: T23S R3W S31 CS BT.
No more suitable trees available to N.E.

July 15, 1963

153

Milo E. Godfrey
Vernon Tracy &
Mike Stone.
Feb. 1963
C. S. File
No. 53/9

1/4 Section Corner to Sections 15 and 14.
Found-Fir Snag, now 32", S.78°E. 22.4 ft., good bark scribing
visible "1/4 S BT".
No trace found of S. W. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T24S R4W 1/4 S15/S14
New BT's: 10" D.Fir N.34°E. 54.0 ft. Mkd: 1/4 S14 CS BT.
6" W.Fir S.20°W. 44.9 ft. Mkd: 1/4 S15 CS BT.

SEPT. '68

MICROFILM TO HERE 10/67

154

John Powell
W. Penley &
J. Heritage
C.S. File
No.
53/9

West 1/16 Corner Sections 25 and 36.
Found = 1963 B.L.M. Brass Cap, properly mkd.
28" D.Fir N. 78¹/₂° W. 5.9 ft. pitched over, scribe visible.
(This tree to be cut, high stump)
29" D.Fir S.32°E. 18.5 ft., pitched over, scribe visible.
New BT: 18" Double Cedar N.15°W.42.6 ft., scribed "W 1/16 S25 CS BT".
Bearing Object: 5/8" I.Rod at base of 30" D.Fir Stump N.20°E. 39.1 ft.
10/9/70

155

V. "Ray"
Tracy &
Crew
C.S.
File
No. 53/9

Section Corner to Sections 28 - 29 - 32 - 33.
Found - 1960 C.S. Brass Cap, in place, properly marked, See Ren. #42.
Orig. 24", now 50" W.Oak, alive, N.25°E. 277.2 ft., "R4W" scribe visible.
24" B.Oak N.38¹/₂°E. 245.5 ft., healing blaze, to be cut for view
of valley.
16" W.Oak N.83¹/₂°E. 254.5 ft., alive, healed blaze.
A new concrete block house is being constructed, we tie brass cap to
S.E. porch roof support pipe & 3" I.P. N. 4° E. 83.3 ft.
The S, W. Corner of house bears N.18°W. 110.0 ft.

The house sets on top of hill & Sec. Cor. lies S. on moderate S. E. slope.

11/10/70

156

L.E. Monrean
D. E.
J.H.C.
C.S. 57/39
11/26/75

1/4 Corner to Sec. 4 and 3
Found- 1961 C.S. Brass cap in place, properly marked See Ren #85 & 47
A Fir stump 14 (now, bark gone, 32) inch dia. bears N13 1/2°W, 25.7 ft. (rec. 24.4 ft) scribed " 1/4 S BT"
A Fir stump, 18 (now 28) " dia. bears S53°E, 10.6 ft. (rec. S49°E). Stump is out of ground, has good blaze.
A D fir stump, 38" dia bears N80°E, 33.6 ft (rec N78°E) scribed "CS BT"
Incense cedar, 12 (now 19) " diam. bears S 58 1/2°W, 111.3 ft. (rec S57°W) has good blaze, tagged.
Remains of stump bears S33°W, 36.6 ft, broke off near ground, (rec. Ren#47, 14" R Fir S 33°W, 36.6 ft).
Renewal- A douglas Fir, 12 " diam. bears N8°E., 203.9 ft. scribed "1/4 S3 CS BT"
11/26/75

157

W. S. Barnes
For: Richard McGarvey
July 1976
M 60 - 70 3/77

Section Corner for Secs. 31, 32 and 6 & 5, T25-4
Set - 3/4" Iron Pipe by Single Proportion.
Found - Stone with X 10.0 ft. East of 1947 record. Ren. #2
July 1976

JAN 78
1-79