

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

160

(CONT.)

healed, pitched-over blaze bears S.57 1/2 °E., 6.2-ft. (Rec. 7.3-ft.).
No other BT's found...SW BT decayed during 1950 Resurvey; NW BT position located in newly logged area.
New BT's- 9" W. Fir Double blazed & scribed "T24S R4W S24 CS BT" bears N.9 1/2 °W., 8.2-ft.
6" W. Fir Double blazed & scribed "S19 CS BT" bears N.70°E., 64.9-ft.
8" W. Fir Double blazed & scribed "T24S R4W S30 CS BT" bears S.66°E., 47.0-ft.
New BO - Set bridge spike in 48" Red Cedar stump, 2-ft high, stamped: "BO" bears S.13 1/2 °E., 14.6-ft.
Note - Corner lies approx. 15-ft. North of E-W cutting line in a logged area. 11/17/81

161

East 1/4 corner of Sec. 24 only.
Found - BLM B.C. properly stamped, protruding 10" 1950 RESURVEY. above the ground.
BT's - 6" Maple, now 9" w/well healed blaze bears S.11 1/2 °W., 40.7-ft. (Rec. S.6°W., 37.6-ft.).
14" Fir, now 22" stump, 6-ft. high w/well healed blaze bears N.88 3/4 °W., 27.1-ft.
New BT - 5" Hemlock bears N.7°W., 50.7-ft., blazed an X on tree trunk, blaze & scribe "BT" near base.
New BO - Set a RR spike in outer pitch ring of a 46" Fir stump, 2-ft. high, stamped "BO" bears S.35 1/2 °W., 66.8-ft.
Note - Corner lies on a steep North slope, in logged unit, 600-ft. South of cut-line corner. See sketch in file. 11/23/81

162

West 1/4 corner of Sec. 19 only in T. 24-3.
Found - BLM B.C. properly stamped, protruding 3" 1950 RESURVEY. above ground.
BT's - 32" Fir bears N.64 1/2° E., 19.8-ft. with "1/4 S19" visible on partially healed blaze. Now a stump.
13" now 24" Cedar bears S.83°E., 59.4-ft. (Rec. S.84 1/2 °E.), with a well healed single blaze.
12" Hemlock now 16" bears N.77 1/2° E., 55.3-ft. "S19 CS B" visible on a partially healed single blaze. Ren.# 141.
New BT - 9" Cedar bears N.33 1/2°E., 39.5-ft. scribed "1/4 S19 CS-BT" on a double blaze
14" Maple bears S.21°E., 46.4-ft scribed "1/4-S19 CS BT" on a double blaze
Note - Maple tree is on the corner of a cutting line. 11/23/81

163

Center 1/4 Corner for Section 16
Set - 5/8" iron rod on southwesterly slope of hill approx. 150 ft. east of line in a 24" fir stump from which
BT's - a 6" maple bears N.33°E., 32.0 ft. scribed C 1/4 S16 T24S R4W BT.
a 6" maple bears N.87°E., 28.0 ft. scribed C 1/4 S16 T24S R4W BT.

164

Center 1/4 Corner for Section 15
Set - 5/8" iron rod from which:
BT's - a 6" fir bears S.53°E., 4.0 ft. scribed C 1/4 S15 T24S R4W BT.
Note: Corner lies N.15°E., 200 ft. from sharp curve in road.

165

1/4 Corner for Sections 15 and 22
Set - 5/8" iron rod from which:
BT's - a 6" fir bears S.38°W., 88.0 ft. scribed 1/4 S22 T24S R4W BT.
an 18" oak bears N.88°W., 110.0 ft. scribed 1/4 S15 T24S R4W BT.
Note: Corner is north 8 ft. of bottom of drainage.

Larry E. Monrean
Deputy, Doug. Cou.
Surveyors Office
T. Plouff, witness
Nov. 17, 1981
C.S. 61 / 29

Larry E. Monrean
Deputy, Doug. Co.
Surveyor's Office
T. Plouff, witness
Nov. 17, 1981
C.S. 61 / 29

Donald Bentz
For: Knight Ranch
November 1980
M 91 - 2
(Map filed Jan. 1982)