

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T. 24                      T. S.                      R. 4                      R. W. W. M.

FORE-CHAPMAN CO., EUGENE, ORE. 21881

*FD OK 12/95, H. CHRISTENSEN M123-25 4/13*

**180**

¼ cor. of sec. 34 & 35 T24S R4W

Found - A 3¼" BLM Brass Cap on a 2½" Iron Pipe, protruded 3" above ground  
(Set at position as determined in 1985 BLM Survey).

U.S. Dept of The Interior

T24S R4W

¼

S34 | S35

1985

1972

Bur. of Land Management

BT's Found -

32" now 32" dia. 2 ft. high D. Fir stump with partially healed lower blaze no scribing visible bears N.76°W., 33.7 ft. (agrees with record) 1985 BLM.

14" now 15" dia. ash with a partialy healed single blaze scribing visible "¼ S35 BT" bears N.61°E., 43.2 ft (agrees with record) 1985 BLM.

New BT's -

5" D. Fir double blazed and scribed "¼ S35 CS BT" bears S.38°E., 42.2 ft.

7" "X" chisled in top of northwest corner of concrete cattle guard structure, bears S.5°E., 66.2 ft.

13" dia. maple, double blazed and scribed "¼ S34 CS BT" bears N.53¼°W., 100.5 ft.

corner lies approx. 60' northerly of a gravel road and cattle guard, 8 ft. west of a north-south running fence line.

**181**

Secs. 5 & 6; 31 & 32 T23-4

Found - DC Brass cap dated 1963 (Ren # 51)

30" W.Oak log, N.70°W., 103.0'. - Down & out - Rec. N.70°W., 156 lks, - 1855 GLO

26" I.Cedar, S.41°W., 21.2' - Closed face - Rec. S.39°W., 21.4' - 1963 Douglas Co.

26" Fir, S.10°E., 34.9' - Closed face - Rec. S.10°E., 34.9' - 1963 Douglas Co.

Set - 15" Alder (in clump), N.5°E., 18.1' to "W" nail - bark scribed "T23S R4W S32 BT"

10" Fir, N.73°W., 68.0' to "W" nail - scribed "T23S R4W S31 BT"

*see Ren. # 119*

**182**

SEC. 29 SW COR

Mon. Fd. - None, evidence of road work and fence building in area.

Accessories Fd. -

9" now 15" dia, 2' high rotted D.Fir stump, with scribing found "BT", bears N.73°W., 82.6'

8" now 13" dia, Madrone, with a fully healed single blaze, bears S.83°E., 105.4'

8" now 16" 3' high D.Fir stump, with a fully healed single blaze, bears N.59°E. 160'

Mon. Set - 2 3/8" Dia. DCSO Brass cap on a 1 3/8" O.D. by 32" long iron pipe is set at a position determined from BT's, protrudes 7" above ground.

New Accessories -

NE corner of power line tower, where it meet 3' dia 2' high concrete post at NE cor., bears S.11¼°E., 305.2'. (No. "4 PP&L - BPA 42").

5/8" I.R. with alum. cap stamp, "B0-1 1995", bears N.8 3/4°W., 46.7', protrudes 4" above ground.

No reasonable trees in vicinity

Corner is 2' south of a east-west fence and 11' west of dirt road centerline, corner lies near top of ridge in power line easement.

*FD OK 1/23/96, H. CHRISTENSEN, M123 36*

Douglas Co. Surveyors  
Randall Smith  
Stephen Flause  
Sept. 20, 1993  
C.S. File 64/47

Dan Baker  
Weyerhaeuser Co.  
9/94 M 119-40

Douglas County Surveyors  
Randall SMITH & Stephen Flause  
Apr. 1995 C.S. 64/63-7

*see next page*