

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 4 W. R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97501

FORD-NESS-FASSBENDER  
BY STEVEN NESS  
6/25/97  
C.S. 65/15-4B

EAST  $\frac{1}{4}$  CORNER SEC. 10

194

Mon. Fd.- 2 $\frac{1}{2}$ " DCSO Brass cap on a 1 $\frac{1}{4}$ " I.post, top 14" above ground for witness corner (actual corner position is south 40.0' in creek) the following BT's reference the witness corner.

Bt's FD.- 21" D.Fir, S.72°48'E., 39.4', face healed.  
20" D.Fir, S.30°34'E., 26.1, face no healed, scribing "WC  $\frac{1}{4}$  S11 CS BT" visible. snag is about 30' tall.

New Accessories -

9" D.Fir, N.5°09'W., 19.5', scribed "X" on chest high face, scribe "BT" on low face.

The corner is in the NW corner of a recently harvested BLM clear-cut unit. It is + or - 880' east of ridge top.

Mark Smalley  
Roseburg Forest Products  
8/11 & 12/1998  
C.S. File 65/20-39 & 40

Center 1/4 cor. Sec. 16

195

Found - 5/8" I.P.

7" B.Oak, N.33°E., 30.8', good, healed. Plat M 91-2 called this BT 6" Maple N.33°E., 32.0' - We chopped out the face. (Ren. #163)

9" Maple, N.87°E., 28.0', good, healed face.

New BT's - 8" Maple, S.2°E., 26.8', "C  $\frac{1}{4}$  BT"

8" Cedar, N.46°W., 14.5', "C  $\frac{1}{4}$  BT"

N 1/4 Cor. Sec. 16

196

Found - 1963 DCSO BC/IP *Ren #162*

11" Cedar, S.37°W., 17.3', good, healed face.

20" Cedar, N.45°E., 29.5', good, healed face.

28" Maple, N.19°W., 9.2', rotted center - hollow.

New BT's - 9" Fir, N.62°E., 12.5', " $\frac{1}{4}$  S BT"

14" Alder, S.29°E., 27.3', " $\frac{1}{4}$  S BT"

Note - Monument at fence corner. Fences run North, East & West.