

**Douglas County Surveyor's Record of
Government Corners Renewed**

24 T. S. 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

C.S. File No. 49/42

36

Sec. Cor. to Secs. 4 & 5, T24S R5W., & Secs. 32 & 33, T23S R5W.
Found - 3 Orig. BT's. - Orig. 28", now 40", W.Oak N. 9 $\frac{3}{4}$ °E.
539.9 ft., shows good scars. I do not open.
Orig. 60", now 24" W.Oak N. 2°W. 308.9 ft., shows good
scars., I open center, rotted, no scribing found.
Orig. 16", now down & mostly rotted Oak, S. 23 $\frac{1}{2}$ °E. 376.9 ft.,
shows good scribing, reverse, on trunk section "BT W".
Orig. S.W. BT. not found.

Set Brass Cap Mkd: County Surveyor's Office, 1959

S32	S33	T23S R5W
S 5	S 4	T24S R5W

New BT's: 6" W.Oak bears N. 57°E. 12.0 ft. scribed S33 T23S R5W CS BT.
12" R.Fir bears S. 33°W. 19.7 ft. scribed S 5 T24S R5W CS BT.
9" R.Fir bears S. 57°E. 32.2 ft. scribed S 4 T24S R5W CS BT.
28" B.Oak bears N. 10°W. 60.0 ft. scribed S32 T23S R5W CS BT.

Note - 3 Way Fence Corner bears N. 28°W. 30 ft., more or less.

*Fd 7/90
1990-0035*

37

$\frac{1}{4}$ Sec. Cor. to Sec. 6 and 5.
Found - Orig. 20", now down & mostly rotted Oak S. 77°E. 127.4 ft.,
no scribing.

Orig. 30", now 33" B.Oak N. 42 $\frac{1}{2}$ °W. 167.0 ft., I open &
find good scribing "3 BT".

Note - This BT. scribed high & all scribing on one face, also
this BT. was 20" & not 30" as recorded.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

$\frac{1}{4}$ S 6	S 5	T24S R5W
-------------------	-----	----------

New BT's: 7" R.Fir bears S. 17°E. 52.0 ft. scribed $\frac{1}{4}$ S5 CS BT.
9" W.Oak bears S. 25°W. 74.5 ft. scribed $\frac{1}{4}$ S6 CS BT.

Section Corner to Sections 5, 6, 7, 8.

Found - Orig. 12", now 30" B.Oak Snag N. 58°W. 122.1 ft., opened
years ago. Old faces rotted, no scribing found.

No trace of Orig. SE. BT found. (in field). I find depression
which may have been location of Orig. S.W. BT. Record
calls for two BT's. to N.W. I believe it should read
S. 75°W. 216.5 ft.

48" W.Oak checks Orig. bearing for N.E. BT. dist. 441.0 ft.
shows old axe work, center rotted, no scribing found.

Set Brass Cap at Corner Mkd. County Surveyor's Office, 1959

S 6	S 5	T24S R5W
S 7	S 8	

New BT's: 11" B.Oak, double, bears S. 73°W. 24.0 ft. scribed S7 T24S R5W CS BT.
7" W.Oak bears N. 50°W. 50.7 ft. scribed S8 T24S R5W CS BT.
16" W.Oak bears N. 7°E. 29.5 ft. scribed S5 T24S R5W CS BT.
This tree shows scribe marks made several years ago.
Not of record, faces to corner.
4" W.Oak bears S. 54°E. 85.2 ft. scribed S8 CS BT.

*FWD OK
3/21 M.M. 64*

38

$\frac{1}{4}$ Section Corner to Sections 7 and 18.

Found - Orig. 10", now 30" W.Oak S. 10°W. 472.6 ft. I open & find
good scribing "B".

Orig. 30", now 34" partly rotted Oak Stump, checks record
dist. & bearing for Orig.

S.E. BT., no scribing found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{1}{4}$ S 7	T24S R5W
S 18	

New BT's: 14" W.Oak bears N. 19°W. 21.2' ft. scribed $\frac{1}{4}$ S7 CS BT.
7" W.Oak bears S. 8°E. 15.8 ft. scribed $\frac{1}{4}$ S18 CS BT.

39

$\frac{1}{4}$ Section Corner to Sections 17 and 18.

Found - Rock 3" x 7" x 10 $\frac{1}{2}$ " at Corner.

W. Oak, 40", N. 10°E. 39.6 ft., chopped open & fd. reverse
face with small fragment of reverse scribing. Face had
rotted away, apparently tree had been opened previously
& grown back after most of face had rotted.

Oak Stump, now 34", S. 33°W. 92.4 ft. Had been cut off too

40

C.S. File No. 49/124

(CONTINUED OVER)

James W. Byron, Deputy County Surveyor
Milo Godfrey
Clete Putnam
Dec. 16, 1959
C. S. File No. 49/124