

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1960

$\frac{S\ 4}{S\ 9} \mid \frac{S\ 3}{S\ 10}$ T24S R5W

Blaze & Scribe two New Trees:

9" W.Oak N.21°E. 7.2 ft., scribed T24S R5W S3 CS BT."
10" W.Oak N.28°W. 14.5 ft., scribed T24S R5W S4 CS BT."

45

Section Corner to Sections 7 & 18, T24S R5W, & Secs. 12 & 13, T24S R6W.
Found - Orig. 14", now 30" B.Oak N.41°W. 33.0 ft., previously opened & rescribed years ago, not on old face. I find parts of good scribing on old face.

Find Remains of old Oaks that check for Original N. E. & S. W. BT's.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{S\ 12}{S\ 13} \mid \frac{S\ 7}{S\ 18}$ T24S R6W R5W

New BT's: 10" R.Fir bears S.72°E. 51.4 ft. scribed S18 T24S R5W CS BT.
16" R.Fir bears N.68°E. 46.4 ft. scribed S 7 T24S R5W CS BT.
10" R.Fir bears N.30°W. 19.3 ft. scribed S12 T24S R6W CS BT.
8" R.Fir bears S.51°W. 3.5 ft. scribed S13 CS BT.

46

$\frac{1}{4}$ Corner to Section 7, T24S R5W, & Sec. 12, T24S R6W.
Found - Orig. 26", now 34" W. Oak S.27°E. 70.6 ft. I open & find parts of faint reverse scribing "B".

Find remains of large Oak Stump & Stump Hole that checks record for Orig. N. W. BT.
Corner also checks call to creek.

Note - N. S. Fence 2 ft. East.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{1}{4}$ S12/S 7 T24S R6W R5W.

New BT's: 18" W. Oak bears S.58°E. 7.5 ft. scribed $\frac{1}{4}$ S7 CS BT.
7" R.Fir bears N.41°W. 20.4 ft. scribed $\frac{1}{4}$ S12 CS BT.

*Fo. ok 8/92 DeLaw
M 115-49*

47

$\frac{1}{4}$ Section Corner to Sec. 1, T24S R5W. & Sec. 6 T24S R4W.
Found - B.Oak, now 30", S.12°W.(rec. S.11°W.) 158.4 ft. Chopped open & found good scribing "BT". Tree is still in good condition.

B. Oak, now 36", S.67°E.(rec. S.71°E) 95.0 ft. Shows scar, did not open. Tree still in good condition.

At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1960 T24S $\frac{1}{4}$ S1/S6 R5W R4W.

Fence Corner 5 Feet North.

Blazed & Scribed New Trees:

8" Fir S.32 $\frac{1}{2}$ °E. 9.9 ft. mkd. " $\frac{1}{4}$ S6 CS BT."
12" W.Oak S.26°W. 23.7 ft. mkd. " $\frac{1}{4}$ S1 CS BT."

*Fo. ok
S10 & DeLaw
M 96-18*

48

Section Corner to Sections 1, 2, 11, and 12.
Found - Orig. 9", now 20" W.Oak, shows good scar. I do not open.
N.25°E. 64.0 ft.

Orig. 10", now 20", down mostly rotted, B.Oak, N.68°W. 17.8 ft., good reverse scribing found "T 1".

Orig. 40", now 44" remains of Oak stump shell only left, #115

Orig. 24", now B. Oak snag, face & side rotted, no scribing found, S.67°E. 83.8 ft.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{S\ 2}{S\ 11} \mid \frac{S\ 1}{S\ 12}$ T24S R5W

New BT's: 8" W.Oak bears N.72°W. 4.9 ft. scribed S2 T24S R5W CS BT.
12" W.Oak bears S.39°E. 18.8 ft. scribed S12 T24S R5W CS BT.
8" W.Oak BEARS S.18°W. 43.7 ft. scribed T24S R5W S11 CS BT.
Orig. 10", now 20" W.Oak bears N.26°E. 63.5 ft. I do not rescribe, B.T. is O.K.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
February 1960
C. S. File No. 49/124

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
March 1960
C. S. File No. 49/124

RE-RENEWED, SEE CORNER NO. #115