

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

60

$\frac{1}{4}$ Section Corner to Sections 28 and 29.
Found - Orig. 16", now 36" W.Oak N.54°E. 35.4 ft. I open & find
good scribing "T".
Orig. N.E. BT. down & mostly rotted.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 $\frac{1}{4}$ S29/S28 T24S R5W.
New BT's: 16" W.Oak bears S.13°E. 16.6 ft. scribed $\frac{1}{4}$ S28 CS BT.
8" W.Oak bears S.66°W. 58.1 ft. scribed $\frac{1}{4}$ S29 CS BT.

James M. Byron, Deputy
Hilo Godfrey
Clete Putnam
March 8, 1960
C. S. File No. 49/124

RE-RENEWED CORNER NO #110
Section Corner to Secs. 33 & 34, T24S R5W & Secs. 3 & 4, T25S R5W.
Found - 1" I.P. at Corner & now 28" Fir N.72½°E. 33.8 ft.,
shows good scars. **REN. #34**

No Brass Cap Set
New BT's: 10" Laurel bears N.28°W. 124.0 ft. scribed T24SR5W S33 CS BT.
18" Fir bears S.22½°E. 58.0 ft. scribed T25S R5W S3 CS BT
Note - 4 way Fence Corner is 12' North.

RE-RENEWED CORNER NO #90
 $\frac{1}{4}$ Cor. Sec. 33, T24S R5W and Sec. 4, T25S R5W.
Found - Rock with + on top and 24" W.Oak N.68°W. 96.2 ft., shows
good scars, I do not open. **SEE REN No. 18-A**
40" W.Oak S.27°W. 20.6 ft., shows real old scar & newer
scars. I believe this is Orig. B.T. I do not set
Brass Cap.

63

$\frac{1}{4}$ Section Corner to Sections 28 and 33.
Found - Orig. 12", now 24" Oak Stump S.24°E. 45.5 ft. I open &
find good scribing "BT".
Orig. 16", now 24" W.Oak Snag, shows Orig. scribing "BT",
bears N.3½°E. 27.7 ft. This tree has been rescribed,
probably by Theil.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960 $\frac{1}{4}$ S28 T24S R5W
S33
New BT's: 6" W.Oak bears N.53°E. 23.3 ft. scribed $\frac{1}{4}$ S28 CS BT.
7" W.Oak bears S.30°E. 24.2 ft. scribed $\frac{1}{4}$ S33 CS BT.
Note - N. S. Fence is 2' East.

64

$\frac{1}{4}$ Section Corner to Sections 23 and 26.
Found - W.Oak, nearly dead, now 25", N. 7°W. 59.4 ft. This tree
has been opened previously, good scribe, "S".
Oak, dead & down, S.48°W. 108.9 ft. Did not open.
Corner falls in E. & W. fence line.
Set Brass Cap Mkd: County Surveyor's Office, T24S R5W $\frac{1}{4}$ S23
1960 S26
Blaze & Scribe New BT's: 8" W.O. S.75°W. 11.0 ft. Mkd: $\frac{1}{4}$ S26 CS BT.
10" W.O. N.59°E. 8.7 ft. Mkd: $\frac{1}{4}$ S23 CS BT.

65

Section Corner to Sections 22, 23, 26, and 27.
Found - Orig. 20", now 26" B.Oak N.44°E. 77.2 ft., previously
opened, shows good scribing "23S".
Orig. S.E. BT., now stump, not opened.
No trace of Orig. N.W. or S.W. BT. found.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960 $\frac{1}{4}$ S22 | S23 T24S R5W
S27 | S26
New BT's: 11" W.Oak bears S.27°W. 12.1 ft. scribed S27 T24S R5W CS BT.
11" W.Oak bears S.80°E. 26.3 ft. scribed S26 T24S R5W CS BT.
8" W.Oak bears N.70½°W. 18.7 ft. scribed S22 T24S R5WCS BT.
7" B.Oak bears N.25°E. 18.3 ft. scribed S23 T24S R5W CS BT.

66

$\frac{1}{4}$ Section Corner to Sections 11 and 14.
Found - Orig. 14" W.Oak S.24°W. 58.1 ft., now down, & rotted. I find
parts of old face showing good scribe, "1/5"
No trace of Orig. N.W. BT. found.
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ T24S R5W S11 County Surveyor's
S14 Office, 1960
New BT's: 26" B.Oak bears N.77°W. 53.4 ft. scribed $\frac{1}{4}$ S11 CS BT.
24" R.Fir bears S.17°W. 22.0 ft. scribed $\frac{1}{4}$ S14 CS BT.