

Douglas County Surveyor's Record of  
Government Corners Renewed

T 24 T. S. 5W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21851

Section corner for Sec. 6; and Sec 31, T23-5; Sec. 1, T24-6;  
Sec. 36, T23-6:

Found - USGLO Brass cap properly marked and dated 1943.  
From which:

- A 50" Fir stump with good scar bears N. 58° E., 43.0 ft.
- A 38" (rec. N. 57 1/2° E., 39.6 ft.)
- A 38" Fir stump blazed, scribe rotted. Bears S. 59° E., 83.8 ft. (rec. S. 62 1/2° E., 83.8 ft.)
- A 36" Fir stump blazed-some scribing visible, blazed area mainly rotted. Bears S. 18° W., 119.8 ft. (rec. S. 18 1/2° W., 116.8 ft.)
- A 48" Fir blown down blazed, bears N. 84 1/2° W., - ft. (rec. N. 83 1/2° W., 184.8) (DISTANCE INDETERMINATE)

New BT's

- A 9" Fir bears N. 66° W., 30.3 ft. scribed T23S R6W S36 CS BT
- A 30" Fir bears N. 85° E., 30.7 ft. scribed T 23S R5W S31 SCS BT
- A 16" Fir bears S. 7 1/2° E., 66.2 ft scribed T24S R5W S6 CS BT  
Dist 67.50 @ -13° =
- A 10" Fir bears S. 57° W., 27.1 ft. scribed T24S R6W S1 CS BT  
Corner lies in wooded area (Madrone & Fir) is located at intersection of fences running south-erly, easterly and westerly.

4/22/75

88

L.E. Monrean  
A.V. Cangie  
4/22/74  
C.S. 57/21

WPA T240 C.V. 22/720  
EOL. Mappo & DeGennis  
GALVESTON, TEXAS

FA OK  
7/93 MM-52

1/4 Corner for Secs. 11 and 12.

Set - 3/4" I. Pipe

Established bearing trees:

- 10" Oak, N. 65° W., 45.1 ft. scribed "1/4 S11 BT"
- 14" Oak, N. 44° E., 15.4 ft. scribed "1/4 S12 BT"

5/75

89

Romanso E. Ware  
For: Jesse C. Coon  
May 1975  
M 57 - 17

1/4 Corner Betw. Sec. 33, T 24 S, R5W, and Sec. 4, T25 S, R5W

Found: A stone 5"x12"x24", firmly set, with a "+" chiseled on top

From which- An orig. 12" now 36" W Oak bears S31 1/2° W., 19.8 ft.

Alive and well healed.

see Ren. #62-18A

We rescribe "1/4 S 4 CS BT" on a double blaze.

At the corner opint, we set a 1"x30" I. pipe with brass cap attached mkd.

DOUGLAS CO. SURVEYOR  
1975

T 24 S

1/4 S33 R  
S 4 5

T 25 S W

We place the stone alongside the brass cap. There are no other trees near.

This corner lies in an old E-W fenceline. Compass Declination: 20° East.

91

East 1/16 Section Corner between S 32 T24-5 & sec. 5 T25-5:

Corner Location Determined by single proportionate measurement.

At the corner point, we set a 1"x24" I. Pipe with brass cap attached: mkd:

DOUGLAS CO. SURVEYOR  
1975

T 24 S

E 1/16 S 32 5

T 25 S W

and mark the following bearing tree:

- A 12" W. Oak bears S 67 1/2° E., 32.2 ft. Scribed: "E 1/16 S5 CS BT" on a double blaze.

Note" This corner is located approx. 14 ft. north of a fence corner.

Compass Declination: 20° East.

Gary L Langlitz  
Clell E Goodwin  
A Vic. Cangie  
M. Lenora Ladig  
7-31-75  
C.S. 57/34

FOOK  
By David Collier  
5/94 For: Rhyne  
M 120-9