

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Exterior L Corner for DLC #39
Found - DLC cor. stone dug out and moved. Ren. #5
Set - 5/8" I. P. at projected fence cor. for DLC cor. per instructions
from D. R. Mask, Oakland, OR.

3/77
W. S. Barnes
For: Keith
Pedersen
Sept. 1976
M 61 - 58

1/4 Corner for Secs. 21 and 28 Ren. #18
Set - 2" Brass cap and marked T24S R5W 1/4 S21 S28 R.E. 2128, in east
ditch of road. FD OK 12/93 BY R. DOLAN
1994-0009

97

From which:
A 18" Oak (the N.E. fork of a double oak), bears S.31°E., 46.0 ft.
scribed 1/4, S28, T24S, R5W, B.T.
A 1 1/2" x 30" steel axle bears N.41°E., 40.0 ft. (Set in N-S
fence line).

9/77

98

Section Corner for Secs. 21, 22, 28 and 27.
Set - 2" Brass cap set and marked T24S R5W S21, S22, S28, S27, R.E. 2128,

From which:
A 6" Oak bears N.23°W., 56.2 ft. scribed S21, T24S R5W B.T.
A 6" Oak bears S.61°E., 98.2 ft. scribed S27, T24S R5W B.T.

9/77

99

1/4 Corner for Secs 22 and 27.
Set - 2" Brass cap marked: T24S R5W 1/4 S22 S27 R.E. 2128 #113

From which:
A 8" Oak bears N.76°W., 15.0 ft. scribed 1/4 S22, T24S, R5W, B.T.
A 18" Oak bears S.72°E., 36.4 ft. scribed 1/4 S27 T24S, R5W, B.T.

9/77

100

Section Corner for Secs. 16, 15, 21 and 22.
Set - 2" Brass cap marked: T24S R5W S16 S15 S21 S22 R.E. 2128.

From which:
A 1 1/2" I.P. South 24,8 ft. (set in E-W. fence line)
A 10" Ash bears S.38 1/2°W., 301.0 ft. scribed T24S R5W S21 BT.

9/77

101

1/4 Corner for Secs. 20 and 21.
Set - 2" brass cap marked T24S R5W 1/4 20 21 R.E. 2128, in north R/W fence
line of county road.

From which:
An 8" Oak bears S.67°E., 200.6 ft. scribed S21, T24S, R5W B.T.

9/77

102

Sec. Corner for Secs. 20, 21, 29 and 28.
Set - 2" brass cap marked: T24S R5W S20 S21 S29 S28 R.E. 2128

From which:
A 5" Oak bears N.2°W., 32.0 ft. scribed T24S R5W S20 B.T.
A 11" Oak bears N.51°E., 39.2 ft. scribed T24S R5W S21 B.T.

9/77

103

Section Corner for SEcs. 10, 11, 15 and 14.
Found - A 1" x 36" I.P. set 22" in ground bent over with a 1960
County brass cap. properly marked. Ren. #49

- A 20" now 60" Black Oak, (Rec. Y. Oak) bears S.44°E. (Rec. S.47°E)
63.4 ft. with well healed scars.
- A 20" now 36" Oak is down (on blaze area) approx. bears S.74°W.
124.7 ft.
- A 24" now 32" burned out Oak snag bears N.51 1/2°E., (Rec. N.50°E)
232.3 ft. with reverse scribing "4" in a healed blaze.
- A 18" now 24" D. Fir (R.Fir) bears S.29°E., 18.9 ft. with a well
healed double blaze.
- A 12" now 13" Madrone (laurel) measured below the fork, bears
S.17°W., 19.7 ft. with a well healed double blaze.
- A 6" now 11" D. Fir (R.Fir) bears N.45°W., 22.9 ft. with a well
healed double blaze.
- A 17" now 23" D. Fir (R.Fir) bears N.79°E., 39.9 ft. with a well
healed double blaze.

Set - I straighten the bent iron pipe and reset in original location,
stamp "Reset 1978" above existing date "1960". brass cap is
3" above ground.

R. B. Kimberling
P. L. Earle
Doug. Co. Surveyors Office
March 13, 1978
C.S. 59/46

FD. 4-92 BY BENTZ
P.A. 1992-0031

1-77 Note: Corner is on North edge of a jeep trail, 20.0 ft. North of an east-west fence.