

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 24

T. S.

R 5

R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97001

112

Douglas County
Surveyors Office
R. W. Smith
S. J. Flause
June 10, 1989
C. S. 62/63

Section Corner for Secs. 18 and 19; and 13 & 24 of T.24-6
 Found - A 2½" dia. brass cap, properly mkd., on a 1 3/8" O.D. iron pipe
 is firmly set with top bent 6" south of plumb position. Ren.#27
 Evidence of previous monuments not found.
 No evidence of original BTs is found.
 A 12" B. Oak now a 14" DBH B. Oak with a possible healed blaze
 (center of tree burned out) bears S.44°E., 42.9 ft. distant.
 (Rec. Ren.#8 of T.24-6 is S.41°E., 42.9 ft.)
 Evidence of roots and roothole are found bearing approx. S.41°W.,
 44.2 ft. distant. Ren. #27
 Due to land clearing and cat work in area, no evidence of other
 BTs is found. Old fences run south and west from corner positio
 Set - Described found corner monument is to be covered by unstable fill
 slope and will not be easily occupied in future, therefore WE
 ESTABLISH a reference monument,; a 2 3/8" dia. brass cap mkd.
 "Douglas County Surveyors T24S Ref. Point R6W S13 S24 R5W
 S18 S19 N.45°W 60 ft. 1989 Office"
 New BTs - (New accessories are tied to reference monument only)
 A 20" dBH W. Oak scribed "T24S R5W S18 CS BT" on a double blaze
 bears N.49°E., 52.1 ft. distant.
 A 20" DBH southeasterly trunk of a triple trunk W. Oak is scribed
 T24S R6W S24 CS BT on a double blaze. The center of the root
 crown of the triple trunk W. Oak bears S.74½°W., 12.1 ft. dist.
 A 21" DBH douglas fir scribed T24S R6W S13 CS BT on a double
 blaze bears N.66½°W., 144.6 ft. distant
 Monument lies on gradual SW slope on shoulder of ridge running from
 Northwest to southeast.

6/10/89

113

1/4 Corner for Sections 22 and 27
 Found - 2½" dia. brass cap on an 1½" O.D. iron pipe, protruding 12"
 above ground. Ren. No. 99
 8" now 9" dia. W. Oak with a partially healed double blaze,
 illegible scribing visible, bears N.72½°W., 15.0 ft. (Rec.
 N.76°W., 15.0 ft.) Ren. No. 99
 18" now 19" dia. W. Oak with a partially healed double blaze,
 scribing visible "S27 24 BT" bears S.68°E., 37.1 ft. (Rec.
 S.72°E., 36.4ft. dist. possible face measurement) Ren. No. 99
 New BTs - 8" dia. D. fir double blazed and scribed "1/4 S22 CS BT" bears
 N.80°E., 6.7 ft.
 9" dia. W. Oak double blazed and scribed "1/4 S22 CS BT" bears
 S.87°W., 24.3 ft.
 Corner lies near the intersection of an east-west and north running fence,
 lines approx. 250 ft. east of Pollock Creek.

2/28/91

114

1/4 Corner for Sections 10 and 15
 Found - A 2½" dia. 1960 DCSO brass cap on a 1½" O.D. iron pipe, protruding
 14" above ground. Ren. No. 43
 3/4" Bolt protruding 3" above ground, top is bent north, bolt
 is found along east edge of DCSO BC/IP. Ren. No. 16
 8" now 12" dia. W. Oak with a fully healed single blaze bears
 N.49½°W., 139.0 ft. (Rec. N.48½°W., 139.0 ft.)
 16" now 21" dia. W. Oak with a fully healed single blaze, bears
 S.45°W., 83.4 ft. Ren. No. 16
 New BTs - 5" dia. W. Oak double blazed and scribed "X BT" bears
 N.23½°E., 10.2 ft.
 14" dia. D. fir double blazed and scribed "1/4 S15 CS BT" bears
 S.46°E., 49.1 ft.
 Corner is approx. 150 ft. east of gas line near the intersection of an
 east-west and south running fence line.

3/1/91

115

Section Corner for Secs. 1, 2, 11 and 12.
 CONDITION REPORT ONLY
 Found - A 2½" dia. 1960 DCSO brass cap on a 1½" O.D. iron pipe protrudes
 14" above ground. Ren. No. 48
 9" now 23" dia. W. Oak with a fully healed blaze, bears
 N.26°E., 64.5 ft. Orig. BT.
 40" now 32" dia. 1 ft. high Oak stump with a rotted out center,
 bears S.42½°W., 27.1 ft. Orig. BT

C O N T N E X T P A G E

Douglas County Surveyors Office
 Randall Smith - Stephen Flause
 Terrie Franssen
 Feb-March 1991
 C.S. 64/13

FO. 4/92
 BY DEN/12
 PP. 1992-0031