Douglas County Surveyor's Record of Government Corners Renewed

24 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

51

Section Corner to Sections 14, 15, 22, & 23.
Found - Orig. 15", now 46" W.O. shows good scars., I do not open.
Orig. 20", now 36" W.O. N.45°W. 31.0 ft. I do not open.
Orig. 30", now 40" W. O. N.57°E. 20.5 ft. I open & find good scribe marks "BT". Epp. - ~~1946~~ 1926 - Ren. #14.
Renewal 30", now 40" W. Oak down, S.48°W. 13.9 ft.
Find 1" Drill Steel at Corner. I do not set Brass Cap.
New BT's: 14" W. Oak bears N.46°W. 10.6 ft. scribed S15 T24S R6W CS BT.
6" W. Oak bears S.65°W. 25.5 ft. scribed S22 T24S R6W CS BT.
14" R. Fir bears N. 5°E. 37.8 ft. scribed T24S R6W S14 CS BT.
8" W. Oak bears S.81°E. 37.3 ft. scribed T24S R6W S23 CS BT.

52

Section Corner to Sections 15, 16, 21, & 22.
Found - Orig. 11", now 48" Down Fir S.17°W. 87.1 ft. I open Log Section and find good scribing "1 S". see Notes Fd. O.K.
No trace of other BT'S. S16 | S15 1958 Dep. Re survey Vol. 42 P. 164B9
Set Brass Cap at Corner Mkd: T24S R6W S21 | S22 County Surveyor's office
New BT's; 8" W. Oak bears N.64½°E. 164.7 ft. scribed S15 T24S R6W CS BT.
26" Ash bears N.15 °W. 166.0 ft. scribed S16 T24S R6W CS BT.
6" W. Oak bears S.32°E. 45.1 ft. scribed S22 CS BT.
15" R. Fir bears S.65°W. 188.3 ft. scribed S21 T24S R6W CS BT.

53

¼ Section Corner to Sections 22 & 27.
Found - Old Cedar Stake (4"x 4") set by Cole, 1915, with scribing, "CS ¼S" plainly visible. Ren. #5
Remains of Orig. BT. S.18½°W. 37.6 ft. Axe marks & part of old face visible. No scribing visible.
Oak, uprooted & down, with face chopped open. Center portion entirely rotted away. The stump hole for this tree is N.87°W. 28.4 ft. from corner.
Black Oak, now 20" diam., S.32¾°E. 38.9 ft. This tree has been chopped open & center portion is entirely rotted away.
Fir, now 42" diam., S.42½°W. 50.8 ft. This tree has been chopped open & the face badly charred, but faint traces of scribing are visible - No letters or numbers legible.
At Corner Set Iron Pipe with Brass Cap Mkd: " County Surveyor's Office, 1958, T24S R6W ¼ S22 / S27
Blaze & Scribe following Trees:
20" Doug. Fir S.41°W. 12.0 ft. Mkd. ¼ S27 CS BT.
14" Incense Cedar N. 5°E. 15.4 ft. Mkd. ¼ S22 CS BT.
Corner is in East & West Fence Line.

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
Sept. 2, 1958
C. S. File No. 49/83

54

¼ Section Corner to Sections 17 & 20.
Found - Rock at Corner, 6"x 8"x 5"
Cedar Snag, now 30", S.20°E. 21.1 ft., chopped open & found scribe "S".
Cedar Stump, now 18", N.30°W. 18.8 ft. Had been opened previously, marks burned off.
New BT's: 11" Cedar N. 37°W. 50.3 ft. Mkd: "¼ S17 CS BT."
14" Cedar N.48°E. 104.0 ft. Mkd: "¼ S17 CS BT."
Set Brass Cap at Corner alongside Corner Stone Mkd.:
County Surveyor's Office, 1959 ¼ S17 / S20 T24S R6W

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
March 26, 1959
C. S. File No. 49/83

55

¼ Section Corner to Sections 19 & 20.
Found - Both Orig. BT's: Orig. 19", now 30" Cedar S.53°E. 52.1 ft., shows good scribing "¼S".
Orig. 34" Fir, now 44" Stump. I open & find good scribing "S".
Note - ¼ Corner is 10' South of Center Log. Road.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959, ¼ S19/S20 T24S R6W.
New BT's: 48" R.Fir bears N.71½°E. 44.7 ft. scribed ¼ S20 CS BT.
Note - Top of Top Blaze 7½' above ground.
4/7/75 - FIR LEANING - MARLAN WAINES, LAND OWNER WILL CUT ABOVE SCRIBE.