

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner for Sections 2 and 3, and 34 & 35 T23-6. 103  
 Found - 1943 GLO Brass cap at Sec. corner.  
 28" D. Fir, now stump, N.48°W., 18.1 ft. opened for scribe S34.  
 This is orig. tree possibly moved  
 42" D. Fir, stump (out of place) S.32°E., Shows good scar.  
 New BT's - 14" W. Fir, S.73°E., 100.5 ft. Scribed T24S R6W S2 CS BT.  
 8" W. Fir, N.57°E., 24.0 ft. Scribed T23S R6W S35.  
 18" Cedar, N.22°W., 26.8 ft. Scribed T23S R6W S34 CS BT.  
 12" W. Fir, S.81°W., 84.6 ft. Scribed T24S R6W S3 CS BT.  
 Note - Brass cap was set almost flush with surface of ground. Logging  
 has really moved things around. Call of 1.22 chains to the  
 west hits good. Also is good on N-S & E-W blazed lines.  
3/15/73

John M. Powell  
 J. Heritage  
 G. Commons  
 C.S. File 56/25  
 March 15, 1973

Section Corner to Sections 1 - 2 - 11 - 12. 104  
 Set by Proportionate Measurement.  
 Set-Brass Cap mkd: \$142, \$11, 122 T24S R6W  
 RPLS 544 1973  
 8" W. Oak bears S.82°E. 26.1 ft. scribed S12 T24S R6W BT. #108  
 7" W. Oak bears N.32°E. 25.1 ft. scribed S1 T24S R6W BT.  
 6" W. Oak bears N.34°W. 22.7 ft. scribed S2 T24S R6W BT.  
 6" W. Oak bears S.21°W. 19.8 ft. scribed S11 T24S R6W BT.  
Sept. 1973

Don E. Garrett  
 For: Bill Rees  
 Sept. 1973 Map File M 49 - 38

1/4 Corner to Sections 11 and 12. 105  
 FD. OK 8/92 BY DOLAN  
 M 115-49  
 Set-Brass Cap mkd: 1/4 S11, S12 T24S R6W  
 RPLS 544 1973  
 13" Fir bears N.41°30'E. 62.3 ft. scribed 1/4 S12 BT.  
 8" Fir bears N.74°W. 79.3 ft. scribed 1/4 S11 BT.  
Sept. 1973

1/4 Corner to Section 1 and Section 12. 106  
 FD OK 7/94  
 BY Bentz, M 120-42  
 Set by Proportionate Measurement.  
 Set-Brass Cap mkd: 1/4 S1 S12, T24SR6W RPLS 544, 1973  
 6" W. Oak bears N.17°E. 18.4 ft. scribed 1/4 S1 BT.  
 5" Fir bears S.17-1/2°W. 18.7 ft. scribed 1/4 S12 BT.

West 1/4 Cor. Sec. 30 only. 107  
 Found - 1"x1" T-iron with Haines Copper washer attached and  
 brass cap alongside mkd: Ren. #67  
 COUNTY SURVEYORS S25 West S30  
 OFFICE R7W R6W  
 1959 T 24 S

Gary Langlitz, County Surveyors Office  
 Peter Earle  
 Gary Commons  
 C.S. 57/2  
 July 25, 1974

from which:  
 orig. 14" now 40" D. Fir stump bears N.66°W., 11.9 ft. no  
 scribing visible.  
 Orig. 12" now 30" D. Fir, down, bears S.13°E., 40.3 ft. no  
 marks visible  
 A 32" Madrone marked in 1959 by the Co. Surveyor bears  
 S.50°E., 43.2 ft. scribing visible on partially healed  
 blaze.  
 A 5" now 10" Cedar mkd. in 1959 by the Co. Surveyor bears  
 S.16°E., 71.2 ft. well healed.  
 A 17" Madrone, now a stump mkd. in 1962 by BLM Cadastral  
 Survey crews bears N.85°E., 96.4 ft. scribing "1/4 S30  
 BT visible on unhealed blaze.  
 A 6" now 8" D. Fir now down mkd. in 1962 by BLM bears S.64°E.  
 84.8 ft. scribing "1/4 S30 BT" visible on unhealed blaze.  
 At this time the markings "USBLM" noted in the official  
 Government survey notes do not appear on the Co. Surveyors  
 brass cap.  
 We do not mark any new bearing trees.  
 This corner lies 20 ft. SE of a dirt road.  
7/25/74

JAN 75