

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

FD OK By Charles Guile
 $\frac{1}{4}$ Section Corner to Sections 2 & 1. *7/80 M79-52* **35**
 Found - Both Original BT's.:
 Fir Snag, now 29" diam. S.25°E. 13.2 ft.
 Fir Tree, alive, now 45" diam. S.10°W. 9.9 ft.
 Chopped in and found "B.T." scribed on both trees.
 Bark blaze & rescribe in Bark " $\frac{1}{4}$ S2 CS" on 45" Fir S.10°W.9.9".
 Bark Scribe " $\frac{1}{4}$ S1 CS" & Blaze & Scribe in wood "BT" on
 44" Doug. Fir which bears N.80°E. 22.3 ft.
 At Corner Set Iron Pipe with Brass Cap stamped "County Surveyor's Office,
 1958, T24S R7W $\frac{1}{4}$ S2/S1".

James W. Byron, Deputy Surveyor
 M. Godfrey
 S. Blouw
 April 17, 1958
 C. S. File No. 49/41

Section Corner common to Sections 19, 20, 29, 30. *REN. #8* **36**
 Found - Both BT's. as recorded by Eppstein, 1926. Also his axle at
 corner. Distances to BT's. check record but I find bearing
 to N. W. BT. should be N.44°W., record N.46°W. This BT.
 now 22" Stump, good scribing visible.
 The N. E. BT. should be S.86°E., record N.89°E. This BT. alive. **115**
 I open lower section & find good scribing "BT".
 New BT's: 23" double W.Oak N.86°E. 68.0 ft. scribed S20 T24S R7W CS BT.
 15" R.Fir bears N.29°W. 100.3 ft. -S19 T24S R7W CS BT.
 30" R.Fir " S.86°E. 28.4 ft. - S29 T24S R7W CS BT.
 No Trees near in S. W.

April 30, 1958

FD OK by LES ROBERTS 11-20-81 M 90-12
 $\frac{1}{4}$ Section Corner to Sections 19 & 20. **37**
 Found - Orig. 50", now 58" Fir Stump N.88°E. 33.0 ft. Open lower
 Scar & find good scribing "T". *REN. #10*
 16" Myrtle Stub that checks bearing & distance for Orig. S.W. BT.
 Set Brass Cap at Corner Mkd.: $\frac{1}{4}$ S19/S20 T24S R7W., County Surveyor's
 Office, 1958.
 New BT's: 14" Cedar bears S.27 $\frac{1}{2}$ °E. 77.2 ft. scribed $\frac{1}{4}$ S20 CS BT.
 14" R.Fir bears N.62° W. 68,0 ft. scribed $\frac{1}{4}$ S19 CS BT.
 Note: Cedar BT. scribed high, top scribed 8' above ground.

James W. Byron
 M. Godfrey
 S. Blouw
 May 14, 1958
 C.S. File #49/88

$\frac{1}{4}$ Section Corner to Sections 24 & 25. **38**
 Found - Orig. 30", now 38" Cedar S.47°W. 48.8 ft., Open face, good
 scribing visible " $\frac{1}{4}$ S"
 Orig. N. E. BT. gone, old cat road here.
 Set Brass Cap at Corner Mkd.: $\frac{1}{4}$ S24 T24S R7W County Surveyor's
 S25 Office, 1958.
 New BT's: 10" R.Fir bears N.35°W. 15.5 ft. scribed $\frac{1}{4}$ S24 CS BT.
 The Original S. W. BT. O. K.

James W. Byron, Deputy Surveyor
 M. Godfrey
 S. Blouw
 June 3, 1958
 C. S. File No. 49/41

$\frac{1}{4}$ Section Corner to Sections 23 & 24. **39**
 Found - Both Orig. BT's. & Stone at Corner as recorded.
 Orig. 40", now 44" Stump N.49°E. 32.3 ft., I open old
 scar & find good scribing "BT".
 Orig. 6", now 16" Fir N.19°W. 25.7 ft., alive, shows old
 scar, I do not open.
 Set Brass Cap alongside Corner Stone Mkd: $\frac{1}{4}$ S23/S24 T24S R7W
 County Surveyor's Office, 1958.
 New BT: 9" Cedar bears S.86°E. 10.2 ft. scribed $\frac{1}{4}$ S24 CS BT.

FD OK 10/AS Bentley M123-6 FD OK M121-64 APRIL 1994 DOLAN

Renew Corner to Section 13 & 14 & 23. **40**
 Found - Orig. 15", now 36" Fir Stump S.48°W. 23.8 ft. Parts of
 old scribing visible "S 1" on exposed face.
 Old & partly rotted Fir Snag checks bearing & distance
 for original S. E. BT.
 I find Closing Corner T24S R7W
 $\frac{23}{24}$ ← FOUND CORNER - SEE REN # 95
 Find stone marked as recorded at Corner. Also 1" Steel Shaft
 alongside Stone, & all BT's. as recorded, except S.E. BT.
 which is now snag only. The S.W. & N.E. BT's. show good
 scribing. I do not renew this corner.
 Note:- Distance between corners checks record 83.2 ft. Also good
 for bearing. S14/S13 T24S R7W County Surveyor's
 Set Brass Cap at Corner Mkd: S23 Office, 1958

(CONT'D. NEXT PAGE)