

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97195

*Frd. OK  
By LES ROBERTS  
11-20-81  
M 90-12*

Stump Hole that would check bearing. We make distance 13.5 ft,  
record 16.5 ft., for Orig. 12" Cedar S.70°E. 16.5 ft.  
Set Brass Cap at Corner Mkd: R8W  $\frac{S24}{S25}$  |  $\frac{S19}{S30}$  R7W T24S County Surveyor's  
Office, 1958  
New BT's: 10" Cedar bears S.10 $\frac{1}{2}$ °W. 38.6 ft. scribed S25 T24S R8W CS BT.  
I chisel 4" + & B.O. 5' above ground on 10' high sandstone  
bluff which faces West., S.45°E. 7.8 ft.  
24" Maple bears N.17°E. 44.0 ft. scribed S19 T24S R7W CS BT.  
14" W.Fir bears N.82°W. 64.3 ft. scribed S24 T24S R8W CS BT.

*9-21-71-Fd. OK. JWB C.S. 54/55*

J. Byron  
M. Godfrey  
S. Bilow  
June, 1958  
C.S. File 49/41

Section Corner to Sections 26, 25, 35, & 36. 47

Found - Old scribed Stake at Corner & Three Orig. BT's:

*Fd. by LES ROBERTS  
5-10-82  
M 92-36*  
Orig. 14", now 22" Fir Stump shows good scar at top of cut.,  
N.54°E. 42.2 ft.  
Orig. 30", now 40" Fir Snag. I open & find good scribing "W"  
N.61 $\frac{1}{2}$ °W. 23.1 ft.  
Orig. 20", now 36" Fir shows good scar. I do not open.  
S.48 $\frac{1}{2}$ °W. 40.3 ft.

No trace of Original S. E. BT.

Set Brass Cap at Corner Mkd:  $\frac{S26}{S35}$  |  $\frac{S25}{S36}$  T24S R7W County Surveyor's  
Office, 1958

*destroyed by logging*  
New BT's: { 12" R. Fir bears S.88 $\frac{1}{2}$ °E. 16.5 ft. scribed S36 T24S R7W CS BT.  
18" W. Fir bears N.16°E. 32.9 ft. scribed S25 T24S R7W CS BT.  
6" Cedar bears N. 9 $\frac{1}{2}$ °W. 51.7 ft. scribed S26 CS BT.  
Orig. S. W. BT. now alive. I do not rescribe.

James W. Byron, Deputy  
M. Godfrey  
S. Bilow  
August 4, 1958  
C. S. File No. 49/41

$\frac{1}{4}$  Section Corner to Sections 25 & 26. 48

Found - Orig. 14", now 32" Fir previously opened, good scribing  
visible "S"., bears N.54 $\frac{1}{2}$ °E. 21.8 ft.

Orig. 10", now 24" Cedar S.89°W. 4.6 ft. Shows good scar.  
I do not open.

Set Brass Cap at Corner Mkd:  $\frac{1}{4}$  S26/S25 T24S R7W County Surveyor's  
Office, 1958

New BT's: 14" Double Cedar bears N.63°E. 14.8 ft. scribed  $\frac{1}{4}$  S25 CS BT.  
I rescribe Orig. S.89°W. 4.6 ft. 24" Cedar  $\frac{1}{4}$  S26 CS BT.

Section Corner to Sections 23, ~~25~~<sup>35</sup>, 25, & 26. 49

Found - Orig. 24", now 32" Cedar bears S.79°W. 64.0 ft. Open face,  
shows good scribing.

Orig. 24", now 40" Cedar bears S.62°E. 58.1 ft. Shows good  
scar. I do not open.

Orig. 30", now 32" W. Fir N.4°E. 32.3 ft. Shows good Scar.  
I do not open.

No trace of Orig. No W. BT. found.

Set Brass Cap at Corner Mkd:  $\frac{S23}{S26}$  |  $\frac{S24}{S25}$  T24S R7W County Surveyor's  
Office, 1958

New BT's: 8" R.Fir bears N.19°W. 4.2 ft. scribed S23 T24S R7W CS BT.  
The Orig. N.4°E. 32.3 ft., now 32" is O.K. I do not rescribe.  
14" R.Fir bears S.42°W. 9.7 ft. scribed S26 T24S R7W CS BT.  
The Orig. S.62°E. 58.1 ft., now 40", is O.K. I do not rescribe.

$\frac{1}{4}$  Section Corner to Sections 13 & 24. 50

Found -  $\frac{3}{4}$ " Iron Pipe at Corner & Both BT's. as recorded by Frear, 1932.  
36", now 42" Fir S.40°W. 6.6 ft. (measured to face), shows  
good bark scribing " $\frac{1}{4}$  S BT".

60", now 66" Fir Stump N.19°E. 47.6 ft., shows good  
bark scribing "BT".

Set Brass Cap alongside  $\frac{3}{4}$ " Iron Pipe & Mkd: County Surveyor's  
Office, 1959,  $\frac{1}{4}$  Cor.  $\frac{S13}{S24}$  T24S R7W

New BT: 14" R. Fir bears N.49 $\frac{1}{2}$ °E. 65.0 ft. scribed  $\frac{1}{4}$  S13 CS BT.

James W. Byron  
S. A. Bilow  
April 16, 1959  
C.S. File No.  
49/41

*Car. Report  
FO OK 9/5/86  
OSHO  
CS 43/9  
Also 1963  
Blm 11517*

*FD OK M121-64 APR. 1994 DOLAN  
FD OK M123-6 10/95 Bentz*