

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

51

$\frac{1}{4}$ Section Corner to Sections 18 & 19.

Found - Both Original BT's:

Orig. 10", now 14" R. Fir bears S.70°E. 2.6 ft., I open & find good scribing "S".

Orig. 12", now 16" R. Fir N.58°E. 8.6 ft., shows good scars. I do not open.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

$\frac{1}{4}$

S18	T24S R7W
S19	

New BT: 6" W. Fir bears S.45°W. 31.0 ft. scribed $\frac{1}{4}$ S19 CS BT.

Fnd. O.K. by LES ROBERTS 11-20-81 M 90-12

52

Closing Corner to Secs. 18 & 19, T24S R7W, & Sec. 13, T24S R8W.

Found - All three Orig. BT's:

Orig. 40", now 60" R. Fir N.64°W. 100.3 ft., shows good scar. I do not open.

Orig. 12", now 14" Cedar Snag, shows good scribing "S", S.56°E. 27.7 ft.

Orig. 36", now 40" Fir Snag, shows good scribing "BT", N.56°E. 60.1 ft.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

R8W S13

S18	T24S
S19	R7W

Note: I find Sandstone at Corner as recorded. Set Brass Cap alongside Corner Stone.

New BT's: 12" R. Fir bears N.22°E. 37.0 ft. scribed CC S18 T24S R7W CS BT.

13" R. Fir bears S.72°E. 28.5 ft. scribed CC S19 T24S R7W CS BT.

6" R. Fir bears S.79°W. 21.8 ft. scribed CC S13 T24S R8W CS BT.

Fnd. O.K. by LES ROBERTS 11-20-81 M 90-12

53

Section Corner to Sections 26, 27, 34, & 35.

Found - Orig. 36", now 48" Cedar S.85°W. 101.6 ft., center rotted, no scribing found, shows old blaze & axe marks.

Now 36" Partly rotted Fir Snag, checks record distance & bearing for Orig. N. E. BT., no scribing found.

Stump Hole that checks bearing & distance for Orig. N. W. BT., No trace of Original S. E. BT. found.

Find 10"x 14"x 6" Sandstone out of ground, but at corner marked with 2" + on top & C.S. on face.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S27	S26	T24S R7W
S34	S35	

 Reset corner stone alongside Brass Cap.

New BT's: 12" R. Fir bears N.15°W. 15.2 ft. scribed S27 T24S R7W CS BT.

14" R. Fir bears N.49°E. 40.6 ft. scribed S26 T24S R7W CS BT.

14" R. Fir bears S.59°W. 38.8 ft. scribed S34 T24S R7W CS BT.

8" Laurel bears S.74°E. 41.5 ft. scribed S35 T24S R7W CS BT.

REN.#1

54

Section Corner to Sections 27, 28, 33, & 34.

Found - Orig. 20", now 50" Fir S.70°E. 7.3 ft., I open & find good scribing "B".

Orig. 20", now 50" Fir N.80°W. 62.7 ft., partly opened, about 10 years ago.

Remains of Large Oak Stump that checks bearing & distance for Orig. S. W. BT.

No trace of Original N. E. BT. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959

S28	S27	T24S R7W
S33	S34	

New BT's: Rescribe Orig. S.70°E. 8.0 ft. 50" Fir scribed S34 T24S R7W CS BT.

8" W. Fir bears S.52°W. 32.9 ft. scribed S33 T24S R7W CS BT.

20" R. Fir bears N.78°W. 47.0 ft. scribed S28 T24S R7W CS BT.

No trees near to N. E.

55

$\frac{1}{2}$ Corner between Sections 27 & 34.

Set Corner at proportionate distance:

5/8" X 18" Square Head Bolt with "X" on head set 1 ft.

below surface in East shoulder of Road.

Scribed: 30" D. Fir S.56°E. 14.55 feet.

6" D. Fir N.61°E. 22.72 feet.

James W. Byron, Deputy
S. A. Billow
May 20, 1959
C. S. File No. 49/41

James W. Byron, Deputy County Surveyor
Milo Godfrey
C. Putnam
August 14, 1959
C. S. File No. 49/41

Clifford M. Bryden
April, 1960
M 18 - 5