

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$  Section Corner to Sections 20 and 21.

Found - Orig. 10", now 24" W. Oak S. 63° E. 90.4 ft., previously opened, shows good scribing "S".

No trace of Orig. S. W. BT. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{1}{4}$  S20/S21 T24S R7W

New BT's: Note - No trees near West of Line.

12" W. Oak bears N. 43° E. 26.2 ft. scribed  $\frac{1}{4}$  S21 CS BT.

12" W. Oak bears N. 84° E. 54.8 ft. scribed  $\frac{1}{4}$  S21 CS BT.

Section Corner to Sections 16, 17, 20 and 21.

Found - 1 $\frac{1}{2}$ " Axle at corner & 14", now 18" Fir N. 80 $\frac{1}{2}$ ° W. 23.5 ft.

This BT., now snag. REN. #13

8", now 12" W. Oak shows good scar. I do not open

N. E. & S. W. BT's. gone.

New BT. 26" W. Oak bears N. 5° E. 12.5 ft. scribed S16 T24S R7W CS BT.

125.8' corrected 4/17/76 by v.j.

$\frac{1}{4}$  Corner to Section 31, T24S R7W, & Sec. 6, T25S R7W.

Found - Orig. 18", now 26" B. Oak, center partly rotted, shows good scribing (reverse).

Orig. South BT. gone.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{1}{4}$  S31 T24S R7W  
S6 T25S

New BT's: 6" R. Fir bears S. 34° E. 9.4 ft. scribed  $\frac{1}{4}$  S6 CS BT.

5" R. Fir bears N. 70° E. 9.0 ft. scribed  $\frac{1}{4}$  S31 CS BT.

$\frac{1}{4}$  Section Corner to Sections 21 and 28.

Found - Both Orig. BT's. Both check record distance & bearing.

Each was opened years ago. Old faces rotted off. No

scribing found. I find 3" x 3" scribed stake (old) at corner, scribed  $\frac{1}{4}$  S.

Note - Corner under E. W. Fence.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

$\frac{1}{4}$  S21 T24S R7W  
S28

New BT's: 26" W. Oak bears N. 34° W. 73.3 ft. scribed  $\frac{1}{4}$  S21 CS BT.

11" W. Oak bears S. 14° E. 15.2 ft. scribed  $\frac{1}{4}$  S28 CS BT.

Closing Corner to Sections 7 and 18.

Found - Fir Stump, now 60", (Orig. 40", instead of 10") has

been opened & scribe visible, "24S 7W S7 & 18 CC",

Measured N. 17 $\frac{1}{2}$ ° E. 37 feet, slope dist. for Corner.

Fir Tree, now 40", N. 82° E. 23.1 ft., shows good scars.

Corner lies about 15' south of small creek.

No trace of S. E. BT. found.

At Corner Set Iron Pipe with Brass Cap Mkd: County Surveyor's

Office, 1960 T24S R8W CC S7 R7W  
S18

Blaze & Scribe New Tree: 14" Red Cedar S. 67° E. 31.4 ft.

Mkd: "T24S R7W CC S18 CS BT."

Corner to Sections 12 and 13 only.

Found - Fir Stump, now 38", N. 20° W. 10.9 ft. Stump has been

opened & plain scribing "BT" visible. Ring count shws

about 60 yrs. growth outside of old face. Old face

shows tree to have been about 24" when scribed.

Cedar, 21", bears N. 70° E. 5.3 ft. Has been opened & old

axe smoothed face visible inside at approx. 8". Scribing

probably destroyed when closing corner Secs. 7-8 was set

Position for S. E. & S. W. BT's. fall in logging road.

No trace found of either. Corner falls correct dist. South of CC.

At Corner Set Brass Cap Mkd: County Surveyor's

Office, 1960 S12 T24S R8W S13 R7W

New BT's: 16" R. Cedar S. 24° W. 84.3 ft. Mkd. T24S R8W S13 CS BT.

17" R. Cedar N. 47° W. 55.8 ft. Mkd. T24S R8W S12 CS BT.

FD. ok 1/12/82  
G. Quibell  
Devc. Co. Surveyor Office  
C. S. 61/30

James W. Byron, Deputy  
Milo Godfrey  
Clote Putnam  
March 25, 1960  
C.S. File No. 49/41

57

58

59

60

61

July 15, 1960