

Douglas County Surveyor's Record of  
Government Corners Renewed

T 24 S T. S. R7 W R. W. W. M.

KORE-GHAPMAN CO., EUGENE, ORE. 21881

Bert W. Udell  
H. E. Taylor - Wit.  
Sept. 3-4, 1948  
C.S. File No. 40/114

62  
1/4 Corner on N. Line of Section 4, T25S R7W.  
Found: "CS scribed on remains of 12" Fir. This tree is  
rotted & broken. **CORNER NO. 99**  
30" Fir at S. 67°E. is in good shape. Scars show plainly.  
Set; Stake at Corner and Marked new Trees:  
34" Fir N. 52°E. 30.5 feet from corner, Mkd: "CS BT"  
"CS 1/4"

63  
N. E. Corner Section 4, T25S R7W.  
All Trees standing and in good condition. Stake At Corner.  
Fir 14" S. 66°E. 19 lks.  
Cedar 18" S. 65°W. 19 lks.  
Fir 14" N. 43°W E. 22 lks. **CORNER NO. #120**  
*SEE M49-7 & 1958 ELO  
BRASS CAP NOTED  
1/27-29-26/27/28*

64  
Section Corner to Sections 20, 21, 28, and 29.  
Found - Buggy Axle, loose & at South Side of old logging road. (REN. #6)  
True corner is about center of log road.  
Orig. 30", now 44" Fir N. 22°E. 17.2 ft., shows faint scar. #186  
Frear's S. W. & S. E. BT's. show good scars. The N.W. BT. down.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
New BT's:  
S20 | S21 T24S R7W  
S29 | S28  
40" R. Fir bears N. 39°W. 101.0 ft. scribed (bark scribed) G. GRUBB  
S20 T24S R7W CS BT. FEB. 1982  
M 91-27  
Fnd. O.K. by

65  
Section Corner to Sections 17, 18, 19, and 20.  
Found - Orig. 24", now 44" Fir Snag N. 1°E. 23.8 ft., I open &  
find good scribing "T24S R7W S17".  
No trace of other BT's. found.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
S18 | S17 T24S R7W  
S19 | S20  
New BT's: 10" W. Fir bears S. 78 1/2°E. 22.7 ft. scribed S20 T24S R7W CS BT.  
14" R. Fir bears N. 44°E. 68.8 ft. scribed S17 T24S R7W CS BT.  
9" W. Fir bears N. 5°W. 64.3 ft. scribed S18 T24S R7W CS BT.  
10" W. Fir bears S. 60 1/2°W. 64.9 ft. scribed S19 T24S R7W CS BT.

66  
1/4 Section Corner to Sections 28 and 29.  
Found - 1/2" I. P. at corner & both BT's. as recorded by Epp., 1928: (REN. #5)  
18", now 28" Fir Stump N. 17°W. 19.0 ft., fd. good scribing.  
S. E. BT. now down.  
Set - Brass Cap alongside corner Pipe mkd: 1/4 S29/S28 T24S R7W  
County Surveyor's Office, 1960  
Note - Corner under 60" Fir Tree (Down).  
New BT's: 20" R. Fir bears N. 57 1/2°W. 110.0 ft. scribed 1/4 S29 CS BT.  
20" R. Fir bears N. 58 1/2°E. 78.7 ft. scribed 1/4 S28 CS BT.

67  
Section Corner to Sections 28, 29, 32, and 33. #122  
Found - All three BT's., as recorded by Epp., 1928, except we find  
N.E. BT. should be N. 59°E. (record N. 62°E). BT's. show *REN. #4*  
good scars. I do not open.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1960  
S29 | S28 T24S R7W  
S32 | S33  
BT's. are all in good condition. No new BT's. scribed.  
Note - Pipe Set by Eppstein at Corner not found.

68  
M. C. Left Bank Sections 32 and 33.  
Found - Orig. 18", now 24" W. Oak Snag N. 2°W. 220.4 ft. We open &  
find good scribing "S32". Other Orig. BT's. not found.  
Note - M. C. in river bed. I set Wit. Cor. 220 ft. North of Corner.  
Set - Brass Cap at Wit. Cor. Mkd: County Surveyor's Office, 1960  
Wit. Cor. S32/S33 T24S R7W.  
New BT's: 16" W. Oak bears N. 76°E. 27.6 ft. scribed W.C. MC. S33 CS BT.  
14" R. Fir bears S. 72 1/2°W. 33.0 ft. scribed W.C. MC. S32 BS BT.

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
Sept. 1, 1960  
C. S. File No. 49/41