

Douglas County Surveyor's Record of  
Government Corners Renewed

24 T. S. 7 R. W. W. M.

KOKE-CHARMAN CO., EUGENE, ORE. 21891

81

$\frac{1}{4}$  Corner to Sections 13 and 14.  
Found - Orig. Corner Tree, now down, & Orig. N. E. BT.  
We open & find Good scribing "4". This BT.  
now down.  
Set - Brass Cap at Corner & in East West Fence Line Mkd:  
 $\frac{1}{4}$  S14/S13 T24S R7W County Surveyor's Office, 1961  
Note - This Brass Cap set in Concrete under East - West  
Fence, 1962.

New BT's: 5" R. Fir bears S.75°W. 61.7 ft. scribed  $\frac{1}{4}$  S14 CS BT.  
20" R. Fir bears N.60°E. 34.8 ft. scribed  $\frac{1}{4}$  S13 CS BT.

James W. Byron  
Clete Putnam  
July 12, 1961  
C. S. File No. 49/41

FD. OK 4/25/77 - E. MORGAN, OFFICE - C.S. 59/31

82

Closing Corner to Sections 3 and 2.  
Found - Hole for Evans Corner - Set 1" x 1" x 36" T. Iron - Ren. #17  
Original BT's: 24" Fir, now stump S.45°E. 9 lks.  
15" Fir, down, S.70°W. 4 lks.  
Evans BT's: 16" Fir S.60°E. 41.1 ft.  
24" Fir S.3°W. 56.0 ft.  
May 30, 1962

By Wilford  
N. Haines  
For Ray  
Cole  
M 23 - 64

FD T  
Iron - cracks  
Gauge 7-80  
4-79-52

83

$\frac{1}{4}$  Corner to Sections 32 and 33.  
Found - Fir, now 36", S.25°E. 29.7 ft., uprooted & down, had  
been opened previously, good scribing "S" visible on  
old face. This tree had been rescribed " $\frac{1}{4}$ SET" shortly  
before it fell.  
No trace of other Original Bearing Tree.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962  
T24S R7W  $\frac{1}{4}$  S32/S33  
New BT's: 11" D. Fir N.23°E. 42.3 ft. Mkd:  $\frac{1}{4}$  S33 CS BT.  
10" W. Fir S.38°W. 31.8 ft. Mkd:  $\frac{1}{4}$  S32 CS BT.  
A scribed stake Mkd: " $\frac{1}{4}$  S" bears S.47 $\frac{1}{2}$ °E. 17.5 feet.

Milo E. Godfrey, Deputy  
Vernon Tracy  
June 18, 1962  
C. S. File No. 49/41

84

Closing Corner for Section 32 and 33.  
Found - Double W. Fir, now 42", N.35 $\frac{1}{2}$ °W. 16.5 ft. This tree has been  
previously chopped open, scribing visible on old face,  
"24 S R CC".  
D. Fir, now 24", N.86°E. 12.5 ft., shows good scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962  
T24S R7W S32/S33 C.S.  
Rescribe - 24" D. Fir N.86°E. 12.5 ft. Mkd: T24S R7W CC S33 CS BT.  
New BT: 7" W. Fir N.64°W. 33.9 ft. Mkd: T24S R7W CC S32 CS BT.

85

Corner to Sections 5 and 4 only, T25-7W.  
This corner bears West of C.C. S32/S33 T24S R7W 52.1 ft. (record Dist.)  
Found - Fir, now 72", N.37°E. 74.6 ft., shows very faint old scar.  
Did not open.  
Fir Stump, now 56", S.48°E. 89.1 ft. Cut off too low to  
find scars or scribing.  
Rotted Remains of Fir Stump, in place S.60°W. 19.1 ft.  
Rotted Remains of Laurel Stump, in place, N.35°W. 41.6 ft.  
(These 2 stumps too far gone to find scars or scribing)  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962  
T25S R7W S5/S4  
New BT'S: 40" W. Fir S.12°E. 14.4 ft. Mkd: T25S R7W S4 CS BT.  
20" D. Fir S.17°W. 14.4 ft. Mkd: T25S R7W S5 CS BT.

86