

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 7 W. R.W.W.M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21861

109

Wm S. Barnes
For: D. Brownson
April, 1970
M 39 - 51

$\frac{1}{4}$ Corner to Sections 16 and 21.
Prorated Corner
Set - 5/8" Brass Rod for $\frac{1}{4}$ Corner
New BT: 20" D. Fir S. 52° W. 130.6 ft. mkd: "T24S R7W $\frac{1}{4}$ S16 B.T."

Larry D. Bishop
For:
Glanville
Map File
M 40 - 58

$\frac{1}{4}$ Corner to Sections 29 and 32.
Set - Brass Cap T 24 S R 7 W
 $\frac{1}{4}$ S 29
S 32
1970 896
Bearing Trees: 13" Fir S. 81° W. 50.4 ft. scribed " $\frac{1}{4}$ S32 BT."
16" Oak N. 63° 30' W. 110.3 ft. scribed " $\frac{1}{4}$ S29 BT". *Ren. #2*
RE-RENEWED, SEE CORNER NO. #147

111

$\frac{1}{4}$ Corner to Sections 31 and 32. *FD OK PER JOHNSTONE MAY-87 M104-16*
Set Brass Cap T 24 S R 7 W
 $\frac{1}{4}$ S 31 | S 32
1970 896
References: 5/8" I. Rod on the Easterly R/W Co. Rd. #33 N. 70° 31' 30" W.
5/8" I. R. on the Easterly R/W Co. Rd. #33 S. 50° 27' 50" W. 295.16 feet.
Nov. 1970

*FND. OK 11/90
M 111-1*

Fnd. Section Corner to Sections 15 - 16 - 21 - 22. *FD OK P. Shanor 6/96 M125-20 C.S. 65/2-12 AC*
6", now 11" D. Fir Corner Tree, See *Ren. #14*.
30", now 38" D. Fir, N. 43° E. 20.6 ft., bark scribe visible, faint "BT S15".
36", now 39" D. Fir, N. 50° W. 85.3 ft., bark scribe visible "S16 CS BT".
12", now 16" W. Oak, S. 57° W. 18.4 ft., shows good scar.
20" D. Fir, now stump, S. 55 $\frac{1}{2}$ ° E. 25.2 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 24 S R 7 W
(Set on S. side of Office S 16 | S 15
11" Corner Tree) 1970 S 21 | S 22
New BT: 14" D. Fir S. 45° E. 80.5 ft. scribed "T24S R7W S22 CS BT".
Reblzd. & Resbd: 38" D. Fir N. 43° E. 20.6 ft. scribed "T24S R7W S15 CSBT".
This corner lies on top of ridge about 10.0 ft. W. of meandering N-S Fence.
12/10/70

John M. Powell
W. Penley December 1970
C. S. File No. 49/41

$\frac{1}{4}$ Corner to Sections 19 and 30.
Found - Steel Axle at $\frac{1}{4}$ Corner, See *Ren. #9*.
10", now 14" Maple, S. 77° W. 4.3 ft., tree open, scribe visible, "4 S".
18" D. Fir, now down, N. 8° W. 40.3 ft., bark scribe visible " $\frac{1}{4}$ " etc.
DO NOT SET BRASS CAP.
New BT: 10" D. Fir N. 67° E. 78.0 ft. scribed " $\frac{1}{4}$ S19 CS BT".
This corner lies about 20.0 ft. east of draw, running southeast.
12/9/70

Section Corner to Sections 2 - 3 - 10 - 11. *REN SEE #165 FOR 1954 Ren. FD 1" steel shaft 84C Guile 7/80 M179-52*
Found - 1" Steel Shaft at Section Corner, See *Ren. #15*.
26", now 29" D. Fir, S. 55° E. 27.3 ft., scribe visible, "B".
22", now 26" D. Fir, S. 12° W. (Rec. S11° 45' E) 55.0 ft., scribe visible.
DO NOT SET BRASS CAP.
New BT's: 8" D. Fir N. 24° W. 40.8 ft. scribed "T24S R7W S 3 CS BT".
11" W. Fir N. 73° E. 35.4 ft. scribed "T24S R7W S2 CS BT".
Reblzd. & Resbd: 26" D. Fir S. 12° W. 55.0 ft. scribed "T24S R7W S10 CS BT".
This corner lies 8.0 ft. east of N.-S. fence line.
FD OK 4/96 L. Roberts M123-73
12/10/70

Section Corner to Sections 19 - 20 - 29 - 30. *115*
Found - Steel Axle at Section Corner, See *Ren. #36*.
23", now 25" W. Oak, N. 86° E. 68.0 ft., partial scribe marks visible,
(We do not open)
15" D. Fir, now down, N. 29° W. 100.3 ft.
30" D. Fir, now stump, S. 86° E. 28.4 ft., scribe visible "BT".
DO NOT SET BRASS CAP.
New BT's: 19" D. Fir N. 44° W. 91.0 ft. scribed "T24S R7W S19 CS BT".
15" D. Fir N. 15° E. 87.5 ft. scribed "T24S R7W S20 CS BT".
No other trees available.
12/9/70