

Douglas County Surveyor's Record of  
Government Corners Renewed

T 24 T. S. R 7 R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 97401

159

Section Corner for SEctins 1, 2, 11 and 12.

Found - 1958 County brass cap on a 1" I.P. mowed off with 7" of iron pipe attached to BC. Remaining I.P. protrudes 7" out of ground with top bent west. Bearing and distances of accessories taken to plumb position of bent iron pipe. 18" x 13" x 3" stone found laying flat on east edge of plumb position of bent iron pipe near surface. (source unknown) 18" now 54" dia. B. oak with fully healed blazes bears S.3°W., 47.7 ft. (orig. rec. S.5°W., 46.2 ft.) Orig. BT, rescribed in Ren. No. 34.

Orig. Southeast BT is gone, a depression in ground is found near bearing and distance.

24" now 62" dia. B. oak with a burnt out face, no scribing seen bears N.10°E., 196.6 ft. (Rec. N.10°E., 194.7 ft., possible face measurement). Orig. BT.

18" now 36" dia. Oak with a previously opened now burnt and rotted blaze, no scribing found, bears N.84°W., 145.5 ft. (Rec. N.84°W., 143.8 ft. possible face measurement.) Orig. BT.

14" now 19" dia. B. oak with a fully healed double blaze bears N.11°E., 6.5 ft. (agrees with rec.) Ren. No. 34

7" now 12" dia. W. oak with a fully healed double blaze bears S.55½°E., 31.8 ft. (agrees with rec.) Ren. No. 34

15" now 19" dia. W. oak with a fully healed double blaze bears N.81°W., 108.5 ft. (Rec. N.81°W., 109.0 ft.) Ren. No. 34

Set - A 2 3/8" brass cap on a 1½" outside dia. x 31" long I.P. is set flush with ground, marked "Douglas County Surveyors T24S S2 S1 S11 S12 R7W 1988"

1958 brass cap with 7" of I.P. set 5" below ground along south edge of new brass cap/iron pipe.

18"x13"x3" stone, undisturbed while setting new BC, lies along east edge of new brass cap/iron pipe.

Corner position is perpetuated at the plumb position of bent top iron pipe Ren. #34. This position is referenced and above monuments set. Corner lies on a westerly sloping hillside.

1/25/88

1/4 Corner for Sections 22 and 23

160

Found - A 3½" dia. 1973 BLM brass cap on a 2½" O.D. iron pipe protruding 6" above ground.

16" now 20" dia. D. fir with a fully healed single blaze bears N.86°E., 13.5 ft. (agrees with record) 1973 BLM

17" now 18" dia. 5 ft. high D. fir stump with a fully healed single blaze, bears N.24½°W., 38.9 ft. (agrees w/rec.) 1973 BLM

New BTs - 6" dia. madrone bark scribed "1/4 S23 CS BT" bears S.11½°E., 33.1 ft.

7" dia. D. fir double blazed and scribed "1/4 S22 CS BT" bears N.49½°W., 31.6 ft.

8" dia. D. fir double blazed and scribed "1/4 S22 CS BT" bears S.87½°W., 25.2 ft.

FOOK- Degroot - 5/96 - 1996-0051

6/4/90

WITNESS CORNER TO

Section Corner for Sections 31 and 32; and 5 and 6 of T.25-7  
CONDITION REPORT ONLY

161

Found - A 2½" dia. brass cap on a 1½" O.D. iron pipe is firmly set and protrudes approx. 10" from a rough low mound of stone. Ren. #107  
All accessories found as noted in Ren. #151 EXCEPT 11" Willow BT which is now dead.

Monument is at bottom of fill slope on west side of county Rd. #33 and is approx. 650 ft. North from the Tye Access Bridge (USFS Rd. #25-7-5.1)

7/30/90

1/4 Corner for sections 21 and 22.

162

Found - Root hole of original bearing tree, bears S.30°W., 12.5 ft.

Set - 5/8" X 30" I.R. with cap mkd. "ARTMAN RLS 2268"

B.T.s - 10" myrtle bears N.20°W., 22.9 ft. scribed "1/4 S21 BT"

15" d. fir bears N.26°E., 23.5 ft. scribed "1/4 S22 BT"

10" d. fir bears S.08°30'E., 56.3 ft. scribed "1/4 S22 BT"

40" maple bears S.60°W., 3.1 ft. scribed "1/4 S21 BT" to a 60d spike in side

FO OK- Degroot - 5/96 - 1996-0051

11/90

Douglas County Surveyors Office  
Randall Smith  
Stephen J. Flause  
Jan. 25, 1988  
C.S. 62/50

Douglas County Surveyors Office  
Randy Smith  
Steve Flause  
June 4, 1990  
C.S. 64/9

Douglas County Surveyors Office  
Stephen Flause  
Terrie Franssen  
July 30, 1990  
C.S. 64/10

James Artman  
L.S. 2268  
For: D. Ocumpaugh  
Nov. 1990  
M 111 - 1  
C.S. 63/101