

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 24                      T. S.                      R 7                      R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91891

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Terrie Franssen  
May 9, 1991  
C.S. 64/15

1/4 Corner for Section 29 and 32

CONDITION REPORT ONLY

163

Found - 5/8" dia. iron rod with plastic cap mkd. "Baughman Tech. Surv." protrudes 5" above ground. Ren. #147  
13" now 28" dia. D. fir with a fully healed single blaze, bears S.81°W., 50.4 ft. (agrees w/rec.) Ren. No. 110  
16" now 16" dia. Oak with a fully healed single blaze bears N.63½°W., 110.3 ft. (agrees w/rec.) Ren. No. 110  
No other BTs found.  
A 38" dia. D. fir with faint blaze was previously opened by Jim Artman, PLS #2268. We opened further, no blazes or scribing found inside tree, Tree bears S.83½°W., 178.8 ft. from 5/8" iron rod.

**RE-RENEWED SEE CORNER NO. #174**

5/9/91

NOTE: THIS CORNER NOW CONSIDERED ERRONEOUS PER BLM RESURVEY SEE VOL 51 PG. 19453

164

Tsp. Corner - NE Corner Section 1  
Found - 3½" dia. BLM brass cap on iron pipe is flush with ground. (1957 BLM - reset 1977) Ren. No. 132  
22" now 35" dia. Grand Fir with a fully healed single blaze, bears N.74½°W., 115.6 ft. (agrees with Ren. No. 132) 1957 BLM  
8" now 15" dia. D. Fir with a fully healed single blaze, bears N.63°E., 73.3 ft. (agrees w/rec) 1964 BLM  
15" now 22" dia. I. Cedar with a fully healed single blaze bears S.85°E., 107.6 ft. (agrees w/rec) 1964 BLM  
New BT - 8" dia. D. Fir double blazed and scribed "T24S R7W S1 CS BT" bears s.45°W., 19.3 ft.

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Feb. 7, 1992  
C.S. File 64/23

2/7/92

A.R. Evans  
For: L & H Lumber Co.  
Nov. 1954  
C.S. File 41/330

Corner secs. 2, 3, 10, & 11  
Found - Steel shaft and 3 BTs. Ren. #15  
48" Fir, N.23°E., 11 lks. (OBT)  
26" Fir, S.55°E., 27.1' (Dow)  
22" Fir, S.11 3/4°E., 55.0' (Dow)

**RE-RENEWED SEE CORNER NO. #114**

165

Mark Smalley  
Roseburg Forest  
Products  
10/94  
C.S. 63/154

1/4 Secs. 35 & 36

Found - 24" Cedar, S.47°E., 25.1', (1893 GLO), now 64" healed.  
20" Fir, S.76½°W., 22.4', (1893 GLO), now 44" healed.

166

Set - 5/8"x48" iron rod & alum. cap mkd: T24S R7W  
1/4  
35 | 36  
LS 2354  
1994

New BTs- 7" W. Fir, N.19°W., 4.1', scribed "1/4 S BT"  
11" Fir, N.80°E., 11.9', scribed "1/4 S BT"

1/4 Cor. Sec. 36 & Sec. 1, T25-7

Found - 1967 BLM Brass Cap & I.P.  
25" Cedar, N.59°W., 41.3', healed, now 30" (1967 BLM)  
22" Fir, S.84°E., 38.0', healed, now 24" (1967 BLM)  
New BTs- 7" Fir, N.64°E., 7.8', scribed "1/4 BT"  
8" Fir, S.38°W., 20.7', scribed "1/4 BT"

167

E 1/4 Corner Sec. 36 only

Found - 1967 BLM Brass Cap & I.P.  
32" Fir, N.69°W., 13.2', by 1967 BLM survey, now healed 42" fir.  
6" Fir, S.23°W., 41.6', by 1967 BLM survey, now healed 16" Pistol Butted Fir.  
New BTS- 7" Fir, S.3°E., 26.4', scribed "1/4 S BT"  
8" Fir, S.76°E., 18.9', scribed "1/4 S BT"

168

W 1/4 Corner Sec. 31 only T24-6

Found - 1967 BLM Brass Cap  
8" Fir, N1½°E., 143.2', now healed 12" Fir.  
6" Fir, S.50½°E., 14.5', now healed 14" Fir.  
New BTs- 6" Fir, N.26°E., 15.3', "1/4 S BT" - scribed.  
11" Fir, S.67°W., 15.3', "1/4 S BT" - scribed.

169