

Douglas County Surveyor's Record of
Government Corners Renewed

24 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

East $\frac{1}{4}$ Section Corner to Section 24. 17
 Found - Orig. 36", now 40" Fir Snag S.78°E. 93.1 ft., shows good bark
 scribe " $\frac{1}{2}$ "S".
 Orig. 18", now down & mostly rotted Fir, I find parts of
 scribe marks and parts of old axed face S.75°W. 60.7 ft.
 Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1960
 E $\frac{1}{4}$ S24 | T24S R8W
 Note - This corner renewed by Evans, 1956, and I find both of
 his BT's. The snag bears S.88°E., record S.78°E.
 This is not a common corner as renewed by Evans, 1956.
 From Brass Cap Evan's Corner bears S. 7°W. 14.0 ft.
 I destroy scribing on Evans BT's.
 New BT's - 24" R. Fir bears S.79°W. 46.8 ft. scribed $\frac{1}{4}$ S24 CS BT.
 14" W. Fir bears S.36°W. 9.5 ft. scribed $\frac{1}{4}$ S24 CS BT.

Fnd. OK
 by LES ROBERTS
 11-20-81
 M 90-12

C.S. File No. 49/41
 Sept. 1, 1960

East $\frac{1}{4}$ Corner to Section 12, T. 24 S. R. 8 W. 18
 Found - Orig. 30", now 45" Fir Stump N.80°E. 18.5 ft. I
 open & find good scribing "BT".
 Orig. 24", now 52" Fir Stump, shows good bark scribing,
 "BT" S.22°W. 11.9 ft.
 Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1959
 E $\frac{1}{4}$ S12 | T24S R8W/R7W
 New BT's: 8" W. Fir bears S.60 $\frac{1}{2}$ °W. 32.1 ft. scribed $\frac{1}{4}$ S12 CS BT.
 8" Cedar bears N.69°W. 36.3 ft. scribed $\frac{1}{4}$ S12 CS BT.
 BRASS CAP RESET JUNE 5, 1961

James W. Byron, Dep.
 For Martin Box Co.
 With: M. Godfrey
 C. Putnam
 Dec. 21, 1959
 C.S. File No. 52/6

Renew 19

	T23S		
R8W	S1 / S6	S6	R7W
	T24S		

 Found - Orig. 36", now 48" Fir N.38°W. 56.1 ft., old face
 destroyed by fire. 34
 Orig. 36", now 42" Fir S.57°E. 54.8 ft., old face
 destroyed by fire.
 Orig. 48", now 65" Fir S.10°W. (Record S.57°E) 79.2 ft.,
 now Stump shows rotted face.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

	C C		T23S
	S1 / S6	S6	T24S
	R8W		R7W

 New BT's: 4" R. Fir bears S.13°W. 15.4 ft. scribed S1 CS BT.
 Rescribe, now 42" R. Fir S.57°E. 54.8 ft. CC S6
 APRIL '65 - SEE RENEWAL #34 FOR NEW BT'S. T24S R7W CS BT.

RE-RENEWAL

James W. Byron
 Milo Godfrey
 Cleve Putnam
 Sept. 1960
 C.S. File No. 49/41

Section Corner to Sections 10 - 11 - 14 - 15. 20
 Found - Orig. 30", now 44" Fir S.60°E. 18.5 ft., shows good
 scars.
 Orig. 18", now 30" Fir N.48°E. 18.5 ft., shows good
 scars.
 Orig. N. W. BT., now stump hole, only.
 Orig. 24", now 44" Fir S.64°W. 44.2 ft. Standing but
 center burned.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

	S10 S11	T24S
	S15 S14	R8W

 New BT's: 9" R. Fir bears S.36°W. 19.4 ft. scribed S15 T24S R8W CS BT.
 6" R. Fir bears N.52°W. 9.0 ft. scribed S10 CS BT.

November 1960

Section Corner to Sections 13 - 14 - 23 - 24. 21
 Found - All Orig. BT's. All check for bear. & dist. & size
 and all show scars. Orig. N. W. BT. now stump only.
 Orig. S. W. BT. now down.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

	S14 S13	T24S
	S23 S24	R8W

 New BT's: 8" R. Fir bears S.74°W. 17.7 ft. scribed S23 T24S R8W CS BT.
 9" W. Fir bears N.42°W. 53.8 ft. scribed S14 T24S R8W CS BT.
 15" R. Fir bears S. 2°E. 39.0 ft. scribed S24 T24S R8W CS BT.
 13" R. Fir bears N.33°E. 42.0 ft. scribed S13 T24S R8W CS BT.