

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 8 W. R. W. W. M.

North $\frac{1}{4}$ Corner to Section 4 only, T24-8W. 39
 Found - 1894 Rock with " $\frac{1}{4}$ " on N. side.
 1894 BT., now a windfall lying eastward with face up,
 N. 87° W. 30.4 ft., not chopped out.
 1894 BT., S. 34° E. 11.2 ft., now 14" Dead Snag, Face open,
 scribes, "X" chopped in bark.
 6" Alder BT. dying, with Weyer. Alum. Tag, S. $38^{\circ}22'$ E. 35.62 ft.
 Set - $\frac{5}{8}$ " Rod, 4.0 ft. tall adjacent to Rock & Mkd:
 4 ft. diam., dead Fir, S. $89^{\circ}35'$ E. 4.6 ft., old "X" chopped
 bark, placed Weyer. Metal Tag.

$\frac{1}{4}$ Corner to Sections 4 and 9. (South $\frac{1}{4}$ Corner Section 4) 40
 Found - 17" Fir Snag BT., old scar chopped out by me, no scribes,
 old "X" chopped into bark, N. 81° E. 17.6 ft.
 20" Dead Snag, chopped out by me, no scribes, fd. yellow
 metal tag & marks chopped in bark, N. $61\frac{1}{2}^{\circ}$ E. 21.1 ft.
 Original Stone with " $\frac{1}{4}$ ".
 Reference Tree with BLM Metal Tag & marks chopped in bark
 on top ridge.
 Corner is located on top of spur ridge which slopes eastward, at a
 point due east & 349 ft. horz. from a reference tree located 73
 on top of main ridge.

Sec. Cor. to Sections 22 - 23 - 26 - 27. 41
 Found - 1959 Cad. Brass Cap, properly mkd.
 Orig. 63", now 64" Fir, N. 55° E. 58.7 ft., shows good scar.
 Alive, do not open.
 8", now 11" D. Fir (not W. Fir) N. 32° E. 12.5 ft. Alive with
 healed blaze, do not open.
 7", now 13" D. Fir, (not W. Fir), S. $62\frac{1}{2}^{\circ}$ E. 13.9 ft. Alive
 with healed blaze. Do not open.
 8", now 9" D. Fir (not W. Fir) S. 32° W. 17.2 ft. Alive, scribe
 marks visible on nearly healed blaze.
 All other BT's. destroyed by very recent logging.
 New BT: 9" D. Fir N. 1° W. 18.9 ft. mkd. T24S R8W S22 CS BT.
 Note - This corner lies approx. 100 ft. W. of road juncton, Roads E-N & S.
 3-8-71 - F.D. OK. C.S. 54/65

$\frac{1}{4}$ Corner to Sections 27 and 26. 42
 Found - Orig. 70", now 72" Fir, S. 57° W. 34.3 ft. Open & find @BT"
 scribe & reverse. Alive & shows faint upper scar.
 Orig. N.E. BT. turned out & slid downhill approx. 60 ft. &
 partially buried.
 Set - Brass Cap at Cor. Mkd: County Surveyors T 24 S R 8 W
 Office, 1966 $\frac{1}{4}$ S 27/S 26
 New BT's: 11" D. Fir N. 50° W. 12.7 ft. mkd. $\frac{1}{4}$ S27 CS BT.
 6" W. Fir S. 10° W. 14.8 ft. mkd. $\frac{1}{4}$ S27 CS BT.
 7" D. Fir N. 1° E. 9.4 ft. mkd. $\frac{1}{4}$ S26 CS BT.
 Note - This corner lies on very steep, N.E. slope.

$\frac{1}{4}$ Corner to Sections 13 and 24. 43
 Found - Orig. 48", now 52" Fir, S. 16° W. 13.2 ft. (Recorded S. 11° W)
 Alive, shows good scar. We do not open.
 Orig. 36", now 36" Fir Snag, N. 75° W. 24.4 ft., prev. opened,
 & shows " $\frac{1}{4}$ S" scribe.
 Set - Brass Cap at intersection of Dist. & Bear. of N.W. BT.
 County Surveyors T 24 S S 13 R8W
 Office, 1966 $\frac{1}{4}$ S 24 (Set in mound of Stone)
 New BT's: 15" Hemlock N. $64\frac{1}{2}^{\circ}$ W. 39.3 ft. mkd. $\frac{1}{4}$ S13 CS BT.
 11" D. Fir S. 44° E. 51.6 ft. mkd. $\frac{1}{4}$ S24 CS BT.
 Note - This corner lies at the foot of steep slope, changing to
 bench land to N.W.

Meyerhauser Co.
 Louis Prahar
 August, 1966
 C. S. File No. 55/11

Vernone "Ray" Tracy
 Jack Heritage & E. West & ELM Crew
 October 19, 1966
 C. S. File No. 49/34