

Douglas County Surveyor's Record of
Government Corners Renewed

T. 24 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97181

44

V. "Ray"
Tracy &
Crew.
10/19/66
C. S. File
No. 49/84

$\frac{1}{4}$ Corner to Sections 10 and 11.
Found - 9" W. Fir N. 47° E. 30.2 ft. mkd. $\frac{1}{4}$ " S11 CS BT. (
18" D. Fir N. 49° W. 26.3 ft. mkd. $\frac{1}{4}$ " S10 CS BT. (See Ren. #38.
8" W. Fir N. 11° W. 61.7 ft. mkd. $\frac{1}{4}$ " S10 CS BT. (
Reset Brass Cap removed for road construction from BT's. above.
Note - Corner lies approx. 40 ft. West of approx. center line
of new access road & 20 ft. W. of top of cut bank. Road course NE.
- May 69 FOUND O.K. V.R.T. 0254/55 - - - - -

45

Vernon "Ray" Tracy
Jack Heritage & E. West
January, 1967
C.S. File No. 54/12

Sec. Corner to Sections 33 and 34, T23-8W.
(North Bdy. of T24-8W)
Found - Orig. 60", now 62" Fir, N. 83° E. 19.1 ft. ~~Alive~~ #102 shows "T W"
and fragmentary bark scribe.
Orig. 40", now 43" Fir, S. 67° W. 40.9 ft. Alive, shows good scar.
Do not open.
Orig. 12", now decayed remains of 16" Fir Stump, N. 79° W. 41.6 ft.,
find "BT" scribe.
Set - Brass Cap at Cor. mkd: County Surveyor's T23S R 8W
Office S 33 | S 34
1967 T24S
New BT's: 16" D. Fir N. 34 $\frac{1}{2}$ ° E. 22.7 ft. mkd. T23S R8W S34 CSBT.
12" D. Fir N. 37 $\frac{1}{4}$ ° W. 25.2 ft. mkd. T23S R8W S33 CS BT.
Note - This corner lies on steep, south slope, approx. 40 ft. west
of shallow draw, course S.W.
- - - - - 1/6/67

RE-RENEWED, SEE CORNER NO. #102

46

Sec. Corner to Sections 31 & 32, T23-8W.
Found - 1963 Cadastral Brass Cap, properly marked.
Orig. 30" Hemlock, now burned stump, S. 16 $\frac{1}{2}$ ° E., 36.8 ft.
1963 5" Hemlock, dead & burned, N. 37° E. 66.7 ft., scribe visible.
1963 9" Hemlock N. 34 $\frac{1}{2}$ ° W. 37.0 ft., now burned stump, scribe visible.
New BT's: 6" Hemlock N. 27° E. 67.8 ft. mkd. T23S R8W S32 CS BT.
9" Hemlock N. 34 $\frac{1}{2}$ ° W. 90.4 ft. mkd. T23S R8W S31 CS BT.
Note - This corner lies on small bench on westerly slope of small,
course S.E. in large logged-off unit.

47

$\frac{1}{4}$ Corner to Section 32 only, T23-8W.
Found - 1963 Cadastral Brass Cap, properly mkd. & $\frac{1}{2}$ " I.P. alongside.
Orig. 60" Hemlock, now turned out stump nearly face down. N. 29° W.
11.2 ft.
1963 40" Hemlock, alive, face burned, N. 36° W. 51.5 ft.
(Rescribe " $\frac{1}{4}$ " S32 CS BT".)
1963 6" Hemlock, down & dead, face burned, N. 53 $\frac{1}{2}$ ° W. 81.2 ft.
New BT: 5" Hemlock N. 36° W. 41.5 ft. mkd. $\frac{1}{4}$ " S32 CS BT.
Note - This corner lies approx. 150 ft. west of small creek, course N.

48

$\frac{1}{4}$ Corner to Section 6 only, T24-8W.
Found - Orig. 24", now 34" Fir Snag, N. 26° E. 35.0 ft., open & find "S"
scribe very lightly cut into face.
Orig. 12", now 26" Hemlock, turned out & lying face down,
S. 26° E. 21.8 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ " T 23 S R8W
Office, 1967 S 6 T 24 S
New BT's: 13" Hemlock S. 8° E. 26.5 ft. mkd. $\frac{1}{4}$ " S 6 CS BT.
8" Hemlock S. 45 $\frac{1}{2}$ ° W. 29.7 ft. mkd. $\frac{1}{4}$ " S 6 CS BT.
Note - This corner lies nearly on top of ridge, course E.-W.

49

$\frac{1}{4}$ Corner to Sec. 31 only, T23-8W.
Found - Orig. 28", now 32" Fir, shattered snag, N. 23° W., 4.0 ft.,
shows " $\frac{1}{4}$ " S" bark scribe on upper blaze in fair condition,
& fragmentary bark scribe on lower blaze.
S.W. Orig. BT. could be under a pile of blow down.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ " S 31 T 23 S R 8 W
Office, 1967 T 24 S
New BT's: 10" Hemlock N. 65° W. 6.8 ft. mkd. $\frac{1}{4}$ " S 31 CS BT.
6" Hemlock N. 37° E. 15.0 ft. mkd. $\frac{1}{4}$ " S31 CS BT.
Note - This corner lies 33.0' E. of $\frac{1}{4}$ Cor. Sec. 6, See above.