

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 24 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

56

$\frac{1}{4}$  Corner to Section 34 only, T23-8W.  
Found - Orig. 30", now 40" Fir, S.17° E. 31.0 ft. Alive, shows good bark scribe " $\frac{1}{4}$ " S" & fragmentary "BT".  
Orig. 12", now 15" Laurel, N. 40° E. 7.9 ft. Open & find. fragmentary reverse scribe. Alive.  
In excavating to set new monument, we find sharpened end of very old cedar post.  
Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$  S 34 T23S<sup>R8W</sup> T24S  
Office, 1967  
New BT's: 6" D.Fir N. 73° E. 24.3 ft. mkd.  $\frac{1}{4}$  S 34 CS BT.  
24" Laurel W. 37° W. 31.2 ft. mkd.  $\frac{1}{4}$  S34 CS BT.  
Note - This corner lies 10 ft. W. of top of ridge, course SE and 176.6 ft. E. of the  $\frac{1}{4}$  cor. of Sec. 3, T24-8., see below.

57

$\frac{1}{4}$  Corner to Section 3 only, T24-8W.  
Found - Orig. 48", now 56" Fir, S. 59° W. 6.6 ft. Alive, shows good scars. Do not open.  
Orig. 18", now 26" Fir N. 46° W. 25.7 ft. Alive, open & find "4" scribe and reverse.  
Set - Brass Cap at Cor. Mkd: County Surveyor's  $\frac{1}{4}$  S 3 T23S<sup>R8W</sup> T24S  
Office, 1967  
New BT's: 5" D.Fir S. 15 $\frac{1}{2}$ ° W. 38.6 ft. mkd.  $\frac{1}{4}$  S 3 CS BT.  
10" D.Fir S. 20° E. 47.5 ft. mkd.  $\frac{1}{4}$  S 3 CS BT.  
Note - This corner lies on steep, southerly slope & 176.6 ft. west of the  $\frac{1}{4}$  corner of Sec. 34 only, see above.

58

$\frac{1}{4}$  corner common to Sections 17 and 20.  
Found - GLO Survey Record - Post -- Gone.  
60" fir north 29 lks., now 72" fir--cruisers marks.  
30" fir S. 87° W. 61 lks., now 48" fir--face visible, healed over.  
Set - 3/4" x 4' Pipe, 3 $\frac{1}{2}$ ' into ground.  
Mkd.- Original BT's. marked with Weyerhaeuser tags.

59

$\frac{1}{4}$  Corner common to Sections 17 and 18.  
Found - GLO Survey Record - Post -- Gone.  
14" hem West 34 lks., now 24" hem--face visible, scribe part rotted out--cruisers marks.  
6" hem S. 34° E. 19 lks., now 26" white fir(not hem)-- couldn't see any face--base of tree buried by road construction.  
Set - 3/4" x 4' Pipe, 3 $\frac{1}{2}$ ' into ground.  
Original BT's. marked with Weyerhaeuser tags.

60

$\frac{1}{4}$  Corner common to Sections 8 and 17.  
Found - GLO Survey Record - Sand stone -- Gone.  
16" hem S.86°E. 90 lks. -- Gone.  
30" cedar N.80°E. 107 lks., found but had been knocked down during logging.  
Set - 3/4" x 4' Pipe, 3 $\frac{1}{2}$ ' into ground.  
Before logging the corner had been re-referenced by R. Yantis of Weyerhaeuser Co., with a "B" nail and Weyerhaeuser tags.

61

N 1/16 Corner on E. line of Section 17. *FOOK BY SMALLEY JAN, '96 M123-38*  
Set a 4' x 3/4" Pipe and Square Post.  
Referenced by D. L. Peel (Weyerhaeuser Method): 13" fir N. 61° W. 1.9 ft.  
33" fir S. 89° E. 10.1 ft.

62

NE 1/16 Corner for Section 17.  
Set a 4' x 3/4" pipe and square post.  
Referenced by Donald L. Peel (Weyerhaeuser Method): 20" hem N. 64° E. 22.0 ft.  
28" white fir N.61°W. 31.5

Vernon "Ray" Tracy  
Jack Heritage & E. West  
February, 1967  
C. S. File No. 54/12

Weyerhaeuser Co.  
By Donald L. Peel  
March, 1967  
C.S. File No. 55/30