

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 24      T. S.      R 8      R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21991

Howard Johnstone  
For: Roseburg Lbr.  
Nov. 10, 1983  
M 95 - 41

1/4 Corner for Sections 31 and 32.  
Found - 3/4" I.P. and 18 x 16 x 8 sandstone.  
64" fir, N.57°E., 9.2 ft. No marks  
36" fir, N.20°W., 19.8 ft. Bark scribe - down.  
New BT - 5" fir, N.42°W., 3.3 ft.

**104**

11/10/83

Larry (Ed) Monrean  
PLS #1830  
Deputy, Doug. County  
Surveyors Office  
Randall Smith,  
Stephen Flause  
March 5, 1984  
C.S. 62/16

Closing Corner for Sec. 6, in T.24-7; & Sec. 1, of T.24-8.  
Found - I.P. w/properly marked B.C., protruding 12". Ren.#19.  
I.P. w/properly marked B.C., protruding 8". Ren.#93.  
BTs - 8", now 17" W.Fir w/well healed dbl.blaze bears East, 32.8-ft.  
6", now 11" D.Fir w/well healed single blaze bears S.53°W., 74.2-ft.  
These two BTs are as per Ren.#34. (DCSO AM).  
12" fir w/partially healed dbl.blaze with visible scribing:  
"T24", bears S.62°W., 64.1-ft.  
8" fir w/partially healed dbl.blaze, with visible scribing:  
"BT", bears S.55°E., 11.2-ft.  
These two BTs are as per Ren.#93. (PLS #1039).  
Set - The letters "AM" were added to the DCSO Closing Corner Cap.  
Note - See file for sketches. 3/84

**105**

Howard Johnstone  
L.S. #498  
For: Roseburg Resource  
Co., May 12, 1987  
1 104 - 16

1/4 Corner For Sec. 36. and Sec. 31, T24-7.  
Set - A 5/8" x 48" iron rod and aluminum cap.  
BT's- A 12" fir bears N84°E, 5.6 ft.  
Set - 19" fir bears S84°W, 22.5 ft.

**106**

Douglas County  
Surveyors office  
Randall Smith  
Stephen Flause  
February 8, 1988  
C.S. 62/50

1/4 Corner for Sections 23 and 24  
Found - 1958 County brass cap, properly mkd., on a 1 3/8" O.D. iron pipe  
protruding 8" above ground. Ren. No. 6  
16" now 35" dia. 16 ft. high rotted D. fir snag, orig. illegible  
scribing found in previously opened blaze, rescribe visible on  
an unhealed double blaze "1/4 S24 CS BT" bears N.75½°E.,  
66.7 ft. Agrees with record. (orig. BT)  
36" now 42" Dia. 5 ft. high D. fir stump tipped out of ground to  
northeast with possible evidence of face, bears S.78½°W.,  
13.9 ft. to root hole agrees with record. (orig. BT)  
12" now 12" dia. D. fir out of ground down and rotted, scribing  
visible on a partially healed double blaze "1/4 S23 CS BT"  
record position falls on logging skid road, BT was pushed out  
of position and now bears N.56°W., 32.3 ft. root wad. Ren.#6  
New BTs - 9" D. fir double blazed and SCRIBED "1/4 S24 CS BT" bears  
S.31°E., 7.0 ft.  
11" W. fir double blazed and scribed "1/4 S23 CS BT" bears  
N.66°W., 32.2 ft.  
7" D. fir double blazed and scribed "1/4 S23 CS BT" bears  
S.56½°W., 18.5 ft.

**107**

Corner lies approx. 700 ft. west of a dirt road on top of an east-west ridge.

2/8/88

**108**

Douglas County  
Surveyors Office  
Randall Smith, Deputy  
Stephen Flause  
August 3, 1992  
C.S. file 64/31

1/4 Corner for Secs. 4 and 9  
Found - 1½" Iron pipe with a 1 3/4" screw on pipe plug brass cap,  
protrudes 7" above ground. Ren. #73 Edge of stone visible  
along west edge of I.P., most of stone under a log. We did not  
disturb. (Original Stone)  
20" now 22" dia. 10 ft. high rotted Fir snag with a previously  
opened blaze, no scribing visible bears N.62°E., 22.0 ft.  
(Rec. N.62°E., 21.1 ft. (Orig. BT)  
16" now 14" dia. 9 ft. high rotted Fir snag with a previously  
opened blaze, no scribing visible bears N.81°E., 18.5 ft.  
(Rec. N.86°E., 18.5 ft.) (Orig. BT)  
16" now 18" dia. 6 ft. high D.Fir stump with a healed notch near  
bottom of trunk, bears S.78°W., 17.0 ft. to center stump.  
(Rec. S.78°W., 16.1 ft. to nail) Ren. No. 73  
NE BT from Ren. No. 73 is gone.  
New BTs - 11" D.Fir double blazed and scribed "¼ S4 CS BT" bears  
N.78½°E., 36.9 ft.  
4" D.Fir double blazed and scribed "X BT", tree is a pistol butt  
bears N.49°E., 15.1 ft. to center of trunk.  
7" pistol butt D.Fir double blazed and scribed "¼ S9 CS BT" bears  
S.40°W., 28.0 ft. to center of root crown.

8/3/92