

Douglas County Surveyor's Record of  
Government Corners Renewed

25 S T. S. R 1 W R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97195

West  $\frac{1}{4}$  Corner Sec. 6, T 25 S, R 1 W. At this point I set a 1" I.P. with steel cap from which:

A Pine 32" in dia. bears N 81° E 27.9 ft. marked T 25 S, R 1 W,  $\frac{1}{4}$  S 6 P.S. 253 BT

A Hemlock 24" in dia. bears S 15° E 49.2 ft. marked T 25 S, R 1 W,  $\frac{1}{4}$  S 6 P.S. 253 B.T.

MAY 1967 SEARCHED FOR, NOT FOUND. V.R.T.

See Drawer 40, File 279 for Dependent Resurvey Range Line between T 25 S, R 1 W, W.M. and T 25 S, R 2 W, W.M.

V.W. Hosford, Surv.  
April 1949 to  
October, 1950

Corner - Secs. 19, 20, 29 and 30

Found original stone corner marked with 5 notches on East and 2 notches on South edges. All original BTs burned and dead. Sec. 30 BT fallen but scribe marks legible. Marked new BTs as follows:

A Fir 16" in diam. bears N 68 $\frac{1}{2}$ ° E 12.2 ft. marked T 25 S, S 20 P.S. 253 B.T.

A Fir 18" in diam. bears S 68 $\frac{1}{2}$ ° E 8.1 ft. marked T 1 W, S 29, P.S. 253 B.T.

A Fir 28" in diam. bears S 48° W 32.5 ft. marked S 30 P.S. 253 BT

A Fir 22" in diam. bears N 44 $\frac{1}{2}$ ° W 54.0 ft. marked S 19 P.S. 253 BT

Closing Corner T 25 S, R's 1 and 2 W

Set a 2" I.P. with steel cap for the closing corner from which

A Fir 22" in dia. bears S 30° E 20.2 ft. marked T 25 S, R 1 W, S 6 C.C. P.S. 253 BT

A Fir 24" in dia. bears S 35° W 8.7 ft. marked T 25 S, R 2 W, S 1 C.C. P.S. 253 BT

Section Corner  $\frac{13}{24}$  T. 25S., R. 1W., & R.2W.

At this corner I found the iron pipe with steel cap set in my survey of 1950. The bearing tree for Section 13 has been cut. The stump still shows the old faces, but all scribing has burned away. The B.T. for Section 24 is up-rooted and badly burned. This area has burned extensively and no green trees remain within a reasonable distance.

From my original I. P. corner:

A Fir stump 30" in diam. bears N. 36°W. 21.2 ft. marked T. 25 S., (My original B.T. re-marked) R. 2W. S13 253 B.T.

A dead Fir 40" in diam. bears S. 9 $\frac{1}{2}$ °W. 64.8 ft. marked T.25S., R. 2W. S 24 253 B.T.

Sept. 20, 1957

V.W. Hosford  
Sept. 20, 1957  
C. S. File No. 42/308

$\frac{1}{4}$  Section Corner to Sections 13 & 24.

Found - 50" Fir at Corner

18" Fir S. 50°W. 44.2 ft.

Set: 48" Fir S. 38 $\frac{1}{2}$ °W. 18.8 ft.

50" Fir N. 38 $\frac{1}{2}$ °E. 35.3 ft.

Section Corner to Sections 13, 14, 23, & 24.

Found - Corner Stone

12" Madrone S 5°W. 7.9 ft.

Set: 26" Fir N. 77°E. 27.0 ft.

36" Fir N. 18° W. 15.7 ft.

26" Fir S. 66°E. 30.0 ft.

$\frac{1}{4}$  Section Corner to Sections 22 and 27.

Found - Stone with "X" on East Face, 10" Cedar N. 31°W. - 16 lks.

11" Fir S. 60°W. - 28 lks.

Note - I chopped open the above trees and found scribed & in good condition.

I scribe two New BT's: 6" Hemlock S. 12°E. 19.4 ft.

10" Fir N. 32°W. 24.0 ft.

Note - (1) Approximately 30' East of this corner is the bottom of a small but sharp draw bearing S. 30°E.

(2) The Section Corner 22, 23, 26, 27, bears S. 89°51'E. 2636.3 ft.

The Section Corner 21, 22, 27, 28, bears N. 86°57'W. 2563.4 ft.

G. Robert Lecklider  
For U. S. Plywood  
Witness: Tom Cody, Jr.  
Oct. 16, 1959  
C. S. File No. 51/53

28. File No. 40/279  
M12-61

RE-RENEWED, SEE CORNER NO. 116

RE-RENEWED, SEE CORNER NO. 116

RE-RENEWED, SEE CORNER NO. 87

RE-RENEWED, SEE CORNER NO. 86

RE-RENEWED, SEE CORNER NO. 56