

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 S. T.S. R 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy County Surveyor
Verdon Tracy and Clete Putnam
June 6, 1962
C. S. File No. 52/30 and C. S. File No. 52/42

Section Corner to Sections 10 - 11 - 14 - 15. 42
Found - $\frac{3}{4}$ " Iron reinforcing Rod at Corner.
26" D.Fir N.65°W. 7.3 ft., shows 2 very plain axe scars.
Did not open.
32" D.Fir N.79°E. 8.6 ft., shows 2 very plain axe scars. Didn't open.
Stump & Sprouts of Dogwood S.70°E. 5.9 ft.
No trace of Chinquapin to S. W. 90
New BT's: 16" R.Cedar S.1°W. 22.8 ft. Mkd: T25S RLW S15 CS BT.
14" R.Cedar S.26°E. 40.2 ft. Mkd: T25S RLW S14 CS BT.

$\frac{1}{4}$ Corner to Sections 10 and 15. 43
Found - Hemlock, now 8", at corner. N. face opened & good
scribing " $\frac{1}{4}$ " S visible on old face.
Hemlock, now 18", S.51°E. 18.5 ft. Has been opened previously
& good scribing " $\frac{1}{4}$ S15" visible on old face.
6" Dogwood N.5°E. 17.2 ft., shows scar.
New BT's: 8" Hemlock N.25°E. 33.2 ft. Mkd: $\frac{1}{4}$ S10 CS BT.
Drive $\frac{3}{4}$ " Iron Rod at Base of Corner Tree. - FOUND O.K. Nov. 1966 - C.S. 52/30
(L. Steel Fence Post Set, See C.S. File No. 55/106)

$\frac{1}{4}$ Corner to Sections 10 and 11. 44
Found - $\frac{3}{4}$ " Reinforcing Rod in Mound of Rock at Corner.
Cedar N.72°W. 18.5 ft., down & badly rotted, faint portions
of scribe marks barely visible on badly rotted faces (2 faces)
Rotted Remnants of Hemlock Stump S.70°E. 16.5 ft., too far gone
to find any marks.
New BT's: 14" Hemlock S.64°W. 20.1 ft. Mkd: $\frac{1}{4}$ S10 CS BT.
11" D.Fir N.23°E. 31.0 ft. Mkd: $\frac{1}{4}$ S11 CS BT.
Corner lies approx. 200 ft. West of Canton Creek.

Sec. Cor. to Secs. 4 & 5, T25-1W. & Secs. 32 & 33, T24-1W. 45
Found - New 4" x 4" Cedar Stake at Corner.
Fir Tree, now 34", S.10°E. 33.7 ft., shows 2 good axe scars.
Fir Tree, uprooted & down, S.51 $\frac{1}{2}$ °W. 4.0 ft., opened scar, good scribng.
Fir Tree, uprooted & down, N.60°E. 5.3 ft., shows good scar.
Fir Tree, uprooted & down, N.44°W. 18.5 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S

S32	S33
S 5	S 4

 T25S RLW
Office, 1962
New BT's: 16" D.Fir S.24°W. 22.9 ft. Mkd: T25S RLW S5 CS BT.
11" D.Fir N.20°W. 14.7 ft. Mkd: T24SRLW S32 CS BT.
8" D.Fir N.45°E. 23.2 ft. Mkd: T24S RLW S33 CS BT. FOUND O.K. Nov. '66
Aug. 21, 1962 - C.S. 52/42

Sec. Cor. to Secs. 3 & 2, T25-1W. & Secs. 34 & 35, T24-1W. 46
Found - Fir Snag, now 28", N.71°E. 17.8 ft, Cut open & fd. good scribing.
Fir Tree, now 45", S.5°W. 20.5 ft., shows very plain axe scar.
Did Not Open.
Fir Tree, now 26", S.64°E., instead of S.69°E. 29.0 ft.,
shows very plain axe scar.
20" Cedar, not Fir, N.4°W. 27.1 ft., shows faint axe scars.
(All Distances mentioned above are slope distances.)
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S

S34	S35
S 3	S 2

 T25S RLW
Office, 1962
Blaze & Rescribe: 20" R.Cedar N.4°W. 26.3 ft. Mkd: T24SRLW S34 CS BT.
New BT's: 16" Hemlock N.21°E. 34.0 ft. Mkd: T24S RLW S35 CS BT.
8" Hemlock S.40°W. 25.1 ft. Mkd: T25SRLW S3 CS BT.
Aug. 23, 1962

$\frac{1}{4}$ Corner to Sec. 4, T25-1W. & Sec. 33, T24-1W. 47
Found - 14" Yew S.82°E. 17.8 ft. (slope dist) Both scars previously opened.
36" W.Fir N.55°W. 11.2 ft. Broken off about 25' above ground.
Both scars prev. opened & good scribing visible on old faces.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S RLW

$\frac{1}{4}$ S33
S. 4

 T25S
Office, 1962
New BT: 8" Hemlock N.12°W. 38.5 ft. Mkd: $\frac{1}{4}$ S33 CS BT. 95
Setp. 17, 1962