

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 W. R. W. W. M.

61

$\frac{1}{4}$ Corner to Sections 13 and 14.
 Found - 6"x8"x14" Basalt Stone, firmly set & mkd. " $\frac{1}{4}$ " on W. face.
 Orig. 14", now 16" Fir S. 62° W. 8.8 ft. (recorded N.33°W.)18.5'
 Prev. opened & shows " $\frac{1}{4}$ " scribe.
 $\frac{1}{2}$ " Steel Pipe set alongside Rock & BT. recorded in Ren. #29.
 32" Fir N. 45° E. 22.0 ft. shows " $\frac{1}{4}$ S13 RE4079 BT", bark scribe.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
 T25S $\frac{1}{4}$ S 14/S 13 RLW.
 New BT's: 6" Yew N. 80° W. 36.5 ft. mkd. $\frac{1}{4}$ S14 CS BT.
 12" D. Fir N. 5° E. 24.1 ft. mkd. $\frac{1}{4}$ S13 CS BT & cruiser's mk. "I"

62

Section Corner to Secs. 11 - 12 - 13 - 14.
 Found - No trace of Basalt Stone called for in Orig. notes.
 BT's. all destroyed except one, as follows: Ren. #28
 30", now 31" D. Fir N. 10° W. 42.0 ft., Alive, shows S11 RE4079 BT".
 Set - Brass Cap mkd. County Surveyor's Office, 1966

T25S	S 11	S 12	RLW
	S 14	S 13	

 New BT's: 20" I. Cedar N. 40° W. 50.3 ft. mkd. T25S RLW S11 CS BT.
 9" I. Cedar S. 20° W. 39.7 ft. mkd. T25S RLW S14 CS BT.
 (4 ft. off ground)
 No trees available to East due to logging.
 Corner lies on N-S cutting line, cut off to East.

63

$\frac{1}{4}$ Corner to Sections 14 and 23.
 Found - Mound of Stone, not called for in Orig. notes.
 17", now 19" Alder N. 72° W. 5.3 ft. Alive, shows "4S BT"
 bark scribe.
 8", now 11" Hemlock S. 15° W. 5.3 ft., down & badly rotted,
 Open & find "BT" reverse scribe.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966

T25S	$\frac{1}{4}$ S 14	B 1W
	S 23	

 New BT's: 9" Hemlock S. 77° E. 13.9 ft. mkd. $\frac{1}{4}$ S23 CS BT.
 18" W. Fir N. 9° W. 52.6 ft. mkd. $\frac{1}{4}$ S14 CS BT.
 Note - This corner lies on flat, approx. 170 ft. W. of old Canton
 Creek trail.

64

$\frac{1}{4}$ Corner to Sections 15 and 16.
 Found - Basalt Stone at Corner Point 10" x 10" x 12" mkd. "X" on top.
 Orig. 17" Hemlock S. 44 $\frac{1}{2}$ ° E. 2.6 ft., down & burned, shows scar.
 12", now 13" Hemlock, now dead, S. 72 $\frac{1}{2}$ ° W. 35.3 ft., shows
 scribe on unhealed blaze. See Ren. #34.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966
 T25S $\frac{1}{4}$ S 16/S 15 RLW & place stone
 alongside.
 New BT's: 16" Hemlock S. 46° E. 45.1 ft. mkd. $\frac{1}{4}$ S15 CS BT.
 23" D. Fir S. 86 $\frac{1}{2}$ ° E. 24.2 ft. mkd. $\frac{1}{4}$ S15 CS BT.
 Note - Due to logging to W. of corner, there are no trees available.
 Corner lies on N-S cutting line.

65

Closing Corner

T 25 S	R 1 W
S 36	

 T26-RLW S 1/S 31 T25 $\frac{1}{2}$ -RIE
 Found - 2" I.P. & 1928 GLO Brass Cap attached, properly marked. #153
 18", now 26" Fir S. 38° E. 71.9 ft., shows very good scar,
 Alive, we do not open.
 Orig. 36", now 48" Fir, now badly rotted stump, S. 31° W. 48.2 ft.,
 shows frag. scribe marks "T2" on shattered blaze.
 New BT: 19" Pine S. 64° W. 23.6 ft. mkd. T26S RLW S 1 CC CS BT.
 Note - Corner lies on steep south slope, approx. 140 ft. E. of
 shallow ravine, course S.E.

10/17/66

Vernon "Ray" Tracy
 Jack Heritage
 August, 1966
 C. S. File No. 52/30

RENEWED CORNER NO. #153