

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

66

Closing Corner to Sections 19 & 30 only, T25-RIE.
Found - 1927 GLO Brass Cap, properly mkd., slightly bent over.
16", now 24" Fir, N. 64° E. 84.5 ft., now 5 ft. high stump,
shows good scar. Do not open.
10", now 14", Fir, S. 62° E. 7.3 ft. Alive, shows good scar.
New BT: 20" W. Fir N. 45° E. 8.4 ft. mkd. T25S RIE S19 CC CS BT.
Note - This corner lies approx. 164 ft. south of the sec. cor. of
Secs. 24 and 25 of T25S R1W. on moderate S. slope.

67

$\frac{1}{4}$ Corner to Section 25 only, T25-1W.
Found - 1927 GLO Brass Cap, properly mkd., badly bent and nearly out
of ground. We straighten and Reset.
Orig. 36", now 40" Fir Snag, S. 60° W. 20.5 ft., very good scar.
We do not open.
6", now 10" Fir N. 65° W. 34.3 ft., Alive, shows good scar. Do not open.
Orig. Basalt Stone, showing $\frac{1}{4}$ " chisel marks.
New BT: 9" D. Fir S. 10 $\frac{1}{2}$ ° W. 23.7 ft. mkd. $\frac{1}{4}$ S25 CS BT.
Note - This corner lies on moderate, changing to steep W. slope and
approx. 125 ft. N. of the $\frac{1}{4}$ Corner of Sec. 30, T25-1E.

68

Sec. Corner to Sections 24 and 25 only, T25-1W.
Found - 1927 GLO Brass Cap, properly mkd.
Orig. 28", now 36" W. Fir, S. 14° W. 71.9 ft. (not S. 18° W.) shows scribe
marks on unhealed blaze. Alive.
Orig. 48, now 53" Fir N 18° W. 23.8 ft, dead & shattered, scribe marks
visible on face & reverse on overgrowth.
New BT's: 8" W. Fir S. 56° W. 11.2 ft. mkd. T25S R1W S25 CS BT.
8" D. Fir N. 12° W. 46.4 ft. mkd. T25S R1W S24 CS BT.
Note - This corner lies on southerly slope, approx. 360 ft. S. of top
of spur & approx. 164 ft. N. of cl. corner of Secs. 19 & 30, T25-1E.

69

$\frac{1}{4}$ Corner to Sec. 36 only, T25-1W.
Found - Orig. 50", now stump, (Fir) N. 80 $\frac{1}{2}$ ° W. 28.4 ft., shows "T" scribe.
8" Fir, now down, S. 37° W. 30.4 ft. shows $\frac{1}{4}$ " S36BT" on unhealed blz.
No trace of Rock called for.
Set - Brass Cap at Cor. Mkd. County Surveyors T 25 S
(14" in green & Office, 1966 R1W $\frac{1}{4}$ S 36 | RIE
build mound of stone 18" high)
New BT's: 8" W. Fir, S. 89° W. 12.9 ft. mkd. $\frac{1}{4}$ S36 CS BT.
24" Hemlock S. 16° W. 18.6 ft. mkd. $\frac{1}{4}$ S36 CS BT.
Note - This corner lies on right bank of Canton Creek

70

$\frac{1}{4}$ Corner to Section 31 only, T25-1E.
Found - 1927 GLO Brass Cap mkd. $\frac{1}{4}$ /S31", nearly out of Rock Mound.
We reset in new Mound of Stone 2 ft. high.
Both 1927 BT's. alive & show scar, we reset.
14", now 18" D. Fir S. 28° E. 24.0 ft. rescribed $\frac{1}{4}$ S31 CS BT".
8", now 13" D. Fir N. 41° E. 4.0 ft. rescribed $\frac{1}{4}$ S31 CS BT".
Note - Corner lies 50 ft. west of Canton Creek, course S. on right high
bank & approx. 40 ft. S. of the $\frac{1}{4}$ Cor. of Sec. 36 only, T25-1W.

71

Closing Corner to Sections 30 and 31, T25-1E.
Found - 1927 GLO Brass Cap appropriately mkd.
10", now 14" Fir, S. 64° E. 41.6 ft. (face) prev. opened, scribe
marks visible. Alive.
N. E. BT. lying face down.
New BT's: 8" D. Fir S. 37° E. 14.6 ft. mkd. CC S31 CS BT.
8" Pine N. 44° E. 11.7 ft. mkd. CC S30 CS BT.
Note - This corner lies in logged off unit approx. 150 ft. North of
small ravine, course SW.

Vernon "Ray" Tracy
Jack Heritage and E. West.
October, 1966
C. S. File No. 52/30

RE-RENEWED, SEE CORNER NO. #151