

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$ Corner to Sections 13 and 24.

Found - Orig. Corner Tree, now 50" Fir Stump, shows scar.
48" Fir, now stump; S. $38\frac{1}{2}^\circ$ W. 18.8 ft., shows scribe on
unhealed blaze.)) Ren. #13
50" Fir, now stump, N. $38\frac{1}{2}^\circ$ E. 35.3 ft., shows scribe on
unhealed blaze.

Orig. BT's. gone completely.

We drive $\frac{1}{2}$ x30" I.R. incanter of stump & set Brass Cap at base on West Side
of Corner Stump mkd. County Surveyors $\frac{1}{4}$ S $\frac{13}{24}$ T25S RLW
Office, 1966

New BT's: 10" W. Fir N. 13° E. 71.6 ft. mkd. $\frac{1}{4}$ S13 CS BT.

6" I. Cedar N. 58° E. 84.9 ft. mkd. $\frac{1}{4}$ S13 CS BT.

No trees available in Section 24. - Bear. & distances to I. Rod.

$\frac{1}{4}$ Corner to Sections 23 and 24.

Found - Orig. Basalt Stone 17 x 5 x 9" mkd. " $\frac{1}{4}$ " on W. face, firmly set.
Orig. 20", now 30" Fir, N. 53° E. 32.3 ft. Alive, shows very
good scar. Do not open, but rescribe above old blaze:
" $\frac{1}{4}$ S23 CS BT".

Set - Brass Cap at Cor. Mkd: County Surveyors T25S $\frac{1}{4}$ S 23/S24 RLW
Office, 1966 Reset Rock alongside.

New BT; 7" D. Fir S. 27° E. 12.0 ft. mkd. $\frac{1}{4}$ S24 CS BT.

Note - This corner lies on steep south slope changing to S.W. slope
approx. 500 ft. north of Canton Creek Road.

$\frac{1}{4}$ Corner to Sections 25 and 26.

Found - Orig. 12", now 13" Corner Tree Alive. Chopped open & shows " $\frac{1}{4}$ " S
scribe on W. face.

Orig. 10", now 9" Fir, N. 78° E. 14.1 ft. (not 21.1 ft. prob. 10 lk.
error in orig. meas.) chopped open & shows " $\frac{1}{4}$ S BT" scribe, now Snag.

Vine Maple Sprouts N. 66° W. 5.3 ft., locus of N.W. Orig. BT.

Set - Brass Cap at Cor. Mkd: County Surveyors T25S $\frac{1}{4}$ S 26/S 25 RLW
at base of Corner Tree Office, 1966
on North Side

New BT's: 26" D. Fir S. 71° W. 20.8 ft. mkd. $\frac{1}{4}$ S 26 CS BT.

7" Hemlock S. 36° E. 5.6 ft. mkd. $\frac{1}{4}$ S 25 CS BT.

Note - This corner lies on steep East slope.

Section Corner to Sections 10 - 11 - 14 - 15.

Found - $\frac{3}{4}$ " I. Rod buried approx. 14" below surface of ground. See Ren. #42.

32" D. Fir N. 79° E. 8.6 ft., shows good scars, Alive. Do not open.

16" R. Cedar S. 1° W. 22.8 ft., shows scribe. Alive.

14" R. Cedar S. 26° E. 40.2 ft., shows good scribe.

Orig. N.W. BT., lying face down.

Set - Brass Cap at Cor. Mkd. County Surveyors T25S $\frac{S}{S} \frac{10}{14} | \frac{S}{S} \frac{11}{15}$ RLW
over I. Rod. Office, 1966

New BT: 10" R. Cedar N. 10° W. 60.7 ft. mkd. T25S RLW S10 CS BT.

Note - This corner lies approx. 100 ft. E. of logging access road at
a S.W. corner of timber.

Section Corner to Sections 9 - 10 - 15 - 16.

Found - $1\frac{1}{2}$ " I. Pipe as recorded in Ren. #33.

8", now " Hemlock N. $58\frac{1}{2}^\circ$ E. 28.3 ft., (not 27.3 ft.) Alive.

Orig. 12", now 16" Fir, N. 50° E. 17.8 ft., now decayed stump,
find axe marks only.

Orig. 14", now 16" Fir decayed Stump, S. 61° E. 29.0 ft., find "BT" scribe
All other BT's. down or gone.

Do not set Brass Cap.

New BT's: 11" R. Cedar S. 74° E. 49.5 ft. mkd. T25S RLW S15 CS BT.

6" Hemlock S. 70° W. 7.8 ft. mkd. S16 CS BT.

Note - No trees available to N.W. - This corner lies on N-S cutting line,
cut off to west.

Vernon "Big" Tracy
Jack Heritage & E. West
November, 1966
C. S. File No. 52/30

CAP Mkd
Case ready
Per BLM
10/11/78
12/17/78

579w
Per Research

87

88

89

90

91