

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 1 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

92

$\frac{1}{4}$ Corner to Sections 15 and 22.
Found - Alum. Cap on Steel Pipe mkd. "US P.C. Prop. Cor. RE4287,
T25SRLW $\frac{1}{4}$ S15 & 22". See Ren. #50.
16" Hemlock N. $73\frac{1}{2}^\circ$ E. 36.0 ft., scribe visible on unhealed blaze,
alive and in good condition.
12", now 9" Cedar, S. 34° W. 7.2 ft. Alive, top broken off
& severe injury to E. $\frac{1}{2}$ of tree, scribe visible.
Orig. N. E. BT., now turned out.
New BT: 22" Cedar S. 24° E. 33.4 ft. mkd. $\frac{1}{4}$ S22 CS BT.
Note - This corner lies approx. 60 ft. W. of small creek, course N.E.,
not S.E. as called for in orig. field notes.

93

$\frac{1}{4}$ Corner to Sections 22 and 23.
Found - 1962 CS Brass cap, properly mkd., See Ren. #39.
Orig. N.E. BT. still remains & broken off.
9" Hemlock, severely injured & nearly turned out, S. 33° W. 11.3 ft.,
shows scribe on unhealed blaze.
18" W. Fir, alive & good cond., N. 35° E. 37.3 ft. scribe visible
on unhealed blaze.
New BT: 50" D. Fir Stump, N. 44° W. 21.3 ft. mkd. $\frac{1}{4}$ S22 CS BT.
Note - This corner lies on E. edge clear cut unit approx. 50 ft.
N.E. of road junction.

94

Sec. Cor. to Sections 14 - 15 - 22 - 23.
Found - 1962 C.S. Brass Cap, properly mkd., See Ren. #41.
15" R. Cedar N. 62° W. 29.0 ft. Alive, scribe visible
on unhealed blaze.
38" R. Cedar S. $79\frac{1}{2}^\circ$ E. 9.9 ft. Alive, scribe visible on
upper blaze. lower blaze burned. Rescribe "BT". This
tree also Orig. BT. S.W. Renewal BT, down & out of place. Orig. BT's. destroyed.
New BT's: 5" Hemlock N. 60° E. 85.9 ft. mkd. "S14 CS BT".
24" D. Fir Stump S. 40° W. 63.4 ft. mkd. "T25S RLW S22 CS BT"
Note - This corner lies approx. 200 ft. W. of road at cutting corner,
timber in Section 15 only.

95

$\frac{1}{4}$ Corner to Sec. 4, T25-1W. & Sec. 33, T24-1W.
Found - No trace of Brass Cap, recorded in Ren. #47.
Due to logging, new BT in renewal, knocked over.
14" Yew S. 82° E. 17.8 ft., scribe visible on unhealed blaze.
36" W. Fir, now 25' high Snag, N. 55° W. 11.2 ft., scribe
visible on unhealed blaze.
Set - Brass Cap at Cor. Mkd: County Surveyors $\frac{1}{4}$

S	33	T25S
S	4	RLW

Office, 1966
New BT's: 6" Hemlock S. 29° W. 39.9 ft. mkd. $\frac{1}{4}$ S 4 CS BT.
11" Hemlock N. 83° E. 60.4 ft. mkd. $\frac{1}{4}$ S 33 CS BT.
Note - This corner lies on E - W. cutting line cut off to north
approx. 300 ft. E. of small creek, course S.W.

96

Sec. Cor. to Secs. 3 & 4, T25-1W. & Sec. 33 & 34, T24-1W.
Found - Orig. 48", now 53" Fir, N. 18° E. 44.2 ft. Open & find scribe.
Orig. 6", now 24" Fir, S. 29° E. 29.1 ft. Alive, shows scar.
Orig. 48", now 58" Fir, S. 35° W. 24.4 ft., (not 28.3 ft.)
Alive, shows scar.
Orig. 36", now 54" Fir, N. 24° W. 42.2 ft. Alive, shows
good scar.
Set - Brass Cap mkd. County Surveyors

T24S	S 33	S 34	RLW
T25S	S 4	S 3	

Office, 1966
New BT's: 8" W. Fir N. 40° W. 8.2 ft. mkd. T24S RLW S33 CS BT.
8" W. Fir N. $56\frac{1}{2}^\circ$ E. 13.3 ft. mkd. T24S RLW S34 CS BT.
Note - Corner lies on steep, east slope.

Vernon "Ray" Tracy
 Jack Heritage & F. West
 November, 1966
 C. S. File No. 52/30

RE-RENEWED, SEE CORNER NO. #148

RE-RENEWED, SEE CORNER NO. #159