

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 1 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

106A

Sec. Cor. to Secs. 5 & 6, T25-1W. & Secs. 31 & 32, T24-1W.  
Found - Orig. 12", now 17" Fir Stump, still in place, S.  $87\frac{1}{2}^\circ$  W. 46.2 ft.  
Open & find "S6 RLW" scribe & reverse.  
Bearings & approx. Distances fit holes of other Orig. BT's.,  
down & out of position.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S S 31 | S 32  
Office, 1966 T25S S 6 | S 5 RLW  
New BT's: 6" Hemlock N.  $73^\circ$  W. 52.0 ft. mkd. T24S RLW S 31 CS BT.  
12" Yew S.  $66\frac{1}{2}^\circ$  W. 16.8 ft. mkd. T25S RLW S 6 CS BT.  
11" Yew S.  $25^\circ$  E. 24.4 ft. mkd. T25S RLW S 5 CS BT.  
8" Hemlock N.  $29^\circ$  E. 59.8 ft. mkd. T24S RLW S 32 CS BT.  
Note - This corner lies on N.E. slope in logged unit.

107

$\frac{1}{4}$  Corner to Sections 2 and 11.  
Found - Original Basalt Corner Stone,  $14" \times 10" \times 8"$  mkd. " $\frac{1}{4}$ " on N. Face.  
Orig. 7", now 9" Fir, N.  $15^\circ$  W. 9.9 ft., prev. opened &  
shows "S" pocket knife-type scribe. Open lower & find "BT"  
done in the same manner. Under 66 years growth.  
Orig. S.E. BT., now only rotted remains, possible reverse scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S  $\frac{1}{4}$  S 2 | S 11 RLW  
(Reset Rock alongside) Office, 1966  
New BT's: 8" R. Cedar N.  $39^\circ$  W. 27.7 ft. mkd.  $\frac{1}{4}$  S 2 CS BT.  
8" R. Cedar S.  $48^\circ$  E. 35.2 ft. mkd.  $\frac{1}{4}$  S 11 CS BT.  
Note - This corner lies on nearly flat bench, approx. 200 ft. E. of new  
logging road, course N.-S.  
(4/26/72-Reset Brass Cap & Rock, 3 BT's. O.K. V.R.T.)

108

$\frac{1}{4}$  Corner to Sections 21 and 22.  
Found - Orig. Basalt Corner Stone,  $16" \times 8" \times 6"$  set in mound of Stone and  
marked " $\frac{1}{4}$ ".  
Orig. 12", now 18" Cedar, N.  $22\frac{1}{2}^\circ$  E. 16.5 ft. Alive, top broken off,  
shows good scar. We do not open.  
Orig. 15", now 17" Arbutis (Laurel), Alive, N.  $58^\circ$  W. 34.3 ft.,  
(recorded as 36.6') Open & find frag. reverse scribe., center rotted.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S  $\frac{1}{4}$  S 21 | S 22 RLW  
Office, 1966  
(Set B. Cap in mound of stone & Reset Original Stone)  
New BT's: 8" D. Fir N.  $19^\circ$  W. 29.2 ft. mkd.  $\frac{1}{4}$  S 21 CS BT.  
8" D. Fir S.  $42^\circ$  E. 13.0 ft. mkd.  $\frac{1}{4}$  S 22 CS BT.  
Note - This corner lies on steep East slope on rocky spur.

109

$\frac{1}{4}$  Corner to Sections 4 and 9.  
Found - No trace of Original Corner Tree or BT's.  
Set -  $\frac{1}{4}$  Corner by Single Proportion:  
 $2\frac{1}{2}$ " diam. Aluminum Cap Mkd: U.S. P.C. Prop. Cor. T25S RLW  
R.E. 4287  $\frac{1}{4}$  S 4 | S 9  
New BT's: 36" Red Cedar N.  $31^\circ$  E. 9.4 ft.  
6" Chinkapin S.  $45^\circ$  W. 20.7 ft.  
8" Chinkapin S.  $41^\circ$  E. 13.7 ft.  
Co. Surveyor's BT: 10" Chinquapin S.  $64^\circ$  E. 10.8 ft. mkd.  $\frac{1}{4}$  S 9 CS BT.  
(This BT. mkd. in Dec. 1966, See C.S. File No. 52/30.)  
*SEE ALSO KEN. No. 115*

110

Section Corner to Sections 3 - 4 - 9 - 10.  
Set -  $2\frac{1}{2}$ " diam. Aluminum Cap marked.  
New BT's: 18" Red Cedar S.  $10^\circ$  E. 44.2 ft.  
4" Hemlock N.  $16\frac{1}{2}^\circ$  W., 23.3 ft.  
6" Hemlock S.  $47^\circ$  W. 17.7 ft.  
22" Red Cedar N.  $49^\circ$  E. 23.0 ft.

111

Center  $\frac{1}{4}$  Corner Section 4.  
Set -  $2\frac{1}{2}$ " diam. Aluminum Cap marked.  
15" W. Pine Stump S.  $56\frac{1}{2}^\circ$  E. 18.3 ft.  
13" D. Fir Stump N.  $88^\circ$  W. 15.0 ft.

Vernon "Ray" Tracy  
Jack Heritage & E. West  
December, 1966  
C. S. File No. 52/30

Thomas E. Shrum, Jr.  
For U. S. Plywood Corp.  
November, 1966  
Map File M 32 - 62